

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Paid  
 CLAIM 2529327  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT2LCZB6TB012568  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 048 / 048A  
 ITEM # LCT3411RK  
 DEALER RO # 72763  
 CLAIM START DATE 12/16/2025  
 CLAIM END DATE 12/22/2025

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

Line# 1      **Operation Code**      **Operational Description**  
 30-100-24-00-001046      Cabinet Door - Interior/Cabinetry/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2025-12-16 15:13:30 :: Complaint: Cabinet door has come loose  
 Cause: Fell off in transit Correction: Reinstalled using black screws and touched up scratches in cabinet face  
**Model#**      **Dlr Sub Hrs**      0.40      **Sub Labor Amt** \$76.00  
**Serial#**      **Appr Hrs**      0.40      **Appr Labor Amt** \$76.00

### Notes

NVCB .40 to resecure the door and then to use putty to fill in and cover the scratches. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

### Part

Line# 1      **Item #**      **Description**  
 USERPART      Screws and touch-up for scratches  
**Model #**      **Serial #**      **Part tag**  
     **Sub Qty**      1.00      **Sub Dlr Price**      \$3.80      **Sub Freight**      \$0.00  
     **Appr Qty**      1.00      **Appr Dlr Price**      \$3.80      **Appr Freight**      \$0.00

### Notes

<b>Submitted</b>	Labor Amt	\$76.00		<b>Approved</b>	Labor Amt	\$76.00
	Parts & Freight	\$3.80			Parts & Freight	\$3.80
	Total	\$79.80			Total	\$79.80

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE  
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE  
 All repairs described have been inspected and are satisfactory.