

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$95.00
 Serial# Appr Hrs 0.20 Appr Labor Amt \$38.00

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line#	Item #	Description	Model #	Serial #	Part tag
1	USERPART	Sealant			
	Sub Qty 1.00	Sub Dlr Price \$1.90			Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$1.90			Appr Freight \$0.00

Notes

Labor

Line# 7 Operation Code 30-91-24-11-001301 Operational Description LED Light Strip or Rope Lights - Interior/Living Quarters, Sofa, Chair/Repair/ Electrical

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-23 11:01:51 :: Complaint: Light strip under fireplace is detached Cause: Not properly adhered Correction: Resecure and reseal

Model# Dlr Sub Hrs 0.30 Sub Labor Amt \$57.00
 Serial# Appr Hrs 0.10 Appr Labor Amt \$19.00

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line#	Item #	Description	Model #	Serial #	Part tag
1	USERPART	Sealant			
	Sub Qty 1.00	Sub Dlr Price \$0.95			Sub Freight \$0.00
	Appr Qty 1.00	Appr Dlr Price \$0.95			Appr Freight \$0.00

Notes

Labor

Line# 8 Operation Code 10-9-02-11-000204 Operational Description Sensing Unit - Frame & Chassis/Levelers, Underbelly/Adjust/Electrical

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-23 11:03:08 :: Complaint: Auto level is out of calibration Cause: Needs to be reconfigured Correction: Reconfigure auto level zero point

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$95.00
 Serial# Appr Hrs 0.25 Appr Labor Amt \$47.50

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Labor

Line# 9 Operation Code 30-101-24-00-001076 Operational Description Hinged Passage Door - Interior/Interior Doors/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-23 11:05:29 :: Complaint: Mid bunk room door has rub damage at latching area Cause: Door is rubbing Correction: Sand, stain and resecure frame catch to allow for door clearance

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$95.00
 Serial# Appr Hrs 0.50 Appr Labor Amt \$95.00

Notes

NVCB,R&RI door larch and align,repair door.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1	Item #		Description			
	USERPART		Stain			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$4.75	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$4.75	Appr Freight	\$0.00

Notes

Submitted	Labor Amt	\$570.00	Approved	Labor Amt	\$418.00
	Parts & Freight	\$22.20		Parts & Freight	\$22.20
	Total	\$592.20		Total	\$440.20

DEALER _____ **DATE** _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
All repairs described have been inspected and are satisfactory.