

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2563422
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3CSSB0SG128181
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049B
OWNER INFORMATION		ITEM #	CSF270BHX
BENITO E GONZALES JR		DEALER RO #	72840
16 CRESENCIANO RD		CLAIM START DATE	01/28/2026
Tijeras, NM 87059		CLAIM END DATE	02/10/2026
USA			
Retail Date of Purchase	05/28/2025	WARRANTY EXPIRATION DATE	05/28/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-138-24-00-001520	Black Water Tank (Read Notes!!!) - Plumbing/Drainage System/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-28 08:55:19 :: Complaint: Customer states when raising trailer water runs out from the underbelly Cause: Pressure filled fresh tank. Ran all receptacles and filled holding tanks to test for leaks. Black tank was 3/4 full when unit arrived. Emptied tanks and tested for leaks. Let unit sit pressurized overnight. Correction: No water ever came out of underbelly. Requesting time for troubleshooting. Additional Note : stephanie@dealer-advisors.com, 2026-01-28 08:59:12 :: No pictures, as no problem was diagnosed.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-28 09:00:09 :: Complaint: Customer states hallway motion light at stairs is inop Cause: Oxidized terminal at switch Correction: Removed wiring. Cleaned terminals and reinstalled switch. Tested function, complete.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
	Notes			
	NVCB, Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Labor

Line# 3	Operation Code	Operational Description		
	10-13-02-00-000211	Slide Out Room - Frame & Chassis/Slide Out System/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-28 09:02:10 :: Complaint: Customer states drivers side rear slide is rubbing on the floor and is not flush at exterior, it rubs on fenderskirt. Cause: Found that it was out of adjustment Correction: Performed leveling and stabilizing of coach to ensure accurate adjustments. Raised height of rear floor to max position. tested for clearance.			
	Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$95.00
	Serial#	Appr Hrs	0.50	Appr Labor Amt \$95.00
	Notes			
	NVCB, Per dealers description of this repair. This authorization is pending ALL requirements of			

repair code have been met.TD

Labor

Line# 4

Operation Code	Operational Description
20-69-01-00-000706	Compartment Door - Exterior/Compartment Doors/Replace/No Tread Code
Complaint, Cause, Correction	
Original Note : stephanie@dealer-advisors.com, 2026-01-28 09:03:30 :: Complaint: Docking station door missing one flip door within the door Cause: Missing, unknown Correction: Replace door cover	

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$95.00

Notes
NVCB, Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1

Item #	Description
90M16795A	FLAP COVER FOR HOLES, BLACK, for EXTERIOR SHOWER/DOCKING STATION DOOR (VERMIN DOOR) (MIN QTY 25) FOR 301-010-00012 DOCKING STATION, 201-004-00022 STEMWASHERS FOR INSTALLATION USE 90M35731A, (15F)

Model #	Serial #	Part tag			
Sub Qty	1.00	Sub Dlr Price	\$1.12	Sub Freight	\$16.28
Appr Qty	1.00	Appr Dlr Price	\$1.12	Appr Freight	\$16.28

Notes

Line# 2

Item #	Description
90M35731A	VERM STEMWASHER, for FLAP ATTACHEMENT for EXTERIOR SHOWER/DOCKING STATION DOOR (MIN QTY 50) 104-005-00025 FOR FLAP COVER use 90M16795A, (15F), FOR 301-010-00012 DOCKING STATION

Model #	Serial #	Part tag			
Sub Qty	1.00	Sub Dlr Price	\$0.99	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$0.99	Appr Freight	\$0.00

Notes

Submitted	Labor Amt	\$304.00	Approved	Labor Amt	\$304.00
	Parts & Freight	\$18.39		Parts & Freight	\$18.39
	Total	\$322.39		Total	\$322.39

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.