

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2584547
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVMB2TB941424
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT23BHS
SPENCER PATTON		DEALER RO #	72906
15 EDGE OF WOODS RD		CLAIM START DATE	02/18/2026
Tijeras, NM 87059		CLAIM END DATE	02/19/2026
USA			
Retail Date of Purchase	02/05/2026	WARRANTY EXPIRATION DATE	02/05/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-136-12-00-001500	Fitting - Plumbing/Fresh Water Supply/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-02-18 14:43:22 :: Complaint: Toilet is leaking from behind, possibly at toilet connections. Runs down blue hose and puddles between shower and sink cabinet Cause: Found the water connection for the water line to the toilet was not tight. Correction: Tightened the fitting and tested with 3 gallons of antifreeze.			
Model#		Dlr Sub Hrs	0.57	Sub Labor Amt \$108.30
Serial#		Appr Hrs	0.20	Appr Labor Amt \$38.00
	Notes			
	NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Labor

Line# 2	Operation Code	Operational Description		
	60-141-24-00-001593	Tub Pan - Plumbing/Shower, Tub Surround/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-02-18 14:46:18 :: Complaint: Shower pan needs to be sealed Cause: Missing sealant Correction: Cleaned and used white silicone on the whole edge between the shower floor and wall			
Model#		Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
Serial#		Appr Hrs	0.20	Appr Labor Amt \$38.00
	Notes			
	NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Part

Line# 1	Item #	Description		
	USERPART	Sealant		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$1.90
	Appr Qty	1.00	Appr Dlr Price	\$1.90
			Sub Freight	\$0.00
			Appr Freight	\$0.00
	Notes			

Labor

Line# 3	Operation Code	Operational Description
	30-100-02-00-003062	Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
	Complaint, Cause, Correction	
	Original Note : stephanie@dealer-advisors.com, 2026-02-18 14:49:17 :: Complaint: Customer states cabinet	

below bathroom sink has hinges on both sides and will not close Cause: Unit comes this way from factory to prevent storage under the sink and damage to plumbing. Correction: Screws were put back in the hinges

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
---------	----------	------	----------------	---------

Notes

Labor

Line# 4

Operation Code

20-46-02-00-000721

Operational Description

Window - Exterior/Windows/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-18 14:51:17 :: Complaint: Customer states emergency window at bottom bunk has a gap Cause: Window itself it off center. Found rear of the emergency lower bunk window could see light on the back side. Correction: Removed set screws at the top and center window. Reinstall set screws.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
---------	----------	------	----------------	---------

Notes

Labor

Line# 5

Operation Code

20-66-01-16-000689

Operational Description

Assist Door Handle - Folding - Exterior/Entry Doors/Replace/Structure

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-18 14:53:14 :: Complaint: When entry door handle is closed a screw is sticking out and does not sit flush Cause: Bottom base plate for entry door handle is installed at an angle Correction: Removed screw cover, removed both screws and straighten the base plate. Reinstall screw and tested handle.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
---------	----------	------	----------------	---------

Notes

Labor

Line# 6

Operation Code

40-106-12-00-001320

Operational Description

Exterior Recept - Electrical/12 Volt Exterior/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-18 14:56:57 :: Complaint: Outlet cover on door side needs to be siliconed Cause: Silicone cracked on the top and excessive smear of silicone Correction:Scrape off all the old silicone and used adhesive removed to remove the residue. Resealed the black outlet cover on the black side with black silicone.

Model#	Dlr Sub Hrs	0.35	Sub Labor Amt	\$66.50
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
---------	----------	------	----------------	---------

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1

Item #

USERPART

Description

Silicone

Model #

Serial #

Part tag

Sub Qty 1.00

Sub Dlr Price \$1.90

Sub Freight \$0.00

Appr Qty 1.00

Appr Dlr Price \$1.90

Appr Freight \$0.00

Notes

Labor

Line# 7

Operation Code

10-9-01-00-000177

Operational Description

Bumper End Caps - Frame & Chassis/Levelers, Underbelly/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-18 15:52:29 :: Complaint: Customer states the bumper cap on door side is missing Cause: Cap is missing Correction: Replace cap

Model#	Dlr Sub Hrs	0.05	Sub Labor Amt	\$9.50
Serial#	Appr Hrs	0.05	Appr Labor Amt	\$9.50

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1	Item #	Description			
	USERPART	70406 4" Bumper plug			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$2.29	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.29	Appr Freight \$0.00

Notes**Labor**

Line# 8	Operation Code	Operational Description
	20-43-19-00-004330	Spot Seal Exterior (Dealer) - Exterior/Exterior Miscellaneous/Reseal/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-18 15:54:11 :: Complaint: Customer states silicone needs to be cleaned and reapplied at the rear and front corner moldings on the door side Cause: Silicone is cracked at front and rear passenger side door corners Correction: Scrape and reseal the front corner. Reseal rear corner.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes**Part**

Line# 1	Item #	Description			
	USERPART	Silicone			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$1.90	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$1.90	Appr Freight \$0.00

Notes**Labor**

Line# 9	Operation Code	Operational Description
	20-43-19-00-004330	Spot Seal Exterior (Dealer) - Exterior/Exterior Miscellaneous/Reseal/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-18 15:56:13 :: Complaint: Silicone needs to be cleaned an reapplied at the rear and front corner molding off door side Cause: Silicone is cracked Correction: Scrape and clean the cracked silicone on the front off door side front lower corner and reseal with clear silicone.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1	Item #	Description			
	USERPART	Silicone			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$2.85	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.85	Appr Freight \$0.00

Notes**Labor**

Line# 10

Operation Code
40-106-01-11-001248

Operational Description
12 Volt In-Line Circuit Breaker or Fuse - Electrical/12 Volt Exterior/Replace/
Electrical

Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2026-02-18 15:58:29 :: Complaint: Rear electric jacks will not retract. While customer was here the jacks would not extend when pushing button at the rear of trailer. Cause: No power Correction: Pulled the switch out of the frame and tested power at the switch, no power found. Traced the wires to the fuse block on the frame. Tested power, had 12V coming in power out. Removed fuse block. Replace with new fuse block, tested jack up and down and they now work.

Model#Dlr Sub Hrs0.40Sub Labor Amt \$76.00

Serial#Appr Hrs0.40Appr Labor Amt \$76.00

Notes
NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part
Line# 1

Item #Description

USERPART10138 30 AMP CIR BREAKER

Model #Serial #Part tag

Sub Qty1.00Sub Dlr Price\$4.27Sub Freight\$0.00

Appr Qty1.00Appr Dlr Price\$4.27Appr Freight\$0.00

Notes

Labor
Line# 11

Operation Code
40-106-24-11-001253

Operational Description
Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical

Complaint, Cause, Correction
Original Note : stephanie@dealer-advisors.com, 2026-02-18 16:00:47 :: Complaint: Customer states under slide on off door side electrical wire support is hanging Cause: Electric wiring slide out support Correction: Examined the slide room electric wiring system. It is complete intact and properly secured and holding the wiring as it should be in order for the slide to move in and out without pinching the wires.

Model#Dlr Sub Hrs0.05Sub Labor Amt \$9.50

Serial#Appr Hrs0.05Appr Labor Amt \$9.50

Notes
NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Submitted	Labor Amt	\$497.80	Approved	Labor Amt	\$399.00
	Parts & Freight	\$15.11		Parts & Freight	\$15.11
	Total	\$512.91		Total	\$414.11

DEALERDATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMERDATE

SIGNATURE

All repairs described have been inspected and are satisfactory.