

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Authorized
 CLAIM 2543145
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRPU1XTB035145
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 080 / 080
 ITEM # RPT194-80
 DEALER RO # 72187
 CLAIM START DATE 01/06/2026
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 70-178-01-00-002145 Stove Top Cover - Appliances/Range (Suburban)/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-06 18:02:27 :: Complaint: Stove glass top is broken
 Cause: Glass top is broken, arrived this way. noted on DAF. Correction: Remove and replace glass top
Model# CGH12D2MA1b-bl **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$57.00
Serial# 10002002317062512122 **Appr Hrs** 0.10 **Appr Labor Amt** \$19.00
Notes
 Excessive time requested. Time reduced based on photos, description and flat rate code.
 Authorized broken from the plant/production.

Labor

Line# 2 **Operation Code** **Operational Description**
 30-92-01-00-001154 Sink Cover - Interior/Interior Miscellaneous/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-06 18:06:54 :: Complaint: Sink cover hang handle is bent and missing screw Cause: Arrived this way, noted on DAF Correction: Straightened handle holder and add a new screw
Model# **Dlr Sub Hrs** 0.10 **Sub Labor Amt** \$19.00
Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$19.00
Notes
 Authorized to repalce

Labor

Line# 3 **Operation Code** **Operational Description**
 30-102-15-00-003365 Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-06 18:11:52 :: Complaint: Panel in front of water pump has fallen off Cause: Panel has fallen off due to faulty staples Correction: Resecure and tightened
Model# **Dlr Sub Hrs** 0.10 **Sub Labor Amt** \$19.00
Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$19.00
Notes

Labor

Line# 4 **Operation Code** **Operational Description**
 20-43-24-00-001113 Exterior Sidewall AC Vent - Exterior/Exterior Miscellaneous/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-06 18:13:02 :: Complaint: AC outside cover is making a lot of noise Cause: Outside AC cover is loose Correction: Resecure and tightened

