

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2554162
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3CSSB0SG128181
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049B
OWNER INFORMATION		ITEM #	CSF270BHX
BENITO E GONZALES JR		DEALER RO #	71945
16 CRESENCIANO RD		CLAIM START DATE	01/16/2026
Tijeras, NM 87059		CLAIM END DATE	01/22/2026
USA			
Retail Date of Purchase	05/28/2025	WARRANTY EXPIRATION DATE	05/28/2026

Claim Line Details

Labor

Line# 1	Operation Code 10-3-01-20-000076	Operational Description Tire - Includes Rim, Wheel - Frame & Chassis/Wheels, Tires, Hubcaps/Replace/Wheels		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-16 16:45:36 :: Complaint: Customer states the spare tire is the incorrect size Cause: Spare tire is the wrong size Correction: Replace spare tire			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
	Notes			
	NVCB, Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Part

Line# 1	Item # F100687175	Description TIRE, 15" RAINER, ST225/75R15EX, 6H, MAXION BLACK SPOKE 2860# 80PSI, SPARE, Y809056				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$154.70	Sub Freight	\$55.43
	Appr Qty	1.00	Appr Dlr Price	\$132.64	Appr Freight	\$55.43
	Notes					
	Dealer has submitted a part cost different than what was charged on the Forest River parts order, S5140076. The approved cost has been adjusted to \$115.34 + state allowed mark-up of 15%.					

Labor

Line# 2	Operation Code 40-106-01-11-001248	Operational Description 12 Volt In-Line Circuit Breaker or Fuse - Electrical/12 Volt Exterior/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-16 16:48:03 :: Complaint: Customer states fuse for slide keeps blowing Cause: Battery is bad and could cause fuse to blow Correction: Replace fuse			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
	Notes			

Part

Line# 1	Item # USERPART	Description Fuse				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$1.90	Sub Freight	\$0.00

Apr Qty	1.00	Apr Dlr Price	\$1.90	Apr Freight	\$0.00
Notes					

Labor

Line# 3

Operation Code	Operational Description
40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-16 16:51:03 :: Complaint: Customer states radio has no sound, radio will go on and off by itself Cause: Removed radio from the wall, found no speaker wires connected to the back of the radio. Reached inside and pulled wires out. Located the wires for all 4 speakers. Correction: Once speaker at a time took them down using an extender wire reel, checked continuity of speaker to ensure the inside speakers were on one zone and the outside speakers were on the other zone. Screwed speakers back into ceiling and walls and located the schematic for the radio. Followed discmatic to connect each of the speakers to the appropriate wires. Checked each speaker and all four speakers work and the radio does work correctly. Reinstalled radio and put trim pieces back on the sides. Additional Note : stephanie@dealer-advisors.com, 2026-01-16 16:58:27 :: There is not a flat rate code for this, chose a close to labor code.

Model#	Dlr Sub Hrs	1.50	Sub Labor Amt	\$285.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$95.00

Notes

NVCB,Time requested is excessive,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Labor

Line# 4

Operation Code	Operational Description
20-53-01-00-000702	Screw Cover - Exterior/Fiberglass Sidewall/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-16 16:52:20 :: Complaint: Customer states slide cover for docking station is missing Cause: Swivel cover is missing Correction: replace cover

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes

Part

Line# 1

Item #	Description
90M16795A	FLAP COVER FOR HOLES, BLACK, for EXTERIOR SHOWER/DOCKING STATION DOOR (VERMIN DOOR) (MIN QTY 25) 201-004-00022 STEMWASHERS FOR INSTALLATION USE 90M35731A, (15F)

Model #	Serial #	Part tag
Sub Qty	Sub Dlr Price	Sub Freight
1.00	\$1.12	\$15.81
Appr Qty	Appr Dlr Price	Appr Freight
1.00	\$0.99	\$15.81

Notes

Dealer has submitted a part cost different than what was charged on the Forest River parts order, S5290085. The approved cost has been adjusted to \$0.86 + state allowed mark-up of 15%.

Line# 2

Item #	Description
90M35731A	VERM STEMWASHER, for FLAP ATTACHEMENT for EXTERIOR SHOWER/DOCKING STATION DOOR (MIN QTY 50) 104-005-00025 FOR FLAP COVER use 90M16795A, (15F)

Model #	Serial #	Part tag
Sub Qty	Sub Dlr Price	Sub Freight
1.00	\$0.99	\$0.00
Appr Qty	Appr Dlr Price	Appr Freight
1.00	\$0.99	\$0.00

Notes

Labor

Line# 5

Operation Code	Operational Description
20-66-02-00-000664	Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-16 17:29:25 :: Complaint: Entry door is very hard to close Cause: Door is difficult to close Correction: Found several issues. First the door is hitting the door frame on the bottom. Second door is hitting striker plate and screen door catch not allowing door to close. Adjusted the door frame by removing the outer trim, taking several screws out, pushing the frame over and putting the screws

