

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2543967
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVRBXTB940854

Labor rate:	\$190.00	MILEAGE	0
OWNER INFORMATION		SITE/WAREHOUSE	050 / 050
MARILYN TOWNSEND		ITEM #	AVT26DBS
11920 HORSESHOE TR SE		DEALER RO #	72120
Albuquerque, NM 87123		CLAIM START DATE	01/07/2026
USA		CLAIM END DATE	01/20/2026

Retail Date of Purchase	01/14/2026	WARRANTY EXPIRATION DATE	01/14/2027
-------------------------	------------	--------------------------	------------

## Claim Line Details

### Labor

Line# 1	Operation Code	Operational Description		
	30-101-36-00-001078	Sliding, Pocket Door - Interior/Interior Doors/Touch Up/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2026-01-07 13:50:24 :: Complaint: Bedroom door upper corner has scratches Cause: Bedroom barn door has scratches on upper corner and down below Correction: Used Phil stick to color in scratches on the upper and lower section of the door.			

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

#### Notes

NVCB .20 to use putty ti fill in and cover the scratches on the sliding pocket door. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

### Part

Line# 1	Item #	Description				
	USERPART	Phil stick/color fill				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$1.90	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$1.90	Appr Freight	\$0.00

#### Notes

### Labor

Line# 2	Operation Code	Operational Description			
	30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code			
	<b>Complaint, Cause, Correction</b>				
	Original Note : stephanie@dealer-advisors.com, 2026-01-07 13:54:06 :: Complaint: Trim above door wallpaper is bubbling Cause: Trim above doorway wallpaper is peeling Correction: Trim needs to be removed and replaced with new piece				

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

#### Notes

The time requested is excessive for this repair, time adjusted. VCB .20 to R&R the trim due to it delaminating. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

### Part

Line# 1	Item #	Description			
	F100422411	BATTEN, 198 LU B2E, 5/32 X 1-1/2 X 96, CHILI REDWOOD 45G, 47085751			

<b>Model #</b>		<b>Serial #</b>		<b>Part tag</b>	
Sub Qty	1.00	Sub Dlr Price	\$3.17	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$3.17	Appr Freight	\$0.00

**Notes**

**Labor  
Line# 3**

**Operation Code**                      **Operational Description**  
30-474-12-00-003344                      Bracket - Interior/Appliance Securement/Resecure or Tighten/No Tread Code  
**Complaint, Cause, Correction**  
Original Note : stephanie@dealer-advisors.com, 2026-01-07 13:55:54 :: Complaint: Outside fridge is loose Cause: Outside fridge is loose due to hold down brackets missing screws Correction: Resecure outside fridge by installing new screws into the hold down brackets

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b>	\$57.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$38.00

**Notes**

The time requested is excessive for this repair, time adjusted. NVCB .20 to secure the loose mini fridge. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

**Part  
Line# 1**

<b>Item #</b>		<b>Description</b>		<b>Part tag</b>	
USERPART		Fasteners			
<b>Model #</b>		<b>Serial #</b>		<b>Sub Freight</b>	\$0.00
Sub Qty	1.00	Sub Dlr Price	\$1.90	Appr Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$1.90		

**Notes**

**Labor  
Line# 4**

**Operation Code**                      **Operational Description**  
20-66-02-00-000664                      Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code  
**Complaint, Cause, Correction**  
Original Note : stephanie@dealer-advisors.com, 2026-01-07 13:57:32 :: Complaint: Entry door does not close Cause: Front door does not close due to Lexus being out of alignment Correction: Realigned both door and frame latches to make contact with doors closed

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b>	\$57.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b>	\$57.00

**Notes**

<b>Submitted</b>	Labor Amt	\$247.00	<b>Approved</b>	Labor Amt	\$171.00
	Parts & Freight	\$6.97		Parts & Freight	\$6.97
	Total	\$253.97		Total	\$177.97

\_\_\_\_\_  
**DEALER**                                      **DATE**  
**SIGNATURE**  
I certify that I have performed these repairs consistent with Forest River Policies.

\_\_\_\_\_  
**CUSTOMER**                                      **DATE**  
**SIGNATURE**  
All repairs described have been inspected and are satisfactory.