

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	CLAIM STATUS Paid CLAIM 2532073 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2AVEC7SB940064 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 050 / 050 ITEM # AVT16BH-50 DEALER RO # 72175 CLAIM START DATE 12/18/2025 CLAIM END DATE 01/29/2026
Labor rate: \$190.00 OWNER INFORMATION VANESS ARMIJO-CLEAVER 2638 REDONDO SANTA FE NE Rio Rancho, NM 87144 USA	Retail Date of Purchase 07/01/2025 WARRANTY EXPIRATION DATE 07/01/2026

Claim Line Details

Labor

Line# 1	Operation Code 30-102-08-00-001095	Operational Description Ceiling Panel - Interior/Panels, Ceilings, & Interior Moldings/Overlay/No Tread Code
----------------	--	--

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-18 16:35:25 :: Complaint: Need to add trim to the top of the refrigerator Cause: Hole in the ceiling above the refrigerator, very visible when the doors are open Correction: Remove refrigerator completely to overlay the large hole in the ceiling and then reinstall the refrigerator. This is in reference to claim 2338486 that is now expired. Approved for 2.0 hours.

Model#	Dlr Sub Hrs 2.00	Sub Labor Amt \$380.00
Serial#	Appr Hrs 2.00	Appr Labor Amt \$380.00

Notes

The time for this repair is agreeable. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

Part

Line# 1	Item # F100193994	Description PANELING, MP 5/32 X 47 3/4" X 102", CEILING, MACHE WHITE .004 LAUAN F4E CPII PUR, 45216629D	
	Model #	Serial #	Part tag
	Sub Qty 1.00	Sub Dlr Price \$51.27	Sub Freight \$375.49
	Appr Qty 1.00	Appr Dlr Price \$51.27	Appr Freight \$375.49

Notes

Submitted	Labor Amt \$380.00	Approved	Labor Amt \$380.00
	Parts & Freight \$426.76		Parts & Freight \$426.76
	Total \$806.76		Total \$806.76

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.