

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	CLAIM STATUS Paid CLAIM 2457714 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2AVSB0SB938829 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 050 / 050 ITEM # AVT27DBS-1 DEALER RO # 72380 CLAIM START DATE 10/04/2025 CLAIM END DATE 01/22/2026
Labor rate: \$190.00 OWNER INFORMATION TIMOTHY SANDERS 31 HOLIDAY LOOP Tijeras, NM 87059 USA	
Retail Date of Purchase 10/17/2024	WARRANTY EXPIRATION DATE 10/17/2025

Claim Line Details

Labor

Line# 1	Operation Code 10-9-01-00-000169	Operational Description Enclosed Underbelly Panel(s) - Frame & Chassis/Levelers, Underbelly/Replace/ No Tread Code
	Complaint, Cause, Correction	
	Original Note : b.parrott@myersrv.com, 2025-10-04 12:20:21 :: CUSTOMER STATES UNDERBELLY FELL DURING TRIP. WATER CAME OUT WHEN UNDERBELLY FELL / ELBOW LEAKING UNDER UNIT CAUSING WATER TO POOL. THE WEIGHT OF THE WATER CAUSED THE UNDERBELLY TO FALL. CUSTOMER TIGHTENED FITTING AT TANK. WE WILL REPLACE FITTING. UNDERBELLY WILL NEED TO BE REPLACED.	
Model#	Dlr Sub Hrs 16.00	Sub Labor Amt \$3,040.00
Serial#	Appr Hrs 5.00	Appr Labor Amt \$950.00
	Notes Excessive amount requested. Authorized for 5 hours to install new underbelly. NVCB CB	

Part

Line# 1	Item # 20X25101A	Description LAMI-PLAST, BLACK CORRUGATED 71" WIDTH - UNDERBELLY
	Model #	Serial #
	Sub Qty 180.00	Sub Dlr Price \$116.13
	Appr Qty 180.00	Appr Dlr Price \$116.13
		Part tag
		Sub Freight \$104.96
		Appr Freight \$104.96
	Notes	
Line# 2	Item # USERPART	Description 17150 Spray foam, Kraken Bond Black
	Model #	Serial #
	Sub Qty 1.00	Sub Dlr Price \$14.01
	Appr Qty 1.00	Appr Dlr Price \$14.01
		Part tag
		Sub Freight \$0.00
		Appr Freight \$0.00
	Notes	

Labor

Line# 2	Operation Code 40-106-19-00-001235	Operational Description Porch Light - Electrical/12 Volt Exterior/Reseal/No Tread Code
	Complaint, Cause, Correction	
	Original Note : stephanie@dealer-advisors.com, 2026-01-22 09:19:59 :: Complaint: Exterior light cover at slide will not stay in place Cause: Cover is loose Correction: Applied silicone and reinstalled lens cover	
Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$38.00
Serial#	Appr Hrs 0.20	Appr Labor Amt \$38.00
	Notes	

NVCB .20 to seal the light. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Submitted	Labor Amt	\$3,078.00
	Parts & Freight	\$235.10
	Total	\$3,313.10

Approved	Labor Amt	\$988.00
	Parts & Freight	\$235.10
	Total	\$1,223.10

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.