

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2535423
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3CSYB7TG128431
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049B
OWNER INFORMATION		ITEM #	CSFKING33
		DEALER RO #	72478
		CLAIM START DATE	12/23/2025
		CLAIM END DATE	01/05/2026

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description			
	20-58-12-00-004601	Lower Radius Metal Trim - Exterior/Metal, Aluminum Siding/Resecure or Tighten/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : stephanie@dealer-advisors.com, 2025-12-23 17:24:05 :: Complaint: Several fasteners loose/missing around exterior of the coach on trim and j-wrap Cause: Missing/loose fasteners Correction: Resecure and installed new fasteners				
Model#		Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#		Appr Hrs	0.30	Appr Labor Amt	\$57.00
	Notes				
	NVCB,time to secure exterior metal.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD				

Part

Line# 1	Item #		Description			
	USERPART		Fasteners			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$2.85	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.85	Appr Freight	\$0.00
	Notes					

Labor

Line# 2	Operation Code	Operational Description			
	10-9-02-11-000204	Sensing Unit - Frame & Chassis/Levelers, Underbelly/Adjust/Electrical			
	Complaint, Cause, Correction				
	Original Note : stephanie@dealer-advisors.com, 2025-12-23 17:25:34 :: Complaint: Leveling system is out of calibration on auto level Cause: Out of calibration Correction: Set zero and tested				
Model#		Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#		Appr Hrs	0.20	Appr Labor Amt	\$38.00
	Notes				
	NVCB,time is excessive to reset system.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD				

Labor

Line# 3	Operation Code	Operational Description			
	30-100-02-00-001044	Drawer Guides or Tracks, pair - Interior/Cabinetry/Adjust/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : stephanie@dealer-advisors.com, 2025-12-23 17:27:28 :: Complaint: Top drawer next to stove is getting stuck Cause: Retainer clip is detached/binding Correction: Performed adjustments and reinstalled retainer tab				

Model#

Serial#

Notes

Dlr Sub Hrs

Appr Hrs

0.30

0.20

Sub Labor Amt \$57.00

Appr Labor Amt \$38.00

Labor

Line# 4

Operation Code

Operational Description

Complaint, Cause, Correction

30-100-24-00-001043

Drawer Front - Interior/Cabinetry/Repair/No Tread Code

Original Note : stephanie@dealer-advisors.com, 2025-12-23 17:28:57 :: Complaint: Bottom drawer next to stove is getting stuck Cause: Latch misalignment Correction: Realigned and tested Additional Note : stephanie@dealer-advisors.com, 2025-12-23 17:31:21 :: NO FRC for the latch mechanism, chose the closest one for front drawer repair

Model#

Serial#

Notes

Dlr Sub Hrs

Appr Hrs

0.20

0.20

Sub Labor Amt \$38.00

Appr Labor Amt \$38.00

Labor

Line# 5

Operation Code

Operational Description

Complaint, Cause, Correction

30-100-24-00-001048

Cabinet or Closet Shelf - Interior/Cabinetry/Repair/No Tread Code

Original Note : stephanie@dealer-advisors.com, 2025-12-23 17:31:54 :: Complaint: Cabinet above the TV has misaligned wood frame Cause: Fasteners are detached Correction: Resecure with new fasteners

Model#

Serial#

Notes

Dlr Sub Hrs

Appr Hrs

0.20

0.20

Sub Labor Amt \$38.00

Appr Labor Amt \$38.00

Part

Line# 1

Item #

Description

Model #

Serial #

Sub Qty

Appr Qty

Sub Dlr Price

Appr Dlr Price

Part tag

Sub Freight

Appr Freight

USERPART

Fasteners

1.00

1.00

\$1.90

\$1.90

\$0.00

\$0.00

Labor

Line# 6

Operation Code

Operational Description

Complaint, Cause, Correction

20-66-02-00-000664

Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code

Original Note : stephanie@dealer-advisors.com, 2025-12-23 17:33:42 :: Complaint: Entry door and screen door are sticking causing a hard open/close procedure Cause: Frame catch is hitting the door Correction: Performed adjustments and tested

Model#

Serial#

Notes

Dlr Sub Hrs

Appr Hrs

0.30

0.30

Sub Labor Amt \$57.00

Appr Labor Amt \$57.00

Submitted	Labor Amt	\$304.00	Approved	Labor Amt	\$266.00
	Parts & Freight	\$4.75		Parts & Freight	\$4.75
	Total	\$308.75		Total	\$270.75

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.