

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2559956
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVPB6TB941406
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT25RBS
		DEALER RO #	72574
		CLAIM START DATE	01/23/2026
		CLAIM END DATE	01/23/2026

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 40-106-01-11-001248	Operational Description 12 Volt In-Line Circuit Breaker or Fuse - Electrical/12 Volt Exterior/Replace/ Electrical		
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-01-23 10:03:47 :: Complaint: Refrigerator is not working Cause: 15 amp fuse is missing Correction: Replace fuse			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
	Notes			

Part

Line# 1	Item # USERPART	Description Fuse		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$1.90
	Appr Qty	1.00	Sub Freight	\$0.00
			Appr Dlr Price	\$1.90
			Appr Freight	\$0.00
	Notes			

Labor

Line# 2	Operation Code 30-100-24-00-001046	Operational Description Cabinet Door - Interior/Cabinetry/Repair/No Tread Code		
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-01-23 10:05:01 :: Complaint: Bathroom cabinet doors are rubbing Cause: Cabinet doors are mounted too close together Correction: Realign the doors			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$76.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$76.00
	Notes NVCB .40 to adjust the cabinet doors. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.			

Submitted	Labor Amt	\$114.00	Approved	Labor Amt	\$114.00
	Parts & Freight	\$1.90		Parts & Freight	\$1.90
	Total	\$115.90		Total	\$115.90

DEALER
SIGNATURE

DATE

CUSTOMER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

All repairs described have been inspected and are satisfactory.