



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 71814
Promised Date:
24 OCT 25



WO #: 71814 (Appointment Date: 13 JUN 2025 - Time: 02:15pm)

Customer Name: 59220 - PIPHER, TIM

Completed Date: 12 MAR 26

Invoice#:

Author: BRIAN

Stock Desc: 2023 VENTANA 4369

Serial#: 416175

Chassis#: 4UZFCHE3PCUH4933

Miles/Hrs: 7199

Tag#: 7062

Purchased Date:

Warranty Date:

Date In: 13 JUN 25

Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THE COMPARTMENT DOOR LATCH INOPERATIVE

CAUSE: Misaligned latch and catch caused damage to latching mechanism on handle.

CORRECTION: Replace complete latching mechanism on door. Perform adjustments on both latch and catch assemblies.
.50HRS

Labor

Job #	Description	Total
1	COMPARTMENT DOOR LOCK/LATCH DIAG	92.50

Parts

Part #	Description	Qty	Price	Total
118613	PADDLE HANDLE LH CHROME	1.00	110.18	110.18
121672	STRIKER PIN SH BAGGAGE DOOR	1.00	16.11	16.11
160485	LATCH ROTARY MINI #141 LH	1.00	8.61	8.61

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 227.40

Job #1A - Warranty

COMPLAINT: CUSTOMER STATES PASSENGER SIDE (2ND FROM FRONT) COMPARTMENT DOOR WILL NOT OPEN PROPERLY / WILL NOT OPERATE WITH REMOTE

CAUSE: DEFECTIVE LATCH

CORRECTION: Replace complete latching mechanism on door. Perform adjustments on both latch and catch assemblies.
1.00HRS

Labor

Job #	Description	Total
1A	COMPARTMENT DOOR LATCH R&R	185.00

Parts

Part #	Description	Qty	Price	Total
64291	LATCH - LH MINI BAGGAGE DOOR	2.00	8.61	17.22
118612	PADDLE HANDLE RH CHROME	2.00	110.18	220.36

Customer #: 59220
PIPHER, TIM





121672	STRIKER PIN SH BAGGAGE DOOR	2.00	16.11	32.22
--------	-----------------------------	------	-------	-------

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	38.49	38.49

Subtotal for Job #1A: 493.29

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES MOLDING AROUND SHOWER IS COMING OFF.

CAUSE: Loss of grip in seam with press fit seal.

CORRECTION: Reinstalled seal by press fitting from top to bottom. Sealed with silicone to prevent future back out of seal. Completed

Labor

Job #	Description	Total
2	SHOWER INSERT MOULDING DIAG	55.50

Subtotal for Job #2: 55.50

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES BATHROOM DOOR LATCH DOESN'T WORK. KM

CAUSE: Door warped

CORRECTION: Replace door. Order. Swivel door. Need extra time for hardware install.
 22 1/4 wide x 75 3/8 tall

Labor

Job #	Description	Total
3	BATHROOM DOOR ADJUST	185.00

Parts

Part #	Description	Qty	Price	Total
021893	DOOR HINGED REC PNL - SPFY	1.00	441.92	441.92

Subtotal for Job #3: 626.92

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES FREEZER DOOR DOESN'T LATCH.

CAUSE: Plastic retainer stripped on slotted hold back

CORRECTION: Replace plastic transport lock. See pic

Labor

Job #	Description	Total
4	FREEZER DOOR LATCH INOP	55.50

Parts

Part #	Description	Qty	Price	Total
103690	SPRING PLUNGER 1/4" X 1" STD HEX	1.00	18.16	18.16
131048	LATCH REFER ALUMINUM EXT BLACK	1.00	5.23	5.23
131057	T-LOCK REV-2 REFER LATCH	1.00	13.66	13.66

Subtotal for Job #4: 92.55

Job #5 - Warranty

COMPLAINT: RECALL ON TOILET SWITCH ENHANCEMENT. TSB 595.

CAUSE: TWO TOILETS .30 EACH



CORRECTION: PERFORMED RECALL ON TWO TOILETS
.60HRS

Labor

Job #	Description	Total
5	TOILET RECALL TSB 595 TWO TOILETS	111.00

Parts

Part #	Description	Qty	Price	Total
023689	DIODE 6A 50V (4PK)	2.00	5.85	11.70
024171	TERMINAL 12 - 10 FM INS DISC	4.00	0.17	0.68

Subtotal for Job #5: 123.38

Job #6 - External

COMPLAINT: CUSTOMER STATES THERE IS NO WHERE TO PUT THE LICENCE PLATE ON.

CAUSE: License plate mounting location on driver side lower corner.

CORRECTION: Installed hardware for customers license plate. Completed

Subtotal for Job #6: 0.00

Parts Total: 896.05
Labour Total: 684.50
Sublet Total: 0.00
Extras Total: 38.49

WORK ORDER TOTAL: 1,619.04

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 12 Mar 2026

W/O: 71814
Promised Date: 24 OCT 25



Customer #: 59220
PIPHER, TIM

