



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72260-1
Promised Date:
47 MAR 26



WO #: 72260-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 13 MAR 26

Invoice#:

Author: ADVISOR

Stock Desc: 9605 2026 OPEN RANGE

COLT 26DBS

Serial#: 58TBM0BP7T76X3088

Chassis#: 58TBM0BP7T76X3088

Miles/Hrs:

Tag#:

Purchased Date:

Warranty Date:

Date In: 17 JAN 26

Time In:

Job #1 - Warranty

COMPLAINT: A/c flap on living room ceiling unit will not stay open

CAUSE: Plastic catch tabs not set far enough into plastic cog wheel to allow full engagement which in turn caused flap to close.

CORRECTION: Removed ceiling assembly. Removed catch tabs. Oblonged each screw hole to allow forward engagement of catch tab. Reinstalled and tested function of ceiling assembly. Completed.

Asking for .50hr

Labor

Job #	Description	Total
1	AIR CONDITIONER FLAPS	89.50
Subtotal for Job #1:		89.50

Job #2 - Warranty

COMPLAINT: Bed frame not secure

CAUSE: Panel detached

CORRECTION: Resecured with 4 fasteners into structure. Completed

Asking .20hr

Labor

Job #	Description	Total
2	BED FRAME panel	44.75
Subtotal for Job #2:		44.75

Job #3 - Warranty

COMPLAINT: Thermostat face will not stay on

CAUSE: Replace

CORRECTION: Completed. Turned in to service

Labor

Job #	Description	Total
3	AUTO T-STAT	107.40

Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 72260-1
Promised Date: 17 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Parts				
Part #	Description	Qty	Price	Total
2071951	THERMOSTAT, DIGITAL HEAT/COOL BLACK RVP C-SERIES	1.00	53.20	53.20
Subtotal for Job #3:				160.60

Job #4 - Warranty

COMPLAINT: Bedroom sliding door frame detaching

CAUSE: Adhesion failure

CORRECTION: Removed old adhesive. Reapplied silicone to frame. Installed plastic door frame fascia and secured with fasteners. Completed
Asking .30 hr

Labor		
Job #	Description	Total
4	SLIDING DOOR - INTERIOR	89.50
Subtotal for Job #4:		89.50

Job #5 - Warranty

COMPLAINT: Front cap l.e.d light detaching

CAUSE: Remove clean replace, rewire and reseal. Completed

CORRECTION: Completed. Requesting 1.0 hr

Labor				
Job #	Description	Total		
5	FRONT CAP LIGHT	35.80		
Parts				
Part #	Description	Qty	Price	Total
2087249	LIGHT, STRIP WHITE FUSION 93.01" 12V	1.00	91.23	91.23
Subtotal for Job #5:				127.03

Parts Total:	144.43
Labour Total:	366.95
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	511.38

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.



Customer Signature : _____

Date: 13 Mar 2026

W/O: 72260-1
Promised Date: 17 MAR 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Customer Work
Order

