

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Authorized
 CLAIM 2543554
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2AVECXTG815404
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 452 / 452
 ITEM # AVT16RBX-452
 DEALER RO # 72581
 CLAIM START DATE 01/07/2026
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 20-43-01-00-000589 Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 11:05:33 :: Complaint: Black strip on passenger side front top is bubbling Cause: Decal is bubbling Correction: Recommend removal of bubbled decal and replacement with a new one

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$95.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$19.00

Notes
 NVCB,Time requested is excessive ,decal does not need replaced,Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. air bubbles can be removed by pricking with knife or needle and smoothing out.TD

Labor

Line# 2 **Operation Code** **Operational Description**
 20-43-01-00-000589 Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 11:07:11 :: Complaint: Drivers rear large black decal is bubbling Cause: Decal is bubbled Correction: Recommend the removal of the old decal which will involve the removal of the drivers side corner molding and vinyl insert, clean off silicone, install new decal, reinstall corner molding and vinyl insert and reseal

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt \$190.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$19.00

Notes
 NVCB,Time requested is excessive.Decal does not need replaced, air bubble can be removed by pricking it a knife or needle and smooth out.Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Labor

Line# 3 **Operation Code** **Operational Description**
 20-43-01-00-000589 Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 11:08:38 :: Complaint: Decal is coming apart and coming off Cause: Decal is coming off/apart Correction: Recommend the repalcement of the whole front forest river letter decal. Will require removal of old decal, clean the surface and install new decal

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$95.00
Serial#	Appr Hrs	0.50	Appr Labor Amt \$95.00

Notes

NVCB,R&R decals from what I can tell a bad prep job.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Submitted

Labor Amt	\$380.00
Parts & Freight	\$0.00
Total	\$380.00

Approved

Labor Amt	\$133.00
Parts & Freight	\$0.00
Total	\$133.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.