

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2561447
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC9TG815409
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	452 / 452
OWNER INFORMATION		ITEM #	AVT16RBX-452
		DEALER RO #	72583-1
		CLAIM START DATE	01/26/2026
		CLAIM END DATE	03/02/2026

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 20-43-01-00-000589	Operational Description Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-01-26 12:18:54 :: Complaint: Right rear black decals are bubbling Cause: Decals are bubbling Correction: Replace decal, corner trim and vinyl insert will have to be removed. Old decal removed and area cleaned, install new decal and reinstall corner molding and vinyl insert and silicone the edge			
Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$190.00
Serial#	Appr Hrs	0.25	Appr Labor Amt	\$47.50
	Notes Can you have the tech try to pin hole the bubble squeegee the air out while use a heat gun to reattach.TD Tech repaired as suggested, but did mention they will still likely need to be replaced at a later time. NVCB To pin hole and squeegee ,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Labor

Line# 2	Operation Code 20-43-01-00-000589	Operational Description Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-01-26 12:20:31 :: Complaint: Right front black stripe decal is bubbling Cause: Decal is bubbling Correction: Recommend removal and replacement of the decal, cleaning area and installing a new decal.			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.25	Appr Labor Amt	\$47.50
	Notes Can you have the tech try to pin hole the bubble squeegee the air out while use a heat gun to reattach.TD Tech repaired as suggested, but did mention they will still likely need to be replaced at a later time. NVCB, To pin hole and squeegee.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Labor

Line# 3	Operation Code 20-43-01-00-000589	Operational Description Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2026-01-26 12:21:17 :: Complaint: :Left front top black stripe			

decal is bubbling Cause: Decal is bubbling Correction: Recommend removal and replacement of the decal, cleaning area and installing a new decal.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.25	Appr Labor Amt	\$47.50

Notes

Can you have the tech try to pin hole the bubble squeegee the air out while use a heat gun to reattach.TD

Tech repaired as suggested, but did mention they will still likely need to be replaced at a later time.

NVCB,To move blind &fill holes Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Labor

Line# 4

Operation Code	Operational Description
20-43-01-00-000589	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-26 12:22:29 :: Complaint: Left rear black decal is bubbling Cause: Decal is bubbling Correction: Recommend removal and replacement of the decal, cleaning area and installing a new decal. Corner molding and vinyl insert will need to be removed and then new silicone added.

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$190.00
Serial#	Appr Hrs	0.25	Appr Labor Amt	\$47.50

Notes

Can you have the tech try to pin hole the bubble squeegee the air out while use a heat gun to reattach.TD

Tech repaired as suggested, but did mention they will still likely need to be replaced at a later time.

NVCB,To move blind &fill holes Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Labor

Line# 5

Operation Code	Operational Description
60-140-01-00-001571	Lav Sink Stopper - Plumbing/Bathroom (Lavatory) Sink/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-26 12:23:15 :: Complaint: Bathroom sink stopper is missing Cause: Sink stopper is missing Correction: Replace sink stopper

Model#	Dlr Sub Hrs	0.00	Sub Labor Amt	\$0.00
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes

Part

Line# 1

Item #	Description		
60P15562A	WHITE SINK PLUG, used w/ LAV SINKS, FOR SINK 16156PW, 65500110W		
Model #	Serial #		
Sub Qty	Sub Dlr Price	Sub Freight	Part tag
1.00	\$1.11	\$16.30	
Appr Qty	Appr Dlr Price	Appr Freight	
1.00	\$1.12	\$16.30	

Notes

Computer rounded up \$0.01

Submitted

Labor Amt	\$570.00
Parts & Freight	\$17.41
Total	\$587.41

Approved

Labor Amt	\$190.00
Parts & Freight	\$17.42
Total	\$207.42

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.