

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2531686
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2AVTB1SB938658
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 050 / 050
 ITEM # AVT28BHS-50
 DEALER RO # 72750
 CLAIM START DATE 12/18/2025
 CLAIM END DATE 02/27/2026

Labor rate: \$190.00

OWNER INFORMATION

ABEL TAFOYA
 2212 GARLAND CT SW
 Albuquerque, NM 87121
 USA

Retail Date of Purchase 06/07/2025

WARRANTY EXPIRATION DATE

06/07/2026

Claim Line Details

Labor

Line# 2 **Operation Code** **Operational Description**
 30-100-01-00-001061 Nightstand or End Table - Mounted - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2025-12-18 13:36:40 :: Complaint: Customer states end tables on each side of the bed have gaps causing a draft of air Cause: Gap between side of the master bed and exterior wall is allowing air to come from the basement under the bed Correction: Sealed the edge all the way around with clear silicone Additional Note : stephanie@dealer-advisors.com, 2025-12-18 13:41:48 :: **this is not a replacement, it was the only code available for the nightstand. This is just a reseal for both nightstands.**

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$95.00

Notes

The time for this repair is agreeable. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

Part

Line# 1 **Item #** **Description**
 USERPART Clear silicone
Model # **Serial #** **Part tag**

Sub Qty	1.00	Sub Dlr Price	\$4.75	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$4.75	Appr Freight	\$0.00

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 60-141-24-00-001602 Fiberglass Tub, Shower Surround - Plumbing/Shower, Tub Surround/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2025-12-18 13:43:55 :: Complaint: Inside shower top wall is coming apart, when you walk into the shower it will be on the left side Cause: Found the shower wall loose on the short ends. Correction: At the top, added 3 push buttons to each side by drilling holes through the shower wall and the wall pressing the buttons in and securing the shower wall back into place. Used clear silicone across the top of the whole shower to seal it and prevent water from getting between the walls.

Model#	Dlr Sub Hrs	0.25	Sub Labor Amt	\$47.50
Serial#	Appr Hrs	0.25	Appr Labor Amt	\$47.50

Notes

The time for this repair is agreeable. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

Part

Line# 1	Item #		Description			
	USERPART		Clear silicone			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$2.38	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.38	Appr Freight	\$0.00

Notes

Line# 2	Item #		Description			
	USERPART		Clips			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$0.30	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$0.30	Appr Freight	\$0.00

Notes

Labor

Line# 4	Operation Code	Operational Description
	20-58-12-00-004601	Lower Radius Metal Trim - Exterior/Metal, Aluminum Siding/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-18 13:47:52 :: Complaint: Near the rear door to the right at the J-wrap there is a screw missing Cause: Screw fell out of J-wrap Correction: Replace the missing screw with a new one

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00

Notes

Part

Line# 1	Item #		Description			
	USERPART		Screw			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$0.95	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$0.95	Appr Freight	\$0.00

Notes

Labor

Line# 5	Operation Code	Operational Description
	30-102-12-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-18 13:50:30 :: Complaint: Customer states the panel to the right by the window and before the bathroom is loose Cause: Found the panel between the wipe down in the hallway came loose, Correction: Stapled panel back to the stud and used putty to cover the staple holes

Model#	Dlr Sub Hrs	0.25	Sub Labor Amt	\$47.50
Serial#	Appr Hrs	0.25	Appr Labor Amt	\$47.50

Notes

The time for this repair is agreeable. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.

Part

Line# 1	Item #		Description			
	USERPART		Staples & putty			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$2.38	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.38	Appr Freight	\$0.00

Notes

Submitted	Labor Amt	\$209.00
	Parts & Freight	\$10.76
	Total	\$219.76

Approved	Labor Amt	\$209.00
	Parts & Freight	\$10.76
	Total	\$219.76

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.