

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Paid
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2533756
12024 CENTRAL AVE S.E.		<b>CLAIM ORIGIN</b>	WEB
ALBUQUERQUE, NM 87123		<b>ORIGINAL CLAIM ID</b>	
USA		<b>VIN</b>	4X4TRPV20TB035176
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	080 / 080
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	RPT203-80
ROBERT VIGIL		<b>DEALER RO #</b>	72190
355 NM 76 UNIT A		<b>CLAIM START DATE</b>	12/22/2025
Santa Cruz, NM 87567		<b>CLAIM END DATE</b>	02/26/2026
USA			
<b>Retail Date of Purchase</b>	01/31/2026	<b>WARRANTY EXPIRATION DATE</b>	01/31/2027

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-102-12-00-002691	Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2025-12-22 11:04:05 :: Complaint: Panel behind right front close is loose Cause: Panel came loose Correction: Restapled panel back into place			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$38.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$38.00
	<b>Notes</b>			

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>		
	USERPART	Staples		
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>	
	<b>Sub Qty</b>	1.00	<b>Sub Dlr Price</b>	\$1.90
	<b>Appr Qty</b>	1.00	<b>Appr Dlr Price</b>	\$1.90
			<b>Sub Freight</b>	\$0.00
			<b>Appr Freight</b>	\$0.00
	<b>Notes</b>			

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-102-24-00-003061	Ceiling Panel - Touchup - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : stephanie@dealer-advisors.com, 2025-12-22 11:05:48 :: Complaint: Hole in ceiling near air conditioner cover Cause: Hole in the ceiling panel, it is not punched all the way through Correction: Used a putty file stick and filled the hole			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b>	\$19.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b>	\$19.00
	<b>Notes</b>			

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>		
	USERPART	Putty		
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>	
	<b>Sub Qty</b>	1.00	<b>Sub Dlr Price</b>	\$0.95
	<b>Appr Qty</b>	1.00	<b>Appr Dlr Price</b>	\$0.95
			<b>Sub Freight</b>	\$0.00
			<b>Appr Freight</b>	\$0.00

Notes

Labor Line# 3

Operation Code 20-453-01-17-001104 Operational Description Folding Bunk Door Locking Travel Latch - Exterior/Folding Bunk End/Replace/Latch

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-22 11:07:31 :: Complaint: Latch for lower bunk needs to be adjusted, it is not holding bunk in the upright position. Cause: Not enough of the latch bar is in the plate to hold the bed up right Correction: Added a piece of batten trim behind the plate, latch now holds upright and will not fall Additional Note : stephanie@dealer-advisors.com, 2025-12-22 11:08:53 :: \*\*no replacement latch part, just added batten trim to get correction\*\*closest code available\*\*

Table with 4 columns: Model#, Dlr Sub Hrs, Appr Hrs, Sub Labor Amt. Values: Model#, Dlr Sub Hrs 0.10, Sub Labor Amt \$19.00; Serial#, Appr Hrs 0.10, Appr Labor Amt \$19.00

Notes

Part

Line# 1

Table with 6 columns: Item #, Description, Model #, Serial #, Sub Qty, Sub Dlr Price, Sub Freight, Appr Qty, Appr Dlr Price, Appr Freight. Values: USERPART, Trim used behind plate, Model #, Serial #, Sub Qty 1.00, Sub Dlr Price \$0.95, Sub Freight \$0.00, Appr Qty 1.00, Appr Dlr Price \$0.95, Appr Freight \$0.00

Notes

Labor

Line# 4

Operation Code 40-106-01-12-001216 Operational Description Clearance Light - Electrical/12 Volt Exterior/Replace/Exterior Lighting

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-22 11:10:53 :: Complaint: Drivers side front marker light is not working Cause: Marker light is not working, found during the PDI Correction: Replace light - strip silicone, disconnect wires, install new light, reconnect wires, apply new silicone

Table with 4 columns: Model#, Dlr Sub Hrs, Appr Hrs, Sub Labor Amt. Values: Model#, Dlr Sub Hrs 0.50, Sub Labor Amt \$95.00; Serial#, Appr Hrs 0.10, Appr Labor Amt \$19.00

Notes

dealer has requested more time than what is normally approved for this repair. If you have additional information or need more time as the repair progresses, please contact me directly to discuss and I can continue to review it.

Part

Line# 1

Table with 6 columns: Item #, Description, Model #, Serial #, Sub Qty, Sub Dlr Price, Sub Freight, Appr Qty, Appr Dlr Price, Appr Freight. Values: 20X73000A, LIGHT, 3/4" BULLET LIGHT, COOL WHITE \*\*11101C\*\*, Model #, Serial #, Sub Qty 1.00, Sub Dlr Price \$1.80, Sub Freight \$0.00, Appr Qty 1.00, Appr Dlr Price \$1.80, Appr Freight \$0.00

Notes

Labor

Line# 5

Operation Code 30-100-01-00-001035 Operational Description Cabinet Door - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2025-12-22 11:13:20 :: Complaint: Cabinet door is damaged, found during PDI Cause: Damaged door on top cabinets Correction: Will need to be replaced with a new 14X48 door Additional Note : stephanie@dealer-advisors.com, 2025-12-22 11:14:05 :: Hinges and handle will also need to be replaced, .5 labor for door, handle and hinge replacement

Table with 4 columns: Model#, Dlr Sub Hrs, Appr Hrs, Sub Labor Amt. Values: Model#, Dlr Sub Hrs 0.50, Sub Labor Amt \$95.00; Serial#, Appr Hrs 0.40, Appr Labor Amt \$76.00

Notes

can this be repaired? We can do that if we can get the touchup and filler for it.

excessive time requested. Time reduced based on photos, description and flat rate.  
 authorized to repair as stated  
 authorized to replace cab door

**Part**

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>			
	F100568392	DOOR, CABINET 14 X 48 FLAT PANEL - BRIGHTON WHITE			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
	<b>Sub Qty</b>	1.00	<b>Sub Dlr Price</b>	\$39.43	<b>Sub Freight</b> \$54.30
	<b>Appr Qty</b>	1.00	<b>Appr Dlr Price</b>	\$39.43	<b>Appr Freight</b> \$54.30

**Notes**

<b>Submitted</b>	Labor Amt	\$266.00	<b>Approved</b>	Labor Amt	\$171.00
	Parts & Freight	\$99.33		Parts & Freight	\$99.33
	Total	\$365.33		Total	\$270.33

\_\_\_\_\_  
**DEALER** **DATE**

**SIGNATURE**  
 I certify that I have performed these repairs consistent with Forest River Policies.

\_\_\_\_\_  
**CUSTOMER** **DATE**

**SIGNATURE**  
 All repairs described have been inspected and are satisfactory.