



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25239



WO #: 25239

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11084

Stock Desc: 2025 THTT FOREST RIVER ROGUE
26L140

Model: 26L140

Serial #: 4X4TVGB28S5403472

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 08 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: COMPARTMENT DOOR AREA ON THE FRONT OF THE UNIT HAS EXCESSIVE METAL SHAVING ON ALL SIDES OF SEALANT

CAUSE: NOTED ON DAF

CORRECTION: NEED TO REMOVE ALL SEALANT, CLEAN AREA AND RESEAL
LABOR 1.2

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: BLACK PRINTS ON CEILING AT PROJECTOR IN BEDROOM. MARKS ARE OVER HALF WAY ACROSS CEILING PANELS.

CAUSE: NOTED ON DAF

WHEN INSTALLED AT FACTORY AREA WAS NOT CLEANED.

CORRECTION: CLEAN ALL BLACK MARKS OFF CEILING AND PROJECTOR AREA
LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR HAS SCRATCHES ON IT

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND CLEAN SCRATCHED AREA
LABOR .10

Subtotal for Job #3: 0.00

Job #5 - Warranty

COMPLAINT: COMPARTMENT DOOR TO THE RIGHT OF THE ENTRY DOOR WILL NOT SHUT AT THE BOTTOM. THIS CAUSES THE DOOR TO STICK OUT AT THE BOTTOM.

CAUSE: NOTED ON DAF.

CORRECTION: ADJUST COMPARTMENT DOOR
LABOR .20

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: STILE AND TRACK GOING INTO THE BATHROOM IS SCRATCHED.

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND CLEAN SCRATCHED AREAS
LABOR .10

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: MICROWAVE HAS SEVERAL SCRATCHES ALL ACROSS THE FRONT AND SIDES.

MOD# OTR1603B

SER#240730024000294

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE MICROWAVE
LABOR .50

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: HOLE FOUND IN AWNING FABRIC.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE AWNING FABRIC
LABOR 1.5

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: WHITE METAL AT REAR OF UNIT IS SCRATCHED.

CAUSE: NOTED ON DAF

CORRECTION: COLOR,FILL AND CLEAN SCRATCHED AREA
LABOR .20

Subtotal for Job #9: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 08 Apr 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,