

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2261619
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4MFRG24RF064929
 CHASSIS VIN 1FDXE4FN2SDD01919
 MILEAGE 6999
 SITE/WAREHOUSE 034 / 034A
 ITEM # FRC3051SF
 DEALER RO # 25261
 CLAIM START DATE 04/11/2025
 CLAIM END DATE 07/29/2025

Labor rate: \$165.00

OWNER INFORMATION

JANET WILLIS
 1845 BAYS MOUNTAIN RD
 New Market, TN 37820
 USA

Retail Date of Purchase 04/12/2025 WARRANTY EXPIRATION DATE 04/12/2026

Claim Line Details

Labor

Line# 1 Operation Code Operational Description
 SB-460-05-00-004690 34-1893 - CLASS C; SKYLIGHTS CRACKING - INSPECTION ONLY - Technical Service Bulletin/Skylights/Inspect/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-04-11 11:31:05 :: Complaint: Service advisory 34-1893 Skylight cracking Skylight number 1 in shower area Cause: Service advisory 34-1893 Correction: This skylight is not cracked, inspection only

Model#	Dlr Sub Hrs	0.25	Sub Labor Amt	\$41.25
Serial#	Appr Hrs	0.25	Appr Labor Amt	\$41.25

Notes
 NOVCB

Part

Line# 1	Item #	Description			
	USERPART	Lap sealant, white			
	Model #	Serial #	Part tag		
	Sub Qty 3.00	Sub Dlr Price \$30.63	Sub Freight	\$0.00	
	Appr Qty 3.00	Appr Dlr Price \$30.63	Appr Freight	\$0.00	

Notes

Labor

Line# 2 Operation Code Operational Description
 SB-460-05-00-004690 34-1893 - CLASS C; SKYLIGHTS CRACKING - INSPECTION ONLY - Technical Service Bulletin/Skylights/Inspect/No Tread Code

Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-04-11 11:32:35 :: Complaint: Service advisory 34-1893 skylight cracking. Skylight number 2 over bathroom sink area Cause: Service advisory 34-1893 Correction: Skylight is not cracked at this time, inspection only

Model#	Dlr Sub Hrs	0.25	Sub Labor Amt	\$41.25
Serial#	Appr Hrs	0.00	Appr Labor Amt	\$0.00

Notes
 Only 1 inspection per coach. If there was 1 cracked then you would be able to claim 1 for repair and the other for inspect

Labor

Line# 3 Operation Code Operational Description
 SB-460-01-00-004691 34-1893 - CLASS C; SKYLIGHTS CRACKING - INSPECTION AND REMEDY - Technical Service Bulletin/Skylights/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : ashlee@dealer-advisors.com, 2025-04-11 11:33:45 :: Complaint: Service advisory 34-1893 skylight cracking, skylight number 3 living area Cause: Service advisory 34-1893 Correction: Skylight is cracked and needs to be replaced

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$165.00
Serial#	Appr Hrs	1.00	Appr Labor Amt	\$165.00

Notes

Only 1 inspection per coach. If there was 1 cracked then you would be able to claim 1 for repair and the other for inspect
NOVCB

Part

Line# 2	Item #	Description			
	F100716954	TSB KIT: INCLUDES (1) 22" X 30" POLYCARBONATE SKYLIGHT (2230031252), (1) ROLL OF 1/8" BUTYL TAPE (Q13018-34), (40) SCREWS (8Z100SQP0G/P638), (4) TUBES OF DICOR 502LSW SEAL ****KIT CAN ONLY BE SOLD FOR TSB QUALIFYING UNITS*****			
	Model #	22 X 30	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$64.86	Sub Freight \$44.93
	Appr Qty	1.00	Appr Dlr Price	\$64.86	Appr Freight \$44.93

Notes

Submitted	Labor Amt	\$247.50	Approved	Labor Amt	\$206.25
	Parts & Freight	\$140.42		Parts & Freight	\$140.42
	Total	\$387.92		Total	\$346.67

DEALER **DATE**
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE
 All repairs described have been inspected and are satisfactory.