



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25291



WO #: 25291

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:
 Author: S.DAVIS
 Location: IH
 Invoice #:

Stock #: 11092
 Stock Desc: 2025 TT KZ-RV CONNECT 313MK
 Model: 313MK
 Serial #: 4EZTL3322S403555
 Chassis #:
 Mileage:0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 16 APR 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 07 MAY 25
 Warr. Date:

Job #1 - Warranty

COMPLAINT: SEALANT IN FOUR SPOTS ON THE EXTERIOR DOOR SIDE OF THE UNIT

CAUSE: NOTED ON DAF

CORRECTION: SEALANT NEEDS TO BE CLEANED OFF, WASHING THE UNIT AS NORMAL DID NOT REMOVE THE SEALANT.

LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SHADE OVER DOUBLE SEATING IN THE REAR OF UNIT WAS LAYING DOWN WHEN ARRIVED TO DEALER.

CAUSE: NOTED ON DAF

CORRECTION: INSTALL SHADE AND TEST

LABOR .10

Labor

Job #	Description	Hours	Total
2	REATTACHED	0.10	17.50

Subtotal for Job #2: 17.50

Job #3 - Warranty

COMPLAINT: FURRIION STOVE VENT IS SIDEWAYS, NOT INSTALLED CORRECTLY AT BUILD TIME.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND INSTALL THE STOVE VENT COVER CORRECTLY.

LABOR .20

Labor

Job #	Description	Hours	Total
3	RESECURE	0.05	8.75

Subtotal for Job #3: 8.75

Job #4 - Warranty

COMPLAINT: VALANCE OVER SEATING IN LIVING AREA IS NOT SECURED TO THE WALL.

Customer #: 47602
 TRI-AM RV CENTER-EAST
 TN,



CAUSE: NOTED ON DAF.

CORRECTION: RESECURE THE VALANCE TO THE WALL.
LABOR .10

Labor			
Job #	Description	Hours	Total
4	ADJ LOCATION OF SCREW AND RESECURE	0.10	17.50
Subtotal for Job #4:			17.50

Job #5 - Warranty

COMPLAINT: STILE OVER LIVING AREA SEATING HAS HOLES IN IT.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR,BLEND AND CLEAN AREA.
LABOR .10

Labor			
Job #	Description	Hours	Total
5	FILL COLOR AND BLEND AREA	0.05	8.75
Subtotal for Job #5:			8.75

Job #6 - Warranty

COMPLAINT: RIGHT SIDE (IF SITTING ON SEATING) WILL NOT GO IN OR OUT WITHOUT FORCE.

CAUSE: INTERNAL MECHANISM IS FAULTY AND WILL NOT ALLOW THE FOOT REST TO WORK CORRECTLY. NOTED ON DAF.

CORRECTION: RIGHT SIDE OF RECLINER SEATING NEEDS REPALCED.
LABOR .50

Labor			
Job #	Description	Hours	Total
6	ADJUSTED SEATING	0.50	87.50
Subtotal for Job #6:			87.50

Job #7 - Warranty

COMPLAINT: BLACK MARKS ON THE WALL ABOVE THE SHOWER SURROUND.

CAUSE: NOTED ON DAF.

CORRECTION: CLEAN OFF THE BLACK MARKS. COLOR AND BLEND AREA IF NEEDED.
LABOR .10

Labor			
Job #	Description	Hours	Total
7	CLEAN OFF BLACK MARKS	0.10	17.50
Subtotal for Job #7:			17.50

Job #8 - Warranty

COMPLAINT: DOOR FACING GOING INTO THE BEDROOM HAS BLACK MARKS.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN OFF ALL BLACK MARKS. COLOR AND BLEND AREA.
LABOR .10



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Labor			
Job #	Description	Hours	Total
8	CLEAN OFF MARKS	0.05	8.75
Subtotal for Job #8:			8.75

Job #9 - Warranty

COMPLAINT: BEDROOM DOOR IS ROUGH ALL THE WAY DOWN THE SIDE AND DENTED IN ONE AREA ON THE SIDE. THIS DOOR ALSO HAS SEVERAL SCRATCHES. DOOR FACING STILE IS CHIPPED AS WELL.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE BEDROOM DOOR AND STILE THAT IS CHIPPED.
LABOR 1.2

Labor			
Job #	Description	Hours	Total
9	TOUCH UP AREA	0.10	17.50
Subtotal for Job #9:			17.50

Job #10 - Warranty

COMPLAINT: STILE GOING INTO THE BEDROOM CLOSET HAS TWO SPOTS THAT NEED TO BE BLENDED.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR AND BLEND THE AREA.
LABOR .10

Labor			
Job #	Description	Hours	Total
10	FILL COLOR AND BLEND	0.10	17.50
Subtotal for Job #10:			17.50

Job #11 - Warranty

COMPLAINT: BEDROOM DRAWER IS CHIPPED.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR AND CLEAN THE CHIPPED AREA.
LABOR .10

Labor			
Job #	Description	Hours	Total
11	FILL COLOR AND CLEAN	0.05	8.75
Subtotal for Job #11:			8.75

Job #12 - Warranty

COMPLAINT: LINO FLOORING HAS FOUR DIFFERENT HOLES AND A SMALL TEAR NEAR THE ENTRY DOOR. THESE HOLES ARE TO THE LEFT AND THE RIGHT.

CAUSE: NOTED ON DAF

CORRECTION: DAMAGED LINO NEEDS TO BE REMOVED AND REPLACED WITH NEW.
LABOR 6.0

Labor			
Job #	Description	Hours	Total
12	REPAIR LINO	1.00	175.00



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #12: 175.00

W/O: 25291

Parts Total:	0.00
Labour Total:	385.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	385.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 07 May 2025

Customer Work Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

