



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25299



WO #: 25299 (Appointment Date: 17 APR 2025 - Time: 04:00pm)

Customer: 92336 - LIVESAY, JOHN
Address: 580 OLD HICKORY DR
MOUNT CARMEL, TN
37645

Home Phone: (423) 361-1131

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10885

Stock Desc: 2024 FW FOREST RIVER CEDAR
CREEK 3525LF

Model: 3525LF

Serial #: 4X4FCRL25RS233063

Chassis #:

Mileage:

Key #: 10100

Req'n #:

License #:

Trim:

Purchase Date: 04 DEC 24

Date In: 17 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 04 DEC 24

Job #1 - External

DEWIN

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

WASH UNIT

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: TRIM IN MASTER BEDROOM CLOSET IS COMING DOWN ON LEFT SIDE AT THE TOP

CAUSE: TRIM CAME LOOSE AND FALLING DOWN

CORRECTION: RESECURE TRIM BACK IN PLACE
LABOR .10

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: MASTER BEDROOM CLOSET DOOR IS POPPING WHEN CUSTOMER TRIES TO
OPEN/CLOSE

DURING WALK THROUGH WITH CUST COULD NOT GET DOORS TO POP

CORRECTION: TECH COULD NOT DUPLICATE PROBLEM.

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: UP THE STEPS TO THE BEDROOM ON THE LEFT NEAR FLOOR SEAM TAPE IS
COMING LOOSE

CAUSE: SEAM TAPE CAME LOOSE

CORRECTION: RESECURE WITH ADHISIVE BACK INTO PLACE
LABOR .20

Customer #: 92336
LIVESAY, JOHN



Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: WIRE HANGING UNDER THE REAR SLIDE OUT CUSTOMER WOULD LIKE TO HAVE THIS RESECURED

CAUSE: SCREW WAS NOT INSTALLED INTO THE ZIP TIE THAT HOLDS THE WIRES IN PLACE.

CORRECTION: NEED TO REMOVE THE FASCIA AND SECURE ALL WIRES IN PLACE CORRECTLY, REINSTALL FASCIA.

LABOR 1.0

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: PIN WILL NOT GO ALL THE WAY THROUGH THE HAND RAIL AT THE ENTRY DOOR

CAUSE: HAND RAIL IS WARPED NOT ALLOWING THE PIN TO BE INSERTED AS DESIGNED

CORRECTION: REPLACE THE HAND RAIL

LABOR 1.0

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: BEDROOM DRAWER ON RIGHT SIDE WILL NOT CLOSE CORRECTLY AND LOOSE

CAUSE: DRAWER GUIDE IS FAULTY AND NOT ALLOWING THE DRAWER TO CLOSE ALL THE WAY. DRAWER GUIDE SEEMS TO BE INSTALLED SIDEWAYS DUE TO THE DRAWER WHEN TECH CLOSED IT HAS A GAP ON ONE SIDE.

CORRECTION: REMOVE AND REPLACE THE DRAWER GUIDES

LABOR .20

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: PLACE OVER THE BED ON THE RIGHT SIDE AT THE TOP, LOOKS LIKE THE WALL COMES OUT MORE THAN IT SHOULD. BLUE TAPE MARKS THE AREA.

CAUSE: WHEN BUILT THE WALL WAS NOT EVEN WITH THE OTHER PIECE OF WOOD BESIDE OF IT. THIS IS CAUSING THE SEAM TAPE TO POP OFF AND MAKES THIS PART OF WALL STICK OUT.

CORRECTION: R&R CEILING TRIM, PULL OVERLAY OF PAPER OFF TO BE ABLE TO SAND THE WALL TO BE EVEN WITH THE OTHER SIDE. THEN APPLY NEW OVERLAY PAPER AND SEAM TAPE. AREA WILL NEED TO BE CLEANED FROM THE WOOD WORK.

LABOR 3.0

Subtotal for Job #9: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00



Customer #: 92336
LIVESAY, JOHN



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 23 Apr 2025

Customer Signature : _____

W/O : 25299

Customer Work
Order



Customer #: 92336
LIVESAY, JOHN

