



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25342
Promised Date:
26 APR 25



WO #: 25342 (Appointment Date: 28 APR 2025 - Time: 09:00am)

Customer: 90088 - JACKSON, DUSTIN
Address: 6926 SIMS RD
HARRISON, TN
37341

Home Phone: (423) 582-7113

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10799

Stock Desc: 2023 TT KZ-RV CONNECT 282FKK

Model: 282FKK

Serial #: 4EZTL2920P7050675

Chassis #:

Mileage:0

Key #: 2500

Req'n #:

License #:

Trim:

Purchase Date: 24 JUN 23

Date In: 26 APR 25

Promise Date: 26 APR 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 24 JUN 23

Job #1 - Warranty

COMPLAINT: cs that the electric side of the water heater is inop

CAUSE: TESTED AND FOUND OPEN LOOP ON HEATING ELEMENT

CORRECTION: REMOVE AND REPLACE THE HEATING ELEMENT THEN TEST.

LABOR .40

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CS THAT THE MOLDING BY THE ENTRY DOOR HAS COME LOOSE LEFT HAND SIDE WHEN WALKING IN

CAUSE: IMPROPER INSTALLATION, TRIM IS TO LONG.

CORRECTION: REMOVE TRIM, CUT TO FIT AND RESECURE IN PLACE.

LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

CS THAT THE SHOWER DOOR HAS COME LOOSE CHECK AND ADVISE BOTTOM TRACK

Subtotal for Job #3: 0.00

Job #4 - Warranty

CS WE ORDERED A CABINET FOR THIS UNIT FROM AN OLD WO CABINET DOOR IS BY THE BATHROOM

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CS THAT THE FAUCET IN THE KITCHEN IS LEAKING AT THE BASE

CAUSE: WATER IS COMING FROM THE BASE OF THE FAUCET, INTERNAL FAILURE.

CORRECTION: REMOVE, REPLACE AND TEST FAUCET.

LABOR .50

Customer #: 90088
JACKSON, DUSTIN



W/O: 25342
Promised Date: 26 APR 25



Customer #: 90088
JACKSON, DUSTIN



Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
Subtotal for Job #5:				0.00

Job #6 - Warranty

COMPLAINT: CS THAT THE SHADE OVER THE DINETTE LOWER BOTTOM CORNER HAS COME LOOSE

CAUSE: SCREW PULLED AWAY FROM WALL.

CORRECTION: FILL HOLE, OVERLAY AND MOVE SCREW TO CORRECT PLACE TO HOLD THE SHADE IN PLACE.
LABOR .30

Subtotal for Job #6: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #7 - External

CHECK SLIDE SEALS

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: CS THAT THE LED DOCKING LIGHT ON THE JACK WILL NOT WORK.

CAUSE: TECH DETERMINED LIGHT IS GETTING POWER BUT WILL NOT WORK.

CORRECTION: REMOVE, REPLACE JACK AND TEST.
LABOR 1.0

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: CS THAT THE RIGHT REAR TAIL LIGHT IS GETTING A FAULT IN THE TRUCK WHEN PLUGGED IN

CAUSE: TECH DETERMINED THE LIGHT IS FAULTY AND NOT WORKING.

CORRECTION: REPLACE THE REAR TAIL LIGHT.
LABOR .30

Subtotal for Job #9: 0.00

Job #WASH - External

WASH UNIT



W/O: 25342
Promised Date: 26 APR 25



Customer #: 90088
JACKSON, DUSTIN



Subtotal for Job #WASH: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 07 May 2025

Customer Work
Order

