

# DAF: Dealer Unit Inspection Form



**FOREST RIVER**

Forest River, Inc.  
66135 SR 13  
Millersburg, IN 46543  
USA

Short VIN/Unit: RL1908844  
Model/Item: RLT8263MBR  
Dealer: TRI AM RV CENTER OF

1. Forest River allows for a secondary inspection, which must take place within **3 business days** from the **delivery date** for warranty consideration.
2. Dealer Unit Inspection Form is to document substantial damage and shortages, not to note minor defects in material or workmanship.
3. If the Dealer is unable to perform this inspection within **3 business days**, the appropriate Warranty Department must be notified via email or phone.
4. The form must be signed and attached to the VIN on Dealer Connect **within 24 hours after the secondary inspection**.
5. Warranty claims must be submitted and resolved no later than **6 months from delivery** for coverage and payment.

Circle Yes or No if item was received, and if applicable:

Keys	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
BBQ Grill	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Power Cord	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Warranty Packet	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Sink cover	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Jack Handles	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
TV 1	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
TV 2	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Remotes	Yes	No

List Any Miscellaneous Comments Regarding Condition of Unit:

① Shower surround on (R) side is not correct.  
 ② Bathroom door top balance fore & needs cleaned  
 ③ Fascia on (L) side living slide is crooked & sticking on one side.  
 ④ Corner trim @ bar in kitchen damaged

List Any Additional Missing Items:

Suggested areas to inspect:	
Unit Cleanliness	If no, explain:
Condition of Flooring	
Cabinetry Damage	If yes, explain: <span style="color: blue;">Bedroom door (cabinet) loose @ bottom (hole stripped where screw goes for hinge.</span>
Appliance Condition	
Furniture Tears/Stains	If yes, explain:
Frame/Chassis Condition	
Roof Components	
Roof Material	
Awning Fabric	
ODS/DS Walls & Graphics	
Unit Front & Graphics	
Unit Rear & Graphics	
Additional Notations	

Unit/Underside has been washed by the Dealership       Yes       No      Date Washed \_\_\_\_\_

Dealer Signature \_\_\_\_\_ Date \_\_\_\_\_