



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25508



WO #: 25508 (Appointment Date: 27 MAY 2025 - Time: 09:00am)

Customer: 59072 - EXTREME AUTOMOTIVE,
 KYKERS
 Address: 1201 TUSCULUM BLVD
 GREENEVILLE, TN
 37745

Home Phone: 423-525-5147

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10911
 Stock Desc: 2024 FW FOREST RIVER CEDAR
 CREEK 391WOW
 Model: 391WOW
 Serial #: 4X4FCRR27RS233105
 Chassis #:
 Mileage:
 Key #: 13200
 Req'n #:
 License #:
 Trim:

Purchase Date: 28 DEC 24
 Date In: 27 MAY 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 06 AUG 25
 Warr. Date: 28 DEC 24

Job #1 - Warranty

COMPLAINT: AC IS BUZZING AFTER RUNS A WHILE FRONT AND REAR. THIS JOB IS FOR THE BEDROOM A/C. THIS IS AFTER FREEZE SENSORS WERE INSTALLED.

CAUSE: INSULATION FLAPPING ON A/C AND ONLY HAD ONE MOUNTING SCREW HOLDING A/C CONTROL BOARD.

CORRECTION: RESECURED INSULATION IN PLACE AND ADDED TWO MOUNTING SCREWS.
 LABOR .30

Labor

Job #	Description	Hours	Total
1	RESECURE INSULATION	0.50	82.50

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	5.00	5.00
SHP	SHIPPING/FREIGHT FEE	1.00	5.00	5.00

Subtotal for Job #1: 92.50

Job #2 - Warranty

COMPLAINT: CABINET DOOR IS NOT CLOSING AND IS SPLIT

CAUSE: DOOR IS SPLIT AND BOWED TO WHERE IT WILL NOT CLOSE AS DESIGNED.

CORRECTION: REPLACE DOOR AND THIS WILL NEED TO BE PRECUT FOR HARDWARE.
 LABOR .30

Labor

Job #	Description	Hours	Total
2	REPLACE DOOR AND PRECUT HARDWARE	0.40	66.00

Parts

Part #	Description	Qty	Price	Total
F100417535	DOOR, CABINET, POPLAR, FPS, 7 1/2" X 38", SEAFOAM WHITE, 2 1/4" RAIL, SINGLE PANEL	1.00	35.93	35.93

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	170.40	170.40

Customer #: 59072
 EXTREME AUTOMOTIVE,
 KYKERS



Subtotal for Job #2: 272.33

W/O: 25508

Job #3 - Warranty

COMPLAINT: CLOSET DOOR IS DRAGGING

CAUSE: CLOSET DOOR HANGERS RUBBING ON CEILING MOUNTED TRACK. TECH ATTEMPTED TO ADJUST AND NO CHANGE IN CONCERN.

CORRECTION: REPLACE TRACK,HANGERS AND ROLLERS.
LABOR .30

Labor

Job #	Description	Hours	Total
3	REPLACE TRACK HANGERS AND ROLLERS	0.50	82.50

Parts

Part #	Description	Qty	Price	Total
F100151626	TRACK, 96", PASSAGE/POCKET DOOR, WHITE	1.00	11.41	11.41
30I92148A	DOOR GUIDE CLOSET DOOR ROLLER	1.00	2.64	2.64

Subtotal for Job #3: 96.55

Job #4 - Warranty

OFF DOOR SIDE REAR WHEEL IS HOT AFTER 1 HOUR DRIVE DOOR SIDE REAR IS COLD CHECK AND ADVISE

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: TRIM COMING LOOSE ACROSS FROM ENTRANCE DOOR

CAUSE: TRIM CAME LOOSE AND NOT IN PLACE CORRECT.

CORRECTION: RESECURE TRIM IN PLACE
LABOR .10

Labor

Job #	Description	Hours	Total
5	RESECURED IN PLACE	0.10	17.50

Subtotal for Job #5: 17.50

Job #6 - Warranty

COMPLAINT: TRIM LOOSE ON RIGHT FACIA BED SLIDE

CAUSE: TRIM WORKED LOOSE AND NOT IN PLACE.

CORRECTION: RESECURE TRIM TO FASCIA
LABOR .10

Labor

Job #	Description	Hours	Total
6	RESECURED FASCIA	0.10	16.50

Subtotal for Job #6: 16.50

Job #7 - Warranty

COMPLAINT: TRIM MISSING ON BATH DOOR ENTRANCE, BOTTOM RIGHT

CAUSE: TRIM IS MISSING 1" BATTON STRIP AT THE BATHROOM DOOR ENTRANCE.

CORRECTION: INSTALL 1" BATTON STRIP

Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS



LABOR 1.0

Job #	Description	Hours	Total
7	REPLACED TRIM	0.10	16.50

Part #	Description	Qty	Price	Total
F100162414	BATTEN, 7/8" X 9' FLAT, WEBBING HORIZON	1.00	2.60	2.60

Subtotal for Job #7: 19.10

Job #8 - Warranty

COMPLAINT: LP WIRES HANGING BELOW THE ALARM IN REAR OF UNIT

CAUSE: WIRING WAS NOT SECURE IN PLACE AND CAME LOOSE.

CORRECTION: RESECURED WIRING IN CORRECT PLACE.

LABOR .30

Job #	Description	Hours	Total
8	RESECURED WIRING	0.30	49.50

Subtotal for Job #8: 49.50

Job #9 - Warranty

COMPLAINT: DOOR SIDE COMPARTMENT SLAM LOCK CYLINDER IS MISSING ITS FACE

CAUSE: SLAM LOCK CYLINDER FACE MISSING

CORRECTION: REPLACE TUMBLER ON COMPARTMENT DOOR

LABOR .20

Job #	Description	Hours	Total
9	REPLACED TUMBLER	0.20	33.00

Part #	Description	Qty	Price	Total
20X70384A	LOCK COMPARTMENT DOOR	1.00	81.90	81.90

Subtotal for Job #9: 114.90

Job #10 - Warranty

COMPLAINT: FRONT AND REAR AC COMPRESSOR KICKS ON FOR ABOUT 30 SECS AND SHUTS OFF

CAUSE: TECH WENT ON SC AND FOUND THAT NEITHER AC HAD A FREEZE SENSOR INSTALLED

CORRECTION: TECH INSTALLED FREEZE SENSORS ON BOTH A/C'S THAT WE HAD IN STOCK TO ALLOW CUST TO GO ON TRIP.

LABOR 1.0 (LABOR FOR 2 A/C'S)

Job #	Description	Hours	Total
10	RESECURED FREEZE SENSORS IN PLACE	1.00	165.00

Part #	Description	Qty	Price	Total
F100385345	A/C PART - SOP: FREEZER COIL SENSOR, COLEMAN MACH A/C - V# 9530-3231 [AD46]	2.00	19.46	38.92

W/O: 25508



Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS



Subtotal for Job #10: 203.92

Job #11 - Warranty

COMPLAINT: AC IS BUZZING AFTER RUNS A WHILE, THIS IS FOR THE LIVING ROOM A/C. THIS WAS AFTER THE FREEZE SENSOR WAS INSTALLED.

CAUSE: INSULATION FLAPPING AND ONLY HAD ONE MOUNTING SCREW HOLDING A/C CONTROL BOARD.

CORRECTION: RESECURED INSULATION IN PLACE AND ADDED TWO MOUNTING SCREWS. LABOR .30

Labor

Job #	Description	Hours	Total
11	MISC. LABOR CODE	0.50	87.50

Subtotal for Job #11: 87.50

Job #12 - Warranty

COMPLAINT: WALL TRIM LOOSE BELOW SHELF ACROSS FROM ENTRY DOOR

CAUSE: TRIM CAME LOOSE

CORRECTION: RESECURE TRIM IN CORRECT PLACE. LABOR .10

Labor

Job #	Description	Hours	Total
12	RESECURED TRIM IN PLACE	0.10	16.50

Subtotal for Job #12: 16.50

Job #13 - Warranty

COMPLAINT: PANTRY DOOR IS SPLITTING AND BOWED.

CAUSE: PANTRY DOOR IS SPLIT AND WOOD IS BOWING OUT.

CORRECTION: REPLACE THE PANTRY DOOR LABOR .30

Labor

Job #	Description	Hours	Total
13	REPLACED PANTRY DOOR	0.50	82.50

Parts

Part #	Description	Qty	Price	Total
F100452267	DOOR, CABINET, POPLAR, CF3PS, 12 1/2" X 73", THREE PANEL CURIO, SEAFOAM WHITE, 2 1/4" RAIL	1.00	103.45	103.45

Subtotal for Job #13: 185.95

Parts Total: 276.85
Labour Total: 715.50
Sublet Total: 0.00
Extras Total: 180.40
WORK ORDER TOTAL: 1,172.75

W/O: 25508



Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 06 Aug 2025

W/O : 25508

Customer Work
Order



Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS

