



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25714



WO #: 25714

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11139

Stock Desc: 2026 THFW FOREST RIVER ROGUE  
 351G2

Model: 351G2

Serial #: 4X4FVGL2XT5403602

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 03 JUL 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 19 AUG 25

Warr. Date:

**Job #1 - Warranty**

COMPLAINT: MISSING SINK COVER

CAUSE: NOTED ON DAF

CORRECTION: REPLACE SINK COVER

LABOR .10

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: KITCHEN CABINET RUBS WHEN OPENING/CLOSING DOOR

CAUSE: NOTED ON DAF

CORRECTION: ADJUST CABINET DOOR AND COLOR BLEND IF NEEDED WHERE DOOR HAS  
 RUBBED

LABOR .20

**Labor**

Job #	Description	Hours	Total
2	ADJUSTED CAB DOOR	0.10	16.50

**Subtotal for Job #2: 16.50**

**Job #3 - Warranty**

COMPLAINT: PAINT ON BATHROOM DOOR EDGE HAS RUBBED OFF

CAUSE: NOTED ON DAF

CORRECTION: COLOR,FILL AND BLEND

LABOR .20

**Labor**

Job #	Description	Hours	Total
3	COLOR AND BLEND	0.20	33.00

**Subtotal for Job #3: 33.00**

**Job #4 - Warranty**

COMPLAINT: TOP ON THE BEDOOM DRESSER WILL NOT LOCK IN PLACE AND HAS SCRATCHES

Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,



CAUSE: NOTED ON DAF

CORRECTION: REPLACE TOP OF DRESSER  
LABOR .30

**Labor**

Job #	Description	Hours	Total
4	REPLACED DRESSER TOP	0.40	66.00

**Parts**

Part #	Description	Qty	Price	Total
F100622927	COUNTERTOP 60.5X17.5 BRAEMAR ESPRESSO	1.00	169.26	169.26

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	118.31	118.31

**Subtotal for Job #4: 353.57**

**Job #5 - Warranty**

COMPLAINT: CEILING TRIM IN BEDROOM IS FALLING DOWN IN TWO PLACES

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BOTH TRIM PIECES IN CORRECT PLACE  
LABOR .30

**Labor**

Job #	Description	Hours	Total
5	SECURED TRIM	0.05	8.25

**Subtotal for Job #5: 8.25**

**Job #6 - Warranty**

COMPLAINT: BEDROOM DOOR IS SCRATCHED AND OUT OF TRACK

CAUSE: DOOR IS NOT IN THR TRACK CORRECTLY SO THIS HAS CAUSED DAMAGED TO THE DOOR  
NOTED ON DAF

CORRECTION: REMOVE DOOR TO ADJUST ON TRACK CORRECT, COLOR AND BLEND THE DAMAGED AREAS OF THE DOOR  
LABOR .50

**Labor**

Job #	Description	Hours	Total
6	FILLED COLORED AND BLEND	0.20	33.00

**Subtotal for Job #6: 33.00**

**Job #7 - Warranty**

COMPLAINT: SLIDE OUT WALL AT THE COUCH HAS A SMALL HOLE

CAUSE: NOTED ON DAF

CORRECTION: FILL HOLE, SAND AND COLOR BLEND AREA  
LABOR .30

**Labor**

Job #	Description	Hours	Total
7	FILLED	0.20	33.00

W/O: 25714



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



Subtotal for Job #7: 33.00

**Job #8 - Warranty**

COMPLAINT: BROKE TRIM ON LOWER WALL AT THE FIREPLACE

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE TRIM  
LABOR .30

**Labor**

Job #	Description	Hours	Total
8	REPLACED TRIM	0.20	33.00

**Parts**

Part #	Description	Qty	Price	Total
F100606831	BATTON 7/8" SEA PINE MOONSHINE	1.00	15.54	15.54

Subtotal for Job #8: 48.54

**Job #9 - Warranty**

COMPLAINT: KITCHEN BAR IS SCRATCHED TO THE RIGHT OF THE SINK

CAUSE: NOTED ON DAF

CORRECTION: BUFF COUNTER TOP  
LABOR 1.0

**Labor**

Job #	Description	Hours	Total
9	BUFFED COUNTER TOPS	1.00	165.00

Subtotal for Job #9: 165.00

**Job #10 - Warranty**

COMPLAINT: FRONT OF THE MICROWAVE IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: POLISH AND BUFF SCRATCHES  
LABOR .50

**Labor**

Job #	Description	Hours	Total
10	BUFFED	0.10	16.50

Subtotal for Job #10: 16.50

**Job #11 - Warranty**

COMPLAINT: HOLE IN WALL UNDER KITCHEN CABINETS

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREA  
LABOR .20

**Labor**

Job #	Description	Hours	Total
11	COLOR AND FILLED	0.20	33.00

W/O: 25714



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



Subtotal for Job #11: 33.00

**Job #12 - Warranty**

COMPLAINT: DRAWER UNDER STOVE WILL NOT CLOSE

CAUSE: NOTED ON DAF  
DRAWER GUIDE IS UNEVENLY INSTALLED

CORRECTION: REMOVE AND REINSTALL DRAWER CORRECTLY  
LABOR .50

**Labor**

Job #	Description	Hours	Total
12	REMOVE AND REINSTALLQ	0.20	33.00

Subtotal for Job #12: 33.00

**Job #13 - Warranty**

COMPLAINT: THE NUMBERS ON THE FRIDGE DOOR ARE VERY DIM, PHOTO WILL NOT EVEN PICK THEM UP.

CAUSE: NUMBERS WILL NOT LIGHT UP AS THEY SHOULD ON THE FRIDGE DOOR

CORRECTION: REPLACE FRIDGE DOOR  
LABOR 1.0

CLAIM DENIED BY FOREST RIVER

Subtotal for Job #13: 0.00

**Job #14 - Warranty**

COMPLAINT: PAINT IS FADED ON THE WINE RACK ABOVE THE FRIDGE

CAUSE: NOTED ON DAF

CORRECTION: WINE RACK WILL NEED TO BE TAKEN DOWN, REPAINTED AND REINSTALLED'  
LABOR .30

**Labor**

Job #	Description	Hours	Total
14	REMOVED AND REPAINTED	0.20	33.00

**Parts**

Part #	Description	Qty	Price	Total
DAL1608	PREMIUM LACQUER; SEMI-GLOSS BLACK; 12 OZ. AEROSOL	1.00	9.96	9.96

Subtotal for Job #14: 42.96

**Job #15 - Warranty**

COMPLAINT: REAR RAMP DOOR HAS DAYLIGHT COMING IN AROUND BOTH TOP CORNERS

CAUSE: NOTED ON DAF THE SEAL ON REAR DOOR NOT IN CORRECT PLACE

CORRECTION: REPLACE REAR DOOR SEAL  
LABOR 1.5

**Labor**

Job #	Description	Hours	Total
15	REPLACE DOOR SEAL	1.00	165.00

**Parts**

W/O: 25714



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



Part #	Description	Qty	Price	Total
F100694808	SEAL, 5/8" X 25FT SLIDE OUT LG BULB "D" SEAL SELF ADHESIVE - BLACK	1.00	40.76	40.76

**Subtotal for Job #15: 205.76**

**Job #16 - Warranty**

COMPLAINT: MIDDLE BUTTON ON CURTAIN IN THE PATIO AREA IS MISSING THE LATCH ON THE WALL, CURTAIN HAS NO WHERE TO BUTTON IN THE MIDDLE

CAUSE: NOTED ON DAF

CORRECTION: INSTALL BUTTON SNAP LATCH ON WALL FOR CURTAIN  
LABOR .20

<b>Labor</b>			
Job #	Description	Hours	Total
16	REPAIRED	0.10	16.50
<b>Subtotal for Job #16:</b>			<b>16.50</b>

**Job #17 - Warranty**

COMPLAINT: REAR BATHROOM DOOR HAS A SCRATCH

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA  
LABOR .20

<b>Labor</b>			
Job #	Description	Hours	Total
17	FILL AND BLEND	0.20	33.00
<b>Subtotal for Job #17:</b>			<b>33.00</b>

**Job #18 - Warranty**

COMPLAINT: WASHER DRYER HOOK UP IS WARPED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE WASHER DRYER HOOK UP BOX  
LABOR .50

<b>Labor</b>			
Job #	Description	Hours	Total
18	REPLACED EASHER DRYER BOX	0.50	82.50

<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100082514	WASHER BOX BLACK	1.00	4.62	4.62

<b>Other Services</b>				
Code	Description	Qty	Price	Total
SHP	SHIPPING ON SALES ORDER S5108427	1.00	5.00	5.00
SHP	SHIPPING ON SALES ORDER S5108427	1.00	129.91	129.91

**Subtotal for Job #18: 222.03**



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



W/O: 25714

Parts Total:	240.14
Labour Total:	800.25
Sublet Total:	0.00
Extras Total:	253.22
<b>WORK ORDER TOTAL:</b>	<b>1,293.61</b>

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 19 Aug 2025

Customer Signature : \_\_\_\_\_

Customer Work Order



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

