



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25714



WO #: 25714

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11139

Stock Desc: 2026 THFW FOREST RIVER ROGUE
351G2

Model: 351G2

Serial #: 4X4FVGL2XT5403602

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 03 JUL 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: MISSING SINK COVER

CAUSE: NOTED ON DAF

CORRECTION: REPLACE SINK COVER
LABOR .10

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: KITCHEN CABINET RUBS WHEN OPENING/CLOSING DOOR

CAUSE: NOTED ON DAF

CORRECTION: ADJUST CABINET DOOR AND COLOR BLEND IF NEEDED WHERE DOOR HAS
RUBBED
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: PAINT ON BATHROOM DOOR EDGE HAS RUBBED OFF

CAUSE: NOTED ON DAF

CORRECTION: COLOR, FILL AND BLEND
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: TOP ON THE BEDROOM DRESSER WILL NOT LOCK IN PLACE AND HAS SCRATCHES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE TOP OF DRESSER
LABOR .30

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CEILING TRIM IN BEDROOM IS FALLING DOWN IN TWO PLACES

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BOTH TRIM PIECES IN CORRECT PLACE
LABOR .30

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: BEDROOM DOOR IS SCRATCHED AND OUT OF TRACK

CAUSE: DOOR IS NOT IN THR TRACK CORRECTLY SO THIS HAS CAUSED DAMAGED TO THE DOOR
NOTED ON DAF

CORRECTION: REMOVE DOOR TO ADJUST ON TRACK CORRECT, COLOR AND BLEND THE DAMAGED AREAS OF THE DOOR
LABOR .50

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: SLIDE OUT WALL AT THE COUCH HAS A SMALL HOLE

CAUSE: NOTED ON DAF

CORRECTION: FILL HOLE, SAND AND COLOR BLEND AREA
LABOR .30

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: BROKE TRIM ON LOWER WALL AT THE FIREPLACE

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE TRIM
LABOR .30

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: KITCHEN BAR IS SCRATCHED TO THE RIGHT OF THE SINK

CAUSE: NOTED ON DAF

CORRECTION: BUFF COUNTER TOP
LABOR 1.0

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: FRONT OF THE MICROWAVE IS SCRATCHED

CAUSE: NOTED ON DAF



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CORRECTION: POLISH AND BUFF SCRATCHES
LABOR .50

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: HOLE IN WALL UNDER KITCHEN CABINETS

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREA

LABOR .20

Subtotal for Job #11: 0.00

Job #12 - Warranty

COMPLAINT: DRAWER UNDER STOVE WILL NOT CLOSE

CAUSE: NOTED ON DAF

DRAWER GUIDE IS UNEVENLY INSTALLED

CORRECTION: REMOVE AND REINSTALL DRAWER CORRECTLY

LABOR .50

Subtotal for Job #12: 0.00

Job #13 - Warranty

COMPLAINT: THE NUMBERS ON THE FRIDGE DOOR ARE VERY DIM, PHOTO WILL NOT EVEN PICK THEM UP.

CAUSE: NUMBERS WILL NOT LIGHT UP AS THEY SHOULD ON THE FRIDGE DOOR

CORRECTION: REPLACE FRIDGE DOOR

LABOR 1.0

Subtotal for Job #13: 0.00

Job #14 - Warranty

COMPLAINT: PAINT IS FADED ON THE WINE RACK ABOVE THE FRIDGE

CAUSE: NOTED ON DAF

CORRECTION: WINE RACK WILL NEED TO BE TAKEN DOWN, REPAINTED AND REINSTALLED'

LABOR .30

Subtotal for Job #14: 0.00

Job #15 - Warranty

COMPLAINT: REAR RAMP DOOR HAS DAYLIGHT COMING IN AROUND BOTH TOP CORNERS

CAUSE: NOTED ON DAF THE SEAL ON REAR DOOR NOT IN CORRECT PLACE

CORRECTION: REPLACE REAR DOOR SEAL

LABOR 1.5

Subtotal for Job #15: 0.00

Job #16 - Warranty

COMPLAINT: MIDDLE BUTTON ON CURTAIN IN THE PATIO AREA IS MISSING THE LATCH ON THE WALL, CURTAIN HAS NO WHERE TO BUTTON IN THE MIDDLE

W/O: 25714



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CAUSE: NOTED ON DAF

CORRECTION: INSTALL BUTTON SNAP LATCH ON WALL FOR CURTAIN
LABOR .20

Subtotal for Job #16: 0.00

Job #17 - Warranty

COMPLAINT: REAR BATHROOM DOOR HAS A SCRATCH

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #17: 0.00

Job #18 - Warranty

COMPLAINT: WASHER DRYER HOOK UP IS WARPPED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE WASHER DRYER HOOK UP BOX
LABOR .50

Subtotal for Job #18: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 03 Jul 2025

Customer Signature : _____

