



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25735
Promised Date:



Customer #: 92336
LIVESAY, JOHN



WO #: 25735 (Appointment Date: 09 JUL 2025 - Time: 09:00am)

Customer: 92336 - LIVESAY, JOHN
Address: 580 OLD HICKORY DR
MOUNT CARMEL, TN
37645

Home Phone: (423) 361-1131

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10885

Stock Desc: (10885) 2024 FOREST RIVER CEDAR

CREEK 3525LF

Model: 3525LF

Serial #: 4X4FCRL25RS233063

Chassis #:

Mileage:0

Key #: 10100

Req'n #:

License #:

Trim:

Purchase Date: 04 DEC 24

Date In: 09 JUL 25

Promise Date: 30 JUL 25

Promise Time: 09:00am

Schedule Date:

Completed: 31 OCT 25

Warr. Date: 04 DEC 24

Job #1 - External

CS THAT THE CAPS ON THE AXLES KEEP POPPING OFF ON WO#25679

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CS THAT THE TRIM IN THE LIVING ROOM SLIDE HAS TRIM COMING LOOSE

CAUSE: THE RIGHT SIDE OF THE SLIDE FASCIA CAME LOOSE.

CORRECTION: RESECURE FASCIA IN CORRECT PLACE
LABOR .20

Labor

Job #	Description	Hours	Total
2	RESECURED FASCIA	0.30	52.50

Subtotal for Job #2: 52.50

Job #3 - Warranty

COMPLAINT: CS THAT THE MAIN ENTRY DOOR LOCK HAS FAILED AND WILL NOT UNLOCK TO BE ABLE TO OPEN DOOR

CAUSE: MAIN ENTRY DOOR LOCK ASSEMBLY HAS BROKEN.

CORRECTION: REPLACE ENTRY DOOR LOCK ASSEMBLY
LABOR .30

Labor

Job #	Description	Hours	Total
3	REPLACED LOCK	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
20X50296A	LOCK, ENTRY DOOR HANDLE, W/ KEY, GLOBAL, BLACK	1.00	87.28	87.28
79233	BUTYL TAPE 1/8X3/4	1.00	9.67	9.67
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	12.38	12.38



Subtotal for Job #3: 161.83

Job #4 - Warranty

COMPLAINT: CS THAT THE SECOND ENTRY DOOR IS HITTING AND DRAGGING WHEN OPENING

CAUSE: DOOR LOCK IS RUBBING ON STRIKER PLATE DUE TO LOCK ASSEMBLY SLIDING FORWARD. TECH DID ATTEMPT TO REALIGN AND TIGHTEN LOCK ASSEMBLY, NO CHANGE IN LOCK.

CORRECTION: REPLACE DOOR ENTRY LOCK ASSEMBLY

LABOR .30

REQUESTING TIME FOR THE TECH ATTEMPTING TO REPAIR LOCK ASSEMBLY

LABOR .30

Labor

Job #	Description	Hours	Total
4	REPLACED DOOR AND LOCK ASSEMBLY	1.90	313.50

Parts

Part #	Description	Qty	Price	Total
F100381213	DECAL#20 RH/DS	1.00	3.43	3.43
F100381099	DECAL RH/DS	1.00	6.57	6.57
F100433828	DECAL #33 RH/DS	1.00	8.80	8.80
F100229883	DOOR, ENTRY, 32" X 72", RIGHT HINGE W/ SCREEN DOOR, TALON GREY W/ BLACK TRIM, V#2021134715 *COMES WITH SCREW COVER & DRIP RAIL*	1.00	650.10	650.10

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	18.64	18.64
SHP	SHIPPING/FREIGHT FEE	1.00	147.41	147.41
CRA	CRATE CHARGES	1.00	65.00	65.00

Subtotal for Job #4: 1,213.45

Job #5 - Warranty

COMPLAINT: CS THAT THE SHOCK THAT HOLDS THE PANTRY DOOR OPEN HAS POPPED OFF ITS BRACKET

CAUSE: SHOCK FAILED AND BROKE

CORRECTION: REPLACE SHOCK ON PANTRY DOOR

LABOR .30

Labor

Job #	Description	Hours	Total
5	REPLACED SHOCK	0.30	49.50

Parts

Part #	Description	Qty	Price	Total
20X51854A	CABINET SHOCK 20"	1.00	5.85	5.85

Subtotal for Job #5: 55.35

Job #6 - Warranty

CS THAT THE LAST TIME A TECH WORKED ON THERE UNIT THEY NOTICED A SCREEN MISSING FROM THE WINDOW (ASK LOCATION OF WINDOW)

W/O: 25735
Promised Date: 30 JUL 25



Customer #: 92336
LIVESAY, JOHN



W/O: 25735
Promised Date: 30 JUL 25



Customer #: 92336
LIVESAY, JOHN



Subtotal for Job #6: 0.00

Job #7 - Warranty

CS THAT THE AMS ON THW AWNING WILL NOT STAY IN THE PITCHED POSITION TO DRAIN WATER OFF AWNING

Subtotal for Job #7: 0.00

Job #8 - Warranty

CS THAT WHEN USING THE BLACK TANK FLUSH THEY CAN HERE WATER FLOWING BUT NO WATER COMES OUT OF THE TERMINATION VALVE

Subtotal for Job #8: 0.00

Parts Total: 784.08
Labour Total: 468.00
Sublet Total: 0.00
Extras Total: 231.05

WORK ORDER TOTAL: 1,483.13

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 31 Oct 2025

