



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25735
Promised Date:



Customer #: 92336
LIVESAY, JOHN



WO #: 25735 (Appointment Date: 09 JUL 2025 - Time: 09:00am)

Customer: 92336 - LIVESAY, JOHN
Address: 580 OLD HICKORY DR
MOUNT CARMEL, TN
37645

Home Phone: (423) 361-1131

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10885

Stock Desc: (10885) 2024 FOREST RIVER CEDAR

CREEK 3525LF

Model: 3525LF

Serial #: 4X4FCRL25RS233063

Chassis #:

Mileage:0

Key #: 10100

Req'n #:

License #:

Trim:

Purchase Date: 04 DEC 24

Date In: 09 JUL 25

Promise Date: 30 JUL 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 04 DEC 24

Job #1 - External

CS THAT THE CAPS ON THE AXLES KEEP POPPING OFF ON WO#25679

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CS THAT THE TRIM IN THE LIVING ROOM SLIDE HAS TRIM COMING LOOSE

CAUSE: THE RIGHT SIDE OF THE SLIDE FASCIA CAME LOOSE.

CORRECTION: RESECURE FASCIA IN CORRECT PLACE
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CS THAT THE MAIN ENTRY DOOR LOCK HAS FAILED AND WILL NOT UNLOCK TO BE ABLE TO OPEN DOOR

CAUSE: MAIN ENTRY DOOR LOCK ASSEMBLY HAS BROKEN.

CORRECTION: REPLACE ENTRY DOOR LOCK ASSEMBLY
LABOR .30

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CS THAT THE SECOND ENTRY DOOR IS HITTING AND DRAGGING WHEN OPENING

CAUSE: DOOR LOCK IS RUBBING ON STRIKER PLATE DUE TO LOCK ASSEMBLY SLIDING FORWARD. TECH DID ATTEMPT TO REALIGN AND TIGHTEN LOCK ASSEMBLY, NO CHANGE IN LOCK.

CORRECTION: REPLACE DOOR ENTRY LOCK ASSEMBLY
LABOR .30
REQUESTING TIME FOR THE TECH ATTEMPTING TO REPAIR LOCK ASSEMBLY
LABOR .30



W/O: 25735
Promised Date: 30 JUL 25



Customer #: 92336
LIVESAY, JOHN



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CS THAT THE SHOCK THAT HOLDS THE PANTRY DOOR OPEN HAS POPPED OFF ITS BRACKET

CAUSE: SHOCK FAILED AND BROKE

CORRECTION: REPLACE SHOCK ON PANTRY DOOR
LABOR .30

Subtotal for Job #5: 0.00

Job #6 - Warranty

CS THAT THE LAST TIME A TECH WORKED ON THERE UNIT THEY NOTICED A SCREEN MISSING FROM THE WINDOW (ASK LOCATION OF WINDOW)

Subtotal for Job #6: 0.00

Job #7 - Warranty

CS THAT THE AMS ON THW AWNING WILL NOT STAY IN THE PITCHED POSITION TO DRAIN WATER OFF AWNING

Subtotal for Job #7: 0.00

Job #8 - Warranty

CS THAT WHEN USING THE BLACK TANK FLUSH THEY CAN HERE WATER FLOWING BUT NO WATER COMES OUT OF THE TERMINATION VALVE

Subtotal for Job #8: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 17 Jul 2025

