

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2408653
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5NHTVGE22TC005542
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 073 / 073E
 ITEM # VGT29SUT-73E
 DEALER RO # 25957
 CLAIM START DATE 08/20/2025
 CLAIM END DATE 10/21/2025

Labor rate: \$165.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-102-24-00-001094 Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/
 Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-08-20 14:55:55 :: Complaint: Spots on wall and ceiling in the
 slide out Cause: Noted on DAF Correction: Spots need to be blended to look smooth
Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$33.00
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$33.00
Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-100-36-00-001035 Cabinet Door - Interior/Cabinetry/Touch Up/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-08-20 14:57:24 :: Complaint: Two cabinets in the kitchen have
 scratches and a chip on one Cause: Noted on DAF Correction: Fill, color, and blend the area both cabinets and
 spots
Model# **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$49.50
Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$16.50
Notes
 CHANGED TO CORRECT CODE
 CORRECT CODE CHANGED THE FLAT RATE

Labor

Line# 3 **Operation Code** **Operational Description**
 30-101-36-00-001078 Sliding, Pocket Door - Interior/Interior Doors/Touch Up/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-08-20 14:59:11 :: Complaint: The bottom of the bathroom
 door is rough and paint chipped Cause: Noted on DAF Correction: Color and blend the area
Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$33.00
Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$16.50
Notes
 CHANGED TO CORRECT CODE
 CORRECT CODE CHANGED THE FLAT RATE

Labor

Line# 4 **Operation Code** **Operational Description**
 30-100-01-00-001050 Cabinet Stiles - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-08-20 15:01:01 :: Complaint: Kitchen pantry stile is chipped
 Cause: Noted on DAF Correction: Replace stile on pantry

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$82.50
Serial# Appr Hrs 0.50 Appr Labor Amt \$82.50

Notes
thank you

Part

Line# 2 Item # Description
F100602356 SEAM TAPE, 1" X 150' - BRAEMAR ESPRESSO (150' ROLL) | BIN 101
Model # Serial # Part tag
Sub Qty 1.00 Sub Dlr Price \$25.74 Sub Freight \$18.78
Appr Qty 1.00 Appr Dlr Price \$25.74 Appr Freight \$18.78

Notes

Labor

Line# 5 Operation Code Operational Description
30-100-01-00-001050 Cabinet Stiles - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : ashlee@dealer-advisors.com, 2025-08-20 15:02:10 :: Complaint: Stile on kitchen slide is warped and sticking out more than it should Cause: Noted on DAF Correction: Replace the stile on kitchen slide

Model# Dlr Sub Hrs 1.00 Sub Labor Amt \$165.00
Serial# Appr Hrs 0.20 Appr Labor Amt \$33.00

Notes
Dealer has requested more time than what is normally approved for this repair. If you have additional information or need more time as the repair progresses, please contact me directly to discuss and I can continue to review it.

Part

Line# 1 Item # Description
F100645902 TRIM, 3/4" X 9" X 169" MDF FASCIA - BRAEMAR ESPRESSO (322104)
Model # Serial # Part tag
Sub Qty 1.00 Sub Dlr Price \$54.95 Sub Freight \$150.00
Appr Qty 1.00 Appr Dlr Price \$54.95 Appr Freight \$150.00

Notes

Labor

Line# 6 Operation Code Operational Description
30-102-24-00-004562 Gimp/Vinyl Trim - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code
Complaint, Cause, Correction
Original Note : ashlee@dealer-advisors.com, 2025-08-20 15:04:46 :: Complaint: Ceiling panel in bedroom has brown spots Cause: Noted on DAF Correction: Clean spots and then paint to match ceiling panel

Model# Dlr Sub Hrs 0.50 Sub Labor Amt \$82.50
Serial# Appr Hrs 0.50 Appr Labor Amt \$82.50

Notes
thank you

Labor

Line# 7 Operation Code Operational Description
30-102-01-00-001097 Seam Tape, per 8 ft. Strip - Interior/Panels, Ceilings, & Interior Moldings/Replace/
No Tread Code
Complaint, Cause, Correction
Original Note : ashlee@dealer-advisors.com, 2025-08-20 15:07:31 :: Complaint: Ceiling strip in bedroom is stained Cause: Noted on DAF Correction: Clean area and touch up paint if needed

Model# Dlr Sub Hrs 0.20 Sub Labor Amt \$33.00
Serial# Appr Hrs 0.10 Appr Labor Amt \$16.50

Notes
please add required photo
Pictures added, thank you!
Dealer has requested over the flat rate time for this repair, and the information and pictures provided do not explain why additional time is needed. We have reduced the time to the flat rate

time. In the future, your complaint, cause & correction needs to explain or show why additional time is being requested for a flat rate repair.

Submitted	Labor Amt	\$478.50
	Parts & Freight	\$249.47
	Total	\$727.97

Approved	Labor Amt	\$280.50
	Parts & Freight	\$249.47
	Total	\$529.97

DEALER _____ **DATE**

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE**

SIGNATURE

All repairs described have been inspected and are satisfactory.