



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26071



WO #: 26071

Customer: 59072 - EXTREME AUTOMOTIVE,
KYKERS
Address: 1201 TUSCULUM BLVD
GREENEVILLE, TN
37745
Home Phone: 423-525-5147
Work Phone:
Author: SPD
Location: IH
Invoice #: 422277

Stock #: 10911
Stock Desc: 2024 FW FOREST RIVER CEDAR
CREEK 391WOW
Model: 391WOW
Serial #: 4X4FCRR27RS233105
Chassis #:
Mileage:
Key #: 13200
Req'n #:
License #:
Trim:

Purchase Date: 28 DEC 24
Date In: 15 SEP 25
Promise Date:
Promise Time:
Schedule Date:
Completed: 28 FEB 26
Warr. Date: 28 DEC 24

Job #1 - Warranty

COMPLAINT: JWRAP ON DOOR SIDE DRIPS WHEN FRONT AC IS RUNNING

CAUSE: WATER LEAKING THROUGH RAIN GUTTER SEAM AND RUNNING DOWN THE SIDE OF UNIT

CORRECTION: RESEAL AREA
LABOR .20

Labor

Job #	Description	Hours	Total
1	RESEALED	0.20	33.00
Subtotal for Job #1:			33.00

Job #2 - Warranty

COMPLAINT: SCREWS ARE BACKING OUT OF SIDE OF UNIT

CAUSE: SCREWS WORKED LOOSE AND CAME OUT

CORRECTION: RESECURE SCREWS AND REPLACE THE ONES MISSING
LABOR .20

Labor

Job #	Description	Hours	Total
2	RESECURED	0.20	33.00
Subtotal for Job #2:			33.00

Job #3 - Warranty

FRONT AC IS HUMMING WHILE RUNNING

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: TRIM IN FRONT BEDROOM IS FALLING OFF IN CLOSET AND ON SIDE OF SLIDE

CAUSE: TRIM NOT SECURED IN CORRECTLY AND IS COMING LOOSE

CORRECTION: RESECURE TRIM IN PLACE
LABOR .20

Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS



Labor

Job #	Description	Hours	Total
4	RESECURED	0.20	33.00
Subtotal for Job #4:			33.00

Job #5 - Warranty

BEAM ACROSS CEILING IS FALLING DOWN

Subtotal for Job #5: 0.00**Job #6 - Warranty**

COMPLAINT: SHOWER HANDLE FELL APART DRIVING DOWN THE ROAD, CUST FOUND IT BROKE OFF WHEN THEY ARRIVED AT THE CAMP GROUND

CAUSE: FAULTY SHOWER HANDLE

CORRECTION: REPLACE SHOWER HANDLE
AND WATER TEST
LABOR .30**Labor**

Job #	Description	Hours	Total
6	REPLACED	0.10	16.50
Subtotal for Job #6:			16.50

Job #7 - Warranty

COMPLAINT: LATCH ON TV FALSE WALL WILL NOT STAY CLOSED AND FALSE PANEL IS OPENING WHILE DRIVING DOWN THE ROAD CAUSING DAMAGE TO TRIM AND STILE

CAUSE: THE CATCH ON THE FALSE WALL IS BENT AND NOT LATCHING AS IT SHOULD. THIS IS ALLOWING THE DOOR TO COME OPEN IN TRANSIT AND DAMAGED THE DOOR.

CORRECTION: REMOVE ALL DAMAGED PARTS (LATCH AND STILE) REPLACE DAMAGED STILE
AND LATCH ON FALSE WALL
LABOR 2.0**Labor**

Job #	Description	Hours	Total
7	REPALCED DAMAGED STILE	2.00	330.00

Parts

Part #	Description	Qty	Price	Total
F100430490	HIDDEN PANTRY LATCH	1.00	47.81	47.81
F100369593	DOOR JAM	1.00	3.86	3.86

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	18.83	18.83
FRT	FREIGHT ON PARTS	1.00	46.72	46.72

Subtotal for Job #7: 447.22**Job #8 - Warranty**

FRONT BASEMENT ON BOTH SIDES IS LEAKING

Subtotal for Job #8: 0.00**Job #9 - Warranty**

COMPLAINT: CS PINBOX COVER IS BOWED

CAUSE: BOX INSTALLED INCORRECTLY AT FACTORY AND THIS HAS ALLOWED THE BOX TO BOW OVER TIME

Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS

CORRECTION: REMOVE DAMAGED PIN BOX AND REPLACE WITH NEW ONE
LABOR 1.0

Labor

Job #	Description	Hours	Total
9	REPLACED	1.00	165.00

Parts

Part #	Description	Qty	Price	Total
F100447253	HITCH PIN COVER, 2 PIECE, BLACK, FOR PIN BOX	1.00	30.86	30.86

Subtotal for Job #9: 195.86

Job #10 - Warranty

SLIDE ON DOORSIDE WHEN CLOSED IS NOT SEALING ALL OF THE WAY

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: DOORSIDE REAR DECALS ARE PEELING

CAUSE: DECALS ARE BUBBLING UP AT THE REAR CORNER

CORRECTION: REPLACE BOTH THE BLACK AND BLUE DECAL ON DS REAR
LABOR 2.0

Labor

Job #	Description	Hours	Total
11	REPLACED DECALS	2.00	330.00

Subtotal for Job #11: 330.00

Job #12 - External

ACS WILL NOT COOL DOWN BELOW 78* AT BEACH CUS WANTS TO KNOW IF DUCTS ARE
CONNECTED THROUGH THE UNIT

Parts

Part #	Description	Qty	Price	Total
73-9986	Air Conditioner Ceiling Assembly; For Use With Coleman Mach Air Conditioners; Non-Ducted System; Plenum Only; For Use With Wall Thermostat	1.00	N/C	N/C

Subtotal for Job #12: 0.00

Job #13 - Warranty

COMPLAINT: WOOD ON KITCHEN ISLAND IS SWELLED, CUS STATES THERE ARE NO LEAKS

CAUSE: CONNECTION TO KITCHEN SINK WAS DRIPPING OVER NIGHT AND SETTLED NEAR
ISLAND. THIS CAUSED THE WOOD TO SWELL ON ISLAND.

CORRECTION: REMOVE ALL SWOLLEN WOOD. TIGHTEN THE FITTING AND REPLACE THE STILE
AND ANY DAMAGED WOOD ON ISLAND
LABOR 3.0

Labor

Job #	Description	Hours	Total
13	REPAIRED AREA	1.50	247.50

Parts

Part #	Description	Qty	Price	Total
F100663115	ISLAND CABINET	1.00	184.37	184.37

W/O: 26071



Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS



F100234073	STILE, 6" X 9', LUMBERCORE, SQUARE EDGES, VINYL WRAPPED, WHITE, LAV [STILE 39] 2021	2.00	29.37	58.74
------------	---	------	-------	-------

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00
FRT	FREIGHT ON PARTS	1.00	190.55	190.55

Subtotal for Job #13: 681.16

Job #14 - Warranty

COMPLAINT: STOVE HAS SURFACE SCRATCHES

CAUSE: STOVE IS GOUGDED ON THE SURFACE FROM THE GROMMETS NOT BEING THERE

CORRECTION: REPLACE STOVE

LABOR 1.0

Labor

Job #	Description	Hours	Total
14	REPALCED	1.20	198.00

Parts

Part #	Description	Qty	Price	Total
F100499133	RANGE, PART, COOKTOP CONSOLE, 24", STAINLESS STEEL, REPLACEMENT FOR FURRION FGR24D3A1A-SS [CA14] V#2022120274	1.00	56.47	56.47
F100526755	RANGE, PART, COOKTOP GRATE HOLDING GASKET (GROMMET), 4 PACK, FOR FURRION MODEL FGR24D3A1A-SS [AC65] (C-FGR24D3A1A-03)	1.00	2.73	2.73

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON STOVE PARTS	1.00	5.00	5.00

Subtotal for Job #14: 262.20

Parts Total:	384.84
Labour Total:	1,386.00
Sublet Total:	0.00
Extras Total:	261.10
WORK ORDER TOTAL:	2,031.94

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 03 Mar 2026

W/O: 26071



Customer #: 59072
EXTREME AUTOMOTIVE,
KYKERS

