



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26116



WO #: 26116

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11216

Stock Desc: 2026 FW FOREST RIVER CEDAR

CREEK 39RKB

Model: 39RKB

Serial #: 4X4FCRR26TS235368

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim: 39RKB

Purchase Date: 19 JAN 26

Date In: 24 SEP 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 28 JAN 26

Warr. Date: 19 JAN 26

**Job #1 - Warranty**

COMPLAINT: SCRATCH ON KITCHEN CABINET DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

**Labor**

Job #	Description	Hours	Total
1	FILL AND COLOR	0.20	33.00
<b>Subtotal for Job #1:</b>			<b>33.00</b>

**Job #2 - Warranty**

COMPLAINT: KITCHEN STILE BEHIND SEATING NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

**Labor**

Job #	Description	Hours	Total
2	FILL AND COLOR	0.20	33.00
<b>Subtotal for Job #2:</b>			<b>33.00</b>

**Job #3 - Warranty**

COMPLAINT: THE WINDOW IN THE SITTING ROOM IS SHOWING DAYLIGHT AT THE BOTTOM

CAUSE: NOTED ON DAF

OUTTER TRIM WAS NOT INSTALLED CORRECTLY ALLOWING LIGHT TO COME THROUGH THE BOTTOM

CORRECTION: REMOVE SET SCREWS ON INTERIOR TRIM RING AROUND THE WINDOW AND RESECURE BACK IN CORRECT PLACE.

LABOR 1.0 LCI REPLACED WINDOW

**Labor**

Job #	Description	Hours	Total
3	REPLACED WINDOW	1.00	165.00

Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,



<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100688546	30X26 G20 WITH SHADE	1.00	255.88	255.88
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	11.86	11.86
79233	BUTYL TAPE 1/8X3/4	1.00	10.11	10.11
<b>Subtotal for Job #3:</b>				<b>442.85</b>

**Job #4 - Warranty**

COMPLAINT: CHIPS IN BEDROOM DOOR IN DIFF AREAS

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

<b>Labor</b>			
Job #	Description	Hours	Total
4	FILL AND COLOR	0.20	33.00
<b>Subtotal for Job #4:</b>			<b>33.00</b>

**Job #5 - Warranty**

COMPLAINT: STILE ON LIVING ROOM SLIDE HAS DEEP SCRATCHES IN SEVERAL PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND THE AREA  
LABOR .20

<b>Labor</b>			
Job #	Description	Hours	Total
5	FILL AND COLOR	0.20	33.00
<b>Subtotal for Job #5:</b>			<b>33.00</b>

**Job #6 - Warranty**

COMPLAINT: FRIDGE IS NOT SECURED IN PLACE ON THE BOTTOM. FRIDGE IS STICKING OUT AT THE BOTTOM ALOT MORE THAN THE TOP.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE FRIDGE AND RESECURE BACK IN CORRECT PLACE  
LABOR .50

<b>Labor</b>			
Job #	Description	Hours	Total
6	RESECURED FRIDGE IN PLACE	0.50	82.50
<b>Subtotal for Job #6:</b>			<b>82.50</b>

**Job #7 - Warranty**

COMPLAINT: THE MANTEL WHERE THE TV AND FIREPLACE IS HAS SCRATCHES ALL ACROSS THE TOP. THE CORNER TRIM IS CRACKED AND THE FLOATING SHELF IS CRACKED AND DAMGED AS WELL.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE TV AND FIREPLACE. REMOVE THE DAMAGED MANTEL AND TRIM. REPLACE THE MANTEL AND TRIM WITH NEW. REINSTALL TV AND FIREPLACE.  
LABOR 3.1

<b>Labor</b>			
Job #	Description	Hours	Total
7	REPLACED MANTEL	2.00	330.00



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,





Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100771840	PANELING, 4' X 80 3/4", M.WALNUT, GROOVED, PANEL	1.00	250.97	250.97
F100801071	SEAM TAPE	10.00	0.23	2.30
F100663117	MANTEL, 4" x 38", FIREPLACE MANTEL, M.WALNUT   39RKB	1.00	111.35	111.35
F100584778	CASING, 3/8" X 1 7/16" X 121", NOCE SECCHIA/WALNUT 45G, MM CASING 405 MDF   2025 V#47090239	2.00	8.97	17.94

<b>Other Services</b>				
Code	Description	Qty	Price	Total
CRA	CRATE ON F100771640	1.00	65.00	65.00
SHP	SHP ON F100771640	1.00	148.05	148.05
SHP	SHP ON F100801071,663117,584778	1.00	5.00	5.00
SHP	SHP ON PO17615	1.00	222.68	222.68
<b>Subtotal for Job #7:</b>				<b>1,153.29</b>

**Job #8 - Warranty**

COMPLAINT: WINDOW IN THE BEDROOM ON DOOR SIDE HAS A GAP AT THE BOTTOM, WINDOW NOT CLOSING CORRECTLY

CAUSE: NOTED ON DAF  
OUTTER TRIM NOT INSTALLED CORRECTLY ALLOWING LIGHT OT COME IN AT THE BOTTOM

CORRECTION: REMOVE SET SCREWS IN THE TRIM RING ON THE INTERIOR AND THEN RESECURE BACK IN CORRECT PLACE.

LABOR 1.0 LCI REPLACED WINDOW

<b>Labor</b>			
Job #	Description	Hours	Total
8	REPLACED WINDOW	1.00	165.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100688546	30X26 G20 WITH SHADE	1.00	255.88	255.88

<b>Other Services</b>				
Code	Description	Qty	Price	Total
CRA	CRATE CHARGES	1.00	130.00	130.00
SHP	SHIPPING/FREIGHT FEE	1.00	5.00	5.00
<b>Subtotal for Job #8:</b>				<b>555.88</b>

**Job #9 - Warranty**

COMPLAINT: WIRES ARE STRIPPED ON THE ODS SLIDE OVER THE TIRE

CAUSE: NOTED ON DAF  
WIRES ARE LAYING ON THE TIRES AND RUBBING CAUSING THE WIRES TO BE DAMAGED

CORRECTION: REMOVE AND REINSTALL FLEX GUARD, REPLACE WIRE LOOM, REPLACE ALL DAMAGED WIRE AND INSTALL WITH WATER PROOF CONNECTIONS.

LABOR 2.0

<b>Labor</b>			
Job #	Description	Hours	Total
9	REPLACED LOOM AND REPAIRED AREA	2.00	330.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
1834045	TEMFLEX 175 ELECTRICAL TAPE VINYL	1.00	2.86	2.86



737302

POLYLOOM

2.00

0.01

0.02

**Subtotal for Job #9:**

**332.88**

W/O: 26116

Parts Total: 919.17

Labour Total: 1,204.50

Sublet Total: 0.00

Extras Total: 575.73

**WORK ORDER TOTAL: 2,699.40**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 12 Feb 2026



Customer Work Order

Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

