



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26132



WO #: 26132

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:
 Author: S.DAVIS
 Location: IH
 Invoice #:

Stock #: 11213
 Stock Desc: 2026 TT KZ-RV CONNECT 313MK
 Model: 313MK
 Serial #: 4EZTL3322T4088810
 Chassis #:
 Mileage: 0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 26 SEP 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 23 OCT 25
 Warr. Date:

Job #1 - Warranty

COMPLAINT: VALANCE AT REAR WINDOW NDS IS PEELING

CAUSE: NOTED ON DAF

CORRECTION: TRIM THE PAPER, COLOR AND BLEND AREA
 LABOR .20

Labor

Job #	Description	Hours	Total
1	CORRECTED AND COLOR	0.10	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REAR WINDOW ON UNIT IS LEAKING AND ALLOWING WATER TO GET ON THE BACK OF THE SEATING.

CAUSE: NOTED ON DAF
 MANUFACTOR DEFECT IN WINDOW

CORRECTION: REMOVE FAULTY WINDOW, CLEAN AREA, REPLACE WITH NEW WINDOW, RESEAL AREA AND WATER TEST
 LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: STILE AT FIREPLACE IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
 LABOR .20

Labor

Job #	Description	Hours	Total
3	FILL COLOR AND BLEND	0.10	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: KITCHEN DRAWER BESIDE STOVE RUBS AGAINST THE STILE WHEN OPENING AND

Customer #: 47602
 TRI-AM RV CENTER-EAST
 TN,



CLOSING

CAUSE: NOTED ON DAF
DOOR IS OUT OF ADJUSTMENT

CORRECTION: REMOVE DRAWER AND GUIDES, COLOR AND BLEND ANY DAMAGE TO THE CABINET, REINSTALL GUIDES TO OPERATE CORRECTLY
LABOR .50

Labor

Job #	Description	Hours	Total
4	REPAIRED AREA	0.30	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: KITCHEN STILE IS CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
5	FILL AND COLOR	0.10	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: SHADE TO THE LEFT OF THE SEATING WILL NOT GO UP

CAUSE: NOTED ON DAF

CORRECTION: REMOVE VALANCE AND SHADE, ADJUST SHADE, REINSTALL SHADE AND VALANCE
LABOR .50

Labor

Job #	Description	Hours	Total
6	ADJUSTED	0.10	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: SECURITY STRAP FOR BEDROOM CLOSET DOOR WAS NEVER INSTALL

CAUSE: NOTED ON DAF
NEVER INSTALLED AT FACTORY, NO HOLES TO PROVE INSTALL

CORRECTION: INSTALL SECURITY STRAP IN CORRECT PLACE
LABOR .20

Labor

Job #	Description	Hours	Total
7	INSTALL STRAP	0.20	N/C

Subtotal for Job #7: 0.00



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



W/O: 26132

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 23 Oct 2025

Customer Signature : _____

Customer Work Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

