



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 26218  
Promised Date: 25 OCT 25



WO #: 26218

Customer: 93198 - MILLSAPS, JOE  
Address: 106 DISSTON RD  
OAK RIDGE, TN  
37830

Home Phone: (865) 263-1912

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #: 11005  
Stock Desc: 2025 CT FOREST RIVER  
ROCKWOOD CAMP A213HS  
Model: A213HS  
Serial #: 4X4CPRW14SD320764  
Chassis #:  
Mileage: 0  
Key #: 1500  
Req'n #:  
License #:  
Trim:

Purchase Date: 20 SEP 25  
Date In: 17 OCT 25  
Promise Date: 30 OCT 25  
Promise Time: 09:00am  
Schedule Date:  
Completed:  
Warr. Date: 20 SEP 25

**Job #1 - External**

CS THAT THERE IS WOOD MISSING UNDER THE BED

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: CS THAT THE ARM FEEL OFF THE THUMB LATCH ON THE COMPARTMENT DOOR.  
THIS DOOR DOES NOT HAVE A TAG, PHOTOS WILL SHOW THIS.

CAUSE: FAULTY THUMB LATCH ON COMPARTMENT DOOR

CORRECTION: REPLACE THUMB LATCH  
LABOR .40

**Subtotal for Job #2: 0.00**

**Job #3 - External**

INSTALL LIC PLATE

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

**Subtotal for Job #3: 0.00**

**Job #5 - Warranty**

COMPLAINT: CS THAT THE WINDOW IN THE ENTRY DOOR WILL NOT OPEN MORE THEN AN INCH

CAUSE: WINDOW IS EXTREMELY TIGHT

CORRECTION: ADJUST WINDOW AND LUBE  
LABOR .30

**Subtotal for Job #5: 0.00**

**Job #6 - Warranty**

COMPLAINT: CS THAT THE ENTRY DOOR WILL NOT LOCK FROM THE INSIDE

CAUSE: STRIKER PLATE IS TO HIGH AND NOT ALLOWING DOOR TO LATCH

CORRECTION: RELOCATE STRIKER PLATE TO LINE UP CORRECTLY FOR DOOR TO CLOSE.  
REPAIR THE HOLES FROM THE FIRST INSTALL OF STRIKER PLATE.

Customer #: 93198  
MILLSAPS, JOE



LABOR .50

Subtotal for Job #6: 0.00

**Job #7 - External**

CS THAT THERE ARE SCREW COMING LOOSE IN THE RIGHT (DOOR SIDE) REAR CORNER ON THE INSIDE

Subtotal for Job #7: 0.00

**Job #8 - Warranty**

COMPLAINT: CS THAT THE TRIM ON THE FRONT DOOR SIDE CORNER IS COMING LOOSE

CAUSE: BOTH SCREWS ARE STRIPPED AND WILL NOT STAY IN PLACE

CORRECTION: REPLACE SCREWS WITH LARGER ONES  
LABOR .20

Subtotal for Job #8: 0.00

**Job #9 - Warranty**

COMPLAINT: CS THAT THE FRIDGE IS NOT SECURED AND COMES OUT OF ITS LOCATION WHEN TRAVELING

CAUSE: FRIDGE ONLY HAS ONE BRACKET HOLDING IT IN PLACE. THIS ALLOWS THE FRIDGE TO MOVE AND THE DOOR COMES OPEN. THE DOOR IS DAMAGED FROM FRIDGE NOT BEING SECURED INTO PLACE CORRECT.

CORRECTION: REPLACE FRIDGE DOOR AND SECURE FRIDGE IN PLACE WITH ANOTHER BRACKET  
LABOR 1.0

Subtotal for Job #9: 0.00

**Job #10 - Warranty**

COMPLAINT: CS THAT THE LATCH THAT HOLDS THE SIDE WALL IN PLACE IS LOOSE

CAUSE: LATCH WORKED LOOSE

CORRECTION: RESECURE LATCH IN PLACE  
LABOR .20

Subtotal for Job #10: 0.00

**Job #11 - Warranty**

COMPLAINT: THE SINK BASE HAS CAME LOOSE FROM THE COUNTER

CAUSE: SINK NOT SECURE IN PLACE AND LIFTING, ADHESIVE NOT HOLDING SINK DOWN

CORRECTION: REMOVE SINK, CLEAN AREA, ADD ADHESIVE TO SECURE SINK IN PLACE AND SEAL AREA  
LABOR 1.0

Subtotal for Job #11: 0.00

**Job #12 - Warranty**

COMPLAINT: THE DOOR/WALL AT THE TOILET IS DAMAGED FROM SCREWS NOT STAYING IN

CAUSE: SCREWS ARE STRIPPED OUT ALLOWING DOOR TO FALL AND BECOME DAMAGED

CORRECTION: REPLACE DOOR  
LABOR .50

W/O: 26218  
Promised Date: 30 OCT 25



Customer #: 93198  
MILLSAPS, JOE



Subtotal for Job #12: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

W/O: 26218  
Promised Date: 30 OCT 25

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X

-----  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 24 Oct 2025



Customer Work Order

Customer #: 93198  
MILLSAPS, JOE

