



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26371



WO #: 26371 (Appointment Date: 10 NOV 2025 - Time: 03:00pm)

Customer: 93399 - WEBB, JOHN  
 Address:

Home Phone: 276-275-4536

Work Phone:  
 Author: S.DAVIS  
 Location: IH  
 Invoice #:

Stock #:  
 Stock Desc: 2025 TT FOREST RIVER EAST TO  
 WEST  
 Model:  
 Serial #: 5ZT2DERB2S9015465  
 Chassis #:  
 Mileage:  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date:  
 Date In: 10 NOV 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 12 JAN 26  
 Warr. Date:

**Job #1 - Warranty**

COMPLAINT: SEVERAL OF THE LIGHTS THAT HAVE THE BUTTON IN THE MIDDLE ARE VERY HARD TO PUSH TO GET ON. THESE ARE IN THE BEDROOM AND ON THE SLIDE OUT

CAUSE: BOTH LIGHTS ON THE SLIDE OUT WILL NOT WORK AS DESIGNED, FAULTY LIGHTS.

CORRECTION: REPLACE THE TWO ROUND LIGHTS ON THE MAIN SLIDE OUT  
 LABOR FOR BOTH .40

**Labor**

Job #	Description	Hours	Total
1	REPLACED LIGHTS	0.20	33.00

**Parts**

Part #	Description	Qty	Price	Total
F100040874	LIGHT - 3C-2: LED PUSH BUTTON FLUSH MOUNT MUSHROOM ROOF DOME LIGHT, ULTRA BRIGHT - 4 1/2"	2.00	2.30	4.60

**Subtotal for Job #1: 37.60**

**Job #2 - Warranty**

COMPLAINT: RUST ON THE FRAME WHERE THE JACKS ARE AND OTHER AREAS UNDERNEATH

CAUSE: RUST HAS DEVELOPED ALONG THE FRONT SIDE OF THE FRAME BY THE STAB JACK

CORRECTION: CLEAN AND REPAINT THE RUSTED AREA  
 LABOR .50

**Labor**

Job #	Description	Hours	Total
2	REPAINTED AREA	0.50	82.50

**Subtotal for Job #2: 82.50**

**Job #3 - External**

CUST HAS A EXTRA PANEL WHERE HIS PANEL IS THAT SHOWS TANK LEVELS, CUST WOULD LIKE TO KNOW WHAT THAT PANEL IS FOR AT PICK UP

Customer #: 93399  
 WEBB, JOHN



**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
<b>Subtotal for Job #3:</b>				<b>0.00</b>

**Job #4 - External**

CUST HAS A TRIP RIGHT BEFORE THANKSGIVING

**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: INSULATION COMING OUT FRONT AND BACK CHECK AND ADVISE

CAUSE: SPRAY FOAM INSULATION IS PROTRUDING FROM UNDERBELLY OF UNIT

CORRECTION: CUT OFF AND REMOVE THE EXCESSIVE FOAM  
LABOR .50

**Labor**

Job #	Description	Hours	Total
5	CLEANED AND RESEALED	0.10	16.50
<b>Subtotal for Job #5:</b>			<b>16.50</b>

**Job #6 - Warranty**

COMPLAINT: BACK DOORSIDE CORNER CAULKING ON ROOF IS CRACKING CHECK AND ADVISE

CAUSE: TECH VERIFIED THE SEALANT ON THE BACK CORNER HAS OPEN VOIDS AND ALLOWING MOISTURE AND WATER IN THESE AREAS

CORRECTION: CLEAN AND RESEAL THE NEEDED AREA ON THE ROOF  
LABOR .50

**Labor**

Job #	Description	Hours	Total
6	CLEANED AREA	0.20	33.00
<b>Subtotal for Job #6:</b>			<b>33.00</b>

**Job #7 - Warranty**

COMPLAINT: DOOR SIDE AWNING RAIL SPLIT IS NOT CAULKED CHECK AND ADVISE

CAUSE: GUTTER RAIL IS NOT SEALED WHERE IT MEETS AT AND ALLOWING WATER TO RUN DOWN THE SIDE OF THE UNIT

CORRECTION: CLEAN AND RESEAL THE GUTTER RAIL  
LABOR .40

**Labor**

Job #	Description	Hours	Total
7	CLEANED AND RESEALED	0.20	33.00

**Parts**

Part #	Description	Qty	Price	Total
38-1865	PROFLEX RV SEALANT BLK	1.00	12.38	12.38
<b>Subtotal for Job #7:</b>				<b>45.38</b>

**Job #8 - Warranty**

COMPLAINT: FRONT DOORSIDE CORNER AT GUTTER SPOUT SEALANT LOOKS BAD CHECK AND ADVISE

CAUSE: FOUND OPEN VOIDS IN THE SEALANT ALLOWING MOISTURE AND WATER IN THE CORNERS OF THE UNIT



Customer #: 93399  
WEBB, JOHN



CORRECTION: CURRENT SEAL NEEDS TO BE REMOVED, AREA CLEANED AND NEW SEALANT APPLIED TO THE AREAS  
LABOR 1.0

**Labor**

Job #	Description	Hours	Total
8	RESEAL AREA	0.20	33.00

**Parts**

Part #	Description	Qty	Price	Total
38-9018	LAP SEALANT WHITE	1.00	10.21	10.21

**Subtotal for Job #8: 43.21**

**Job #9 - Warranty**

COMPLAINT: LARGE SLIDE IS DROPPED DOWN IN THE MIDDLE WHEN LOOKING AT ROOF, CHECK AND ADVISE

CAUSE: TOP SLIDE SEAL ON MAIN SLIDE DROPS DOWN AT OR NEAR THE CENTER POINT. SEAL NOT STAYING IN CORRECT PLACE.

CORRECTION: REPLACE THE SLIDE SEAL ON THE TOP OF THE MAIN SLIDE OUT. THE SLIDE TOPPER WILL NEED TO BE REMOVED AND REINSTALLED TO DO THIS JOB

LABOR 2.5

**Labor**

Job #	Description	Hours	Total
9	REPAIR	0.70	115.50

**Parts**

Part #	Description	Qty	Price	Total
F100212571	SEAL, 84" LENGTH, DOUBLE WIPE 2" WALL CAP WITH 2.375" WIPE   BOYD 2271-84	2.00	27.82	55.64

**Other Services**

Code	Description	Qty	Price	Total
SPK	SPECIAL PACKING/TUBE	1.00	20.00	20.00
SHP	SHIPPING/FREIGHT FEE	1.00	50.46	50.46

**Subtotal for Job #9: 241.60**

**Job #10 - Warranty**

COMPLAINT: WHEN SLIDE IS OUT ON LARGE SLIDE THE FRONT SEALS TOUCH, THE REAR SEALS DO NOT, CHECK AND ADVISE

CAUSE: RIGHT SIDE SEAL ON MAIN SLIDE IS VERY TIGHT WHILE LEFT SIDE SEAL DON'T TOUCH SLIDE.

CORRECTION: NEED TO LOOSEN SLIDE FROM MOUNTS AND SHIFT OVER 1.5" TO ALIGN PROPERLY AND CORRECT CONCERN

LABOR 1.5

**Labor**

Job #	Description	Hours	Total
10	ADJUST SLIDE	0.50	82.50

**Subtotal for Job #10: 82.50**

W/O: 26371



Customer #: 93399  
WEBB, JOHN



Parts Total: 82.83  
Labour Total: 429.00  
Sublet Total: 0.00  
Extras Total: 70.46  
**WORK ORDER TOTAL: 582.29**

W/O: 26371

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 12 Jan 2026

Customer Signature : \_\_\_\_\_

Customer Work Order



Customer #: 93399  
WEBB, JOHN

