



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26375
 Promised Date: 26 NOV 25



WO #: 26375 (Appointment Date: 12 NOV 2025 - Time: 02:00pm)

Customer: 93437 - KOLESSAR, SCOTT
 Address:

Home Phone: 412-997-8153

Work Phone:
 Author: S.DAVIS

Location: IH
 Invoice #:

Stock #:
 Stock Desc: 2026 FOREST RIVER XLR
 Model:
 Serial #: 4X4TXLJ2XTF171151
 Chassis #:
 Mileage:0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 12 NOV 25
 Promise Date: 30 NOV 25
 Promise Time: 09:00am
 Schedule Date:
 Completed: 17 MAR 26
 Warr. Date:

Job #1 - External

SC TO MAMMOTH RIDGE TO ADDRESS WARRANTY CONCERNS. CUST IS TAKING OFF WORK TO MEET US THERE @ 2:00

\$50.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: FLUSH TANK IS LEAKING, CUST WILL GO OVER DETAIL WITH TECH

CAUSE: BLACK TANK FLUSH IS LEAKING

CORRECTION: REPLACE BLACK TANK FLUSH
 LABOR .30

Labor

Job #	Description	Hours	Total
2	REPLACED BLACK TANK FLUSH	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
60P14421A	VACUUM BREAKER	1.00	13.91	13.91

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	19.46	19.46
Subtotal for Job #2:				85.87

Job #3 - Warranty

COMPLAINT: GETTING NO HEAT TO THE BEDROOM AND BATHROOM

CAUSE: UPON INSPECTION THERE IS A 1" GAP BETWEEN FURNACE AIR OUTLET AND DUCTWORK IN THE FLOOR. ALLOWING AIR LEAKAGE AND REDUCED AIR FLOW TO AFFECTED AREAS.

CORRECTION: REMOVE AND REINSTALL FURNACE. BUILD A NEW PLATFORM WITH NEW GASKET TO INSTALL GASKET ON.
 LABOR 3.0

Customer #: 93437
 KOLESSAR, SCOTT



W/O: 26375
Promised Date: 30 NOV 25

Labor	Description	Hours	Total
Job #			
3	BUILT NEW PLATFORM	2.30	402.50

Parts	Description	Qty	Price	Total
Part #				
70A03036A	GASKET-BOTTOM, FURNACE	1.00	1.61	1.61
Subtotal for Job #3:				404.11

Job #4 - Warranty

COMPLAINT: RIGHT FRONT TIRE HAS A SPOT STICKING OUT ON IT

CAUSE: VERIFIED TIRE HAS A BULGE ON RIGHT FRONT. THIS IS CAUSED BY INTERNAL DAMAGE TO THE TIRES STRUCTURE.

CORRECTION: REPLACE TIRE.DAMAGED TIRE NEEDS TO BE REMOVED FROM RIM AND INSTALL NEW ONE.
LABOR 1.0

Subtotal for Job #4: 0.00

Job #5 - External

GET UNIT INFO

Subtotal for Job #5: 0.00

Parts Total: 15.52
Labour Total: 455.00
Sublet Total: 0.00
Extras Total: 19.46
WORK ORDER TOTAL: 489.98

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 17 Mar 2026

Customer #: 93437
KOLESSAR, SCOTT

