



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26388



WO #: 26388

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11240

Stock Desc: 2026 FW FOREST RIVER CEDAR

CREEK 385RK

Model: 385RK

Serial #: 4X4FCRR26TS235371

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 14 NOV 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 25 FEB 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: COMPARTMENT DOOR TO THE LEFT OF THE ENTRY DOOR HAS SEVERAL SCRATCHES ACROSS THE DOOR

CAUSE: NOTED ON DAF

SCRATCHED AT INSTALL AT FACTORY

CORRECTION: REPLACE COMPARTMENT DOOR

PERP TECH HAS ATTEMPTED TO BUFF OUT THE SCRATCHES BEFORE WE ASK FOR A REPLACEMENT

LABOR 1.0

Labor

Job #	Description	Hours	Total
1	REPLACE COMPARTMENT DOOR	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
F100748724	COMPARTMENT DOOR, 60" X 30", BLACK, 725 BAG RD4 SD TH 60X30 BK FN 7846BK F1x2 27A BKPL MB0023 EXA 2-LK590 2026 V#V001145654	1.00	549.87	549.87

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	148.00	148.00
CRA	CRATE CHARGES	1.00	65.00	65.00

Subtotal for Job #1: 850.37

Job #2 - Warranty

COMPLAINT: THE COMPARTMENT DOOR TO THE RIGHT OF THE ENTRY DOOR IS SCRATCHED AND HAS SEVERAL MARKS ON IT

CAUSE: NOTED ON DAF

SCRATCHED FROM FACTORY

CORRECTION: REPLACE THE COMPARTMENT DOOR

LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPLACED COMPARTMENT DOOR	0.50	87.50

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



**Parts**

Part #	Description	Qty	Price	Total
F100628115	COMPARTMENT DOOR, 28 1/2" X 25 3/4", 600 LPD RD4 SD RH 28.5X25.75 BK FN 7846BK 36A BKPL PNO 2-LK586 1FP NWEED 2025 V#V001145676	1.00	205.30	205.30
F100739334	DECAL, CC, SIDE DIE CUT #54-RH /DS, WHITE STRIPE, CURVED 2026 V#FR-25-94145A-RH	1.00	3.52	3.52

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	108.12	108.12
SHP	SHIPPING ON F100297016	1.00	5.00	5.00

Subtotal for Job #2: 409.44**Job #3 - Warranty**

COMPLAINT: LEASH-LATCH STICKER IS ROLLING UP ALL AROUND IT

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE LEASH-LATCH STICKER
LABOR .20**Labor**

Job #	Description	Hours	Total
3	REPLACED STICKER	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
F100297016	LABEL, LEASH LASH	1.00	2.57	2.57

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	5.00	5.00

Subtotal for Job #3: 42.57**Job #4 - Warranty**

COMPLAINT: KITCHEN CABINET LOOKS CRACKED ON THE LOWER CORNER AT THE HANDLE

CAUSE: NOTED ON DAF
THIS MAKES THE CABINET LOOK CRACKED FROMCORRECTION: FILL, COLOR AND BLEND AREA
LABOR .30**Labor**

Job #	Description	Hours	Total
4	COLOR AND BLEND AREA	0.30	52.50

Subtotal for Job #4: 52.50**Job #5 - Warranty**

COMPLAINT: TOP OF THE DRESSER IN THE BEDROOM IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE DRESSER COUNTER TOP
LABOR .40**Labor**

Job #	Description	Hours	Total
5	REPLACED COUNTER TOP	0.40	70.00



Parts

Part #	Description	Qty	Price	Total
F100734551	COUNTERTOP, DRESSER TOP, 15" X 73 1/8", M.WALNUT, DRESSER TOP, 385RK V#MT1573-MW	1.00	164.61	164.61

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	46.72	46.72

Subtotal for Job #5: 281.33

Parts Total: 925.87
Labour Total: 332.50
Sublet Total: 0.00
Extras Total: 377.84

WORK ORDER TOTAL: 1,636.21

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Feb 2026



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

