



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26446



WO #: 26446

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11247

Stock Desc: 2026 THFW FOREST RIVER ROGUE
351G2

Model: 351G2

Serial #: 4X4FVGL29T5404031

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 02 DEC 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: LINO FLOOR IS ROLLED UP IN THE BASEMENT AREA

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE PLASTIC TRAY AND SMOOTH OUT THE LINO FLOORING
LABOR .80

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SEALANT HAS A HOLE ON THE LED STRIP ON FRONT CAP

CAUSE: NOTED ON DAF

CORRECTION: RESEAL AREA
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SHELF IN BEDROOM CLOSET IS STICKING UP ON ONE SIDE

CAUSE: NOTED ON DAF

CORRECTION: RESECURE SHELF IN CORRECT PLACE TO LAY FLAT
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CARPET STICKING OUT ON BOTH SIDES OF THE BEDROOM SLIDE

CAUSE: NOTED ON DAF

CORRECTION: CUT CARPET TO FIT CORRECTLY AND NOT STICK OUT
LABOR .50

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00**Job #5 - Warranty**

COMPLAINT: THE PLASTIC TRIM ON THE POCKET DOOR GOING TO THE BEDROOM IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE PLASTIC TRIM GOING INTO BEDROOM
LABOR 1.0**Subtotal for Job #5: 0.00****Job #6 - Warranty**

COMPLAINT: GLASS DOOR GOING INTO THE PATIO AREA IS HARD TO OPEN AND CLOSE

CAUSE: NOTED ON DAF

CORRECTION: ADJUST DOOR TO OPERATE CORRECTLY
LABOR .50**Subtotal for Job #6: 0.00****Job #7 - Warranty**

COMPLAINT: BACK OF FOUR GLASS CABINET DOORS ARE GOUGED IN THE LIVING AREA

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE GLASS ON ALL 4 CABINET DOORS IN LIVING AREA
LABOR 2.0**Subtotal for Job #7: 0.00****Job #8 - Warranty**

COMPLAINT: THE WIRE MESH ABOVE THE STOVE IS CUT WRONG AND BOWING OUT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE WIRE MESH AND CUT TO FIT THEN REINSTALL
LABOR .50**Subtotal for Job #8: 0.00****Job #9 - Warranty**

COMPLAINT: KITCHEN SINK IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE SINK FROM COUNTER THAT IS GLUED DOWN, REMOVE ALL WATER CONNECTIONS AND DRAIN PIPE, CLEAN COUNTER. INSTALL NEW SINK, CONNECT ALL WATER CONNECTIONS AND DRAIN PIPE THEN TEST
LABOR 3.0**Subtotal for Job #9: 0.00****Job #10 - Warranty**

COMPLAINT: MARKS ON THE DOOR LATCH GOING OUT TO THE RAMP AREA

CAUSE: NOTED ON DAF

CORRECTION: REPLACE DOOR LATCH

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

LABOR .50

Subtotal for Job #10: 0.00

W/O: 26446

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 02 Dec 2025



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

