

DEALER ACCOUNT #	1054928	CLAIM STATUS	Paid
LINK FORD & RV MINONG LLC		CLAIM	2607369
1025 W HOKAH ST		CLAIM ORIGIN	WEB
MINONG, WI 54859		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVPB1TB941913
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$165.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT25RBS
		DEALER RO #	40250
		CLAIM START DATE	03/12/2026
		CLAIM END DATE	04/09/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor			
Line# 1	Operation Code	Operational Description	
	20-73-15-00-000745	Wheel Well Trim - Exterior/Fender Skirts/Wheel Well/Repair or Replace/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : alix@dealer-advisors.com, 2026-03-12 11:28:03 :: Complaint: Dealer states fabric above ODS front tire is ripped. Cause: Debris from tire cause holes in fabric above tire. Correction: Replace fabric.		
Model#	Dlr Sub Hrs	1.20	Sub Labor Amt \$198.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$16.50
	Notes		
	The time requested is excessive for this repair, time adjusted. NVCB .10 to use darco tape to cover. Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp		

Line# 2	Item #		Description			
	F100697246		67.75"X360' WOVEN BLK WOVEN UNDERBELLY, 871011			
	Model #		Serial #		Part tag	
	Sub Qty	2.00	Sub Dlr Price	\$1.38	Sub Freight	\$113.84
	Appr Qty	2.00	Appr Dlr Price	\$1.38	Appr Freight	\$113.84
	Notes					

Line# 2	Operation Code		Operational Description	
	20-44-19-00-000553		Roof Moldings - Front or Rear - Exterior/Roof/Reseal/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : alix@dealer-advisors.com, 2026-03-12 11:29:39 :: Complaint: Dealer states the roof needs to be sealed in some spots. Cause: Missed sealant from manufacturer. Correction: Applies white quad around both extrusions on the rear of the unit.			
	Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$49.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$49.50	
Notes				
NVCB .30 to use sealant to fill in and cover the seal voids on the entire roof membrane. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.				

Line# 1	Item #	Description				
	USERPART	shop supplies - sealant				
	Model #	Serial #			Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$2.48	Sub Freight	\$0.00

Appr Qty	1.00	Appr Dlr Price	\$2.48	Appr Freight	\$0.00
Notes					

Labor

Line# 3	Operation Code	Operational Description			
	30-99-01-00-001014	Mini-Blind or Vertical Patio Blind Wand - Interior/Soft Goods/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : alix@dealer-advisors.com, 2026-03-12 11:31:24 :: Complaint: Dealer states the blind above the stove is missing the plastic wand. Cause: Missing stick to turn the blinds. Correction: Replace blind wand.				
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$49.50		
Serial#	Appr Hrs	0.01	Appr Labor Amt \$1.65		
	Notes				
	The time requested is excessive for this repair, time adjusted. NVCB .01 to replace the missing wand. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.				

Part

Line# 1	Item #	Description			
	30I42148A	WAND , ALUMINUM BLINDS , 12", (MFG# WAND), 9475			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$0.33	Sub Freight \$113.84
	Appr Qty	1.00	Appr Dlr Price	\$0.33	Appr Freight \$113.84
	Notes				

Labor

Line# 4	Operation Code	Operational Description			
	30-99-24-00-001015	Mini-Blind - Interior/Soft Goods/Repair/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : alix@dealer-advisors.com, 2026-03-12 11:32:23 :: Complaint: Dealer states blind in slide out, closest to rear does not stay up. Cause: Loose string. Correction: Unscrewed string, moved knot up, tested and clipped excess string.				
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt \$66.00		
Serial#	Appr Hrs	0.10	Appr Labor Amt \$16.50		
	Notes				
	Changed to the correct code. Dp.				
	The time requested is excessive for this repair, time adjusted. NVCB .10 to tighten the string tensioners on the blind due to it being loose. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.				

Labor

Line# 5	Operation Code	Operational Description			
	30-102-01-00-001101	Slide Out Fascia, each section - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : alix@dealer-advisors.com, 2026-03-12 11:34:35 :: Complaint: Dealer states decorative fascia, trim on slide out is peeling. Cause: Horizontal top fascia trim has nick and peeling laminet. Weather protectant fascia board wrap for lack fo a proper term is protruding from the top of the trim. Correction: Remove and replace fascia trim and cut and hide fascia wrap.				
Model#	Dlr Sub Hrs	1.30	Sub Labor Amt \$214.50		
Serial#	Appr Hrs	1.00	Appr Labor Amt \$165.00		
	Notes				
	Why can this not be repaired? Thank you Dp.				
	Because it is paper glued to a board and the paper is ripped. Thanks.				
	The time requested is excessive for this repair, time adjusted. NVCB 1.00 to R&R the top slide out fascia due to it peeling. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.				

Part

Line# 1	Item #	Description		
	F100766940	MM STILE MDF SE 3/8X5-1/2X169 IZZY GRANITE 45G, 47092208		
	Model #	Serial #	Part tag	

Sub Qty	1.00	Sub Dlr Price	\$22.54	Sub Freight	\$113.84
Appr Qty	1.00	Appr Dlr Price	\$22.54	Appr Freight	\$113.84

Notes

Labor

Line# 6

Operation Code
60-136-15-00-001499

Operational Description
Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code

Complaint, Cause, Correction
Original Note : alix@dealer-advisors.com, 2026-03-12 11:36:21 :: Complaint: Dealer states shower doesn't work on hot or cold, possibly clogged. Cause: Construction debris clogged shower. Correction: Removed shower head, hit with pressurized hose from both ends, reattached and it works as it should. There was a noticeable amount of debris in waste tank that was apparent after draining.

Model#	Dlr Sub Hrs	0.90	Sub Labor Amt	\$148.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$16.50

Notes

The time requested is excessive for this repair, time adjusted. NVCB .10 to remove the debris from the shower head. Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp

Labor

Line# 7

Operation Code
40-197-01-11-001320

Operational Description
Exterior Recept - Electrical/110 Volt Exterior/Replace/Electrical

Complaint, Cause, Correction
Original Note : alix@dealer-advisors.com, 2026-03-12 11:38:04 :: Complaint: Dealer states that the plastic cover for 30 amp plug-in is broken. Cause: From manufacturer. Opened 30amp plug to provide power, cover came off. Receptacle is broken at the hinge. Correction: Replace receptacle.

Model#	Dlr Sub Hrs	0.80	Sub Labor Amt	\$132.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$82.50

Notes

The time requested is excessive for this repair, time adjusted. NVCB .50 to R&R the shore cord recept due to it being cracked. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1

Item #	Description			
F100371675	INLET, 30A, FOR POWER CORDS, 803EZ-A-SQBK			
Model #	Serial #	Part tag	0000409254	
Sub Qty	1.00	Sub Dlr Price	\$25.34	Sub Freight
Appr Qty	1.00	Appr Dlr Price	\$25.34	Appr Freight
				\$113.84

Notes

Submitted	Labor Amt	\$858.00	Approved	Labor Amt	\$348.15
	Parts & Freight	\$507.43		Parts & Freight	\$507.43
	Total	\$1,365.43		Total	\$855.58

DEALER _____ DATE _____

SIGNATURE _____

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE _____

All repairs described have been inspected and are satisfactory.