



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26581



WO #: 26581

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:  
 Author: S.DAVIS  
 Location: IH  
 Invoice #:

Stock #: 11251  
 Stock Desc: 2026 FW FOREST RIVER  
 SANDPIPER 3844QUAD  
 Model: 3844QUAD  
 Serial #: 4X4FSAP21TJ049010  
 Chassis #:  
 Mileage:0  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date:  
 Date In: 23 DEC 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 24 FEB 26  
 Warr. Date:

**Job #1 - Warranty**

COMPLAINT: DOOR SIDE REAR COMPARTMENT DOOR IS NOT CLOSING CORRECTLY

CAUSE: NOTED ON DAF  
 COMPARTMENT DOOR IS HITTING THE SIDE OF THE OPENING ON THE UNIT WHEN YOU CLOSE IT

CORRECTION: ADJUST COMPARTMENT DOOR  
 LABOR .50

**Labor**

Job #	Description	Hours	Total
1	ADJUSTED DOOR	0.20	33.00
<b>Subtotal for Job #1:</b>			<b>33.00</b>

**Job #2 - Warranty**

COMPLAINT: LIGHT OVER THE ENTRY DOOR IS NOT STRAIGHT

CAUSE: NOTED ON DAF

CORRECTION: RESECURE LIGHT IN PROPERLY AND STRAIGHT THEN RESEAL AROUND LIGHT  
 LABOR .30

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: THERE IS A PAINT CHIP ON THE FRONT CAP OF THE UNIT

CAUSE: NOTED ON DAF

CORRECTION: AREA NEEDS TO BE CLEANED AND TAPED OFF, LIGHTLY SAND, PRIME, REPAINT  
 AFFECTED AREA TO MATCH UNIT. ALLOW PAINT TO CURE, THEN LIGHTLY BUFF AND POLISH  
 LABOR 3.5

**Labor**

Job #	Description	Hours	Total
3	REPAINTED AREA	3.50	577.50

Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,



**Other Services**

Code	Description	Qty	Price	Total
NII	SHOP SUPPLIES FOR REPAIR	1.00	20.00	20.00

**Subtotal for Job #3: 597.50**

**Job #4 - Warranty**

COMPLAINT: DRAWER IN BEDROOM IS SPLITTING ON THE SIDE AND HAS A CHIP

CAUSE: NOTED ON DAF

CORRECTION: REPLACE DRAWER WITH NEW ONE  
 REMOVE AND REINSTALL DRAWER GUIDES ON BOTH SIDES  
 LABOR .50

**Labor**

Job #	Description	Hours	Total
4	INSTALLED DRAWER GUIDE	0.30	49.50

**Parts**

Part #	Description	Qty	Price	Total
F100608770	DRAWER FRONT, MATTE HAZE, 0.75" X 10.5" X 28.5"	1.00	44.29	44.29

**Other Services**

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	5.00	5.00

**Subtotal for Job #4: 98.79**

**Job #5 - Warranty**

COMPLAINT: THE 2ND DRAWER DOWN IN THE BEDROOM WILL NOT CLOSE

CAUSE: NOTED ON DAF  
 DRAWER GUIDES ARE FAULTY

CORRECTION: REPLACE DRAWERS GUIDES  
 LABOR .30

**Labor**

Job #	Description	Hours	Total
5	REPLACED GUIDES	0.20	33.00

**Parts**

Part #	Description	Qty	Price	Total
F100609867	DRAWER GUIDE 12"; CABINET SIDE	1.00	2.70	2.70
F100609869	DRAWER GUIDE 16"; CABINET SIDE	1.00	3.24	3.24

**Subtotal for Job #5: 38.94**

**Job #6 - Warranty**

COMPLAINT: INTERIOR DOOR TRIM IS DAMAGED. TRIM IS BUBBLING UP IN PLACES AND HAS HOLES ACROSS IT THAT ARE DEEP


CAUSE: NOTED ON DAF  
 DAMAGED AT FACTORY INSTALL

CORRECTION: REMOVE CURRENT TRIM AND REPLACE WITH NEW, COLOR AND FILL IF NEEDED  
 LABOR .40

**Labor**

Job #	Description	Hours	Total
6	REPLACED INTERIOR DOOR TRIM	0.20	33.00

**Parts**



Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,



Part #	Description	Qty	Price	Total
F100635860	DOOR CASING, 1 1/4" X 3.42" X 97" FRINTON SAND (41204) 2025- / 47090414	1.00	19.37	19.37

**Other Services**

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	191.02	191.02

**Subtotal for Job #6: 243.39**

**Job #7 - Warranty**

COMPLAINT: FASCIA IN THE BEDROOM IS SCRATCHED AT THE TOP

CAUSE: NOTED ON DAF  
SCRATCHED AT INSTALL

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

**Labor**

Job #	Description	Hours	Total
7	FILL COLOR AND BLEND	0.30	49.50

**Subtotal for Job #7: 49.50**

**Job #8 - Warranty**

COMPLAINT: LIVING AREA FASCIA HAS RED MARKS ACROSS THE TOP AND PLACES THAT ARE CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA THAT HAS THE RED SPOTS THEN FILL, COLOR AND BLEND AREA  
LABOR .30

**Labor**

Job #	Description	Hours	Total
8	REPAIRED AREA	0.30	49.50

**Subtotal for Job #8: 49.50**

**Job #9 - Warranty**

COMPLAINT: UNIT HAS MULTIPLE AREAS OF DULL PAINT FINISH THAT DOES NOT MATCH THE SURROUNDING PANELS.AFFECTED AREAS LACK PROPER GLOSS AND CLARITY COMPARED TO THE REST OF THE PAINT JOB.THESE AREAS ARE NDS MIDDLE OF UNIT, OVER REAR DOOR AREA AND AT FRONT COMPARTMENT DOOR

CAUSE: PAINT FINISH INCONSISTENCY RESULTING IN DULL APPEARANCE AND GLOSS MISMATCH

CORRECTION: AREAS NEED TO BE REFINISHED, RESTORE PROPER GLOSS AND ENSURE PAINT FINISH MATCHES PANELS.  
LABOR 4.5

**Labor**

Job #	Description	Hours	Total
9	REPAIRED AREA	4.50	742.50

**Subtotal for Job #9: 742.50**



Customer #: 47602  
TRI-LAM RV CENTER-EAST  
TN,



Parts Total: 69.60  
Labour Total: 1,567.50  
Sublet Total: 0.00  
Extras Total: 216.02  
**WORK ORDER TOTAL: 1,853.12**

W/O: 26581

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 24 Feb 2026

Customer Signature : \_\_\_\_\_

Customer Work  
Order



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

