BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville IN
US
47725
812-867-5200

WORK ORDER # 66186

Completed :	17 JAN 22	Customer :	1013 - KEYSTONE RV CO -
Licence # :		Invoice # :	
Stock No :	10976	Description :	2021 5W KEYSTONE COUGAR 354FLS
Tag :		Date In :	27 DEC 21 Mileage : 0
Author :	BH	Promised :	
Location :	0120 CHECK WORK	Date Sched :	
Serial# :	4YDFCGS27N2503252	Chassis# :	4YDFCGS27N2503252
Warr. Date :		Cust PO# :	
Print Date :	17 JAN 22		

****

Job #	Description	JOB INFORMATION	Type	Bill	To
PDIN	COMPLAINT:	PDI - NEW FIFTH WHEEL	I	PDI	PRE-D
	CAUSE:	pdi unit and rewinterized unit 2 GALLONS OF ANTIFREEZE			
	CORRECTION:	pdi unit and rewinterized unit 2 GALLONS OF ANTIFREEZE			
1	COMPLAINT:	NAIL IN TIRE R/R	I	SPN	SALES
	CORRECTION:	REPAIRED TIRE ON RIGHT REAR.			
2	COMPLAINT:	BATHROOM DOOR NEEDS ADJ	W	1013	KEYST
	CAUSE:	adjusted the screws on the door			
3	COMPLAINT:	WIRES HANGING OUT OF BOTTOM OF COUCH	W	1013	KEYST
	CAUSE:	removed the bottom of couch to get to the wires then ziptied them and put the couch back together			
4	COMPLAINT:	50 AMP 120V PLUG IS MISSING COVER	W	1013	KEYST
	CAUSE:	put in PO for new plug 1-4-22 REMOVED BROKEN SHORE PLUG INSTALLED NEW SHORE PLUG 1-7-22			
5	COMPLAINT:	BLIND ABOVE TABLE WILL NOT CLOSE ALL THE WAY	W	1013	KEYST
	CAUSE:	put in PO for the proper size blind.THE NEW BLIND IS THE SAME SIZE BUT WRONG MATERIAL SAME COLOR BLIND IS INSTALLED 1-17-22			
6	COMPLAINT:	FR COMPARTMENT DOOR WONT LATCH	W	1013	KEYST
	CAUSE:	added shims and moved striker plate door works as should			
7	COMPLAINT:	TOWEL RACK IN BATHROOM NEEDS FIX	W	1013	KEYST
	CAUSE:	moved screws till it held			

****

Job #	Part No	Description PARTS	Bill to	Qty	Price	Total
4	380642	50 AMP INLET - BLA	W-1013	1	42.63	42.63
5	609080	50X37 BLACK SHADE	W-1013	0	27.14	0.00

Continued on page 2

Work Order : 66186

Job #	Part No	Description PARTS	Bill to	Qty	Price	Total
5	658159	50X38 ROLLER SHADE	W-1013	1	67.52	67.52

Job#	Lab Code	Description LABOUR	Mech	Bill to	Hrs	Rate	Total
DINFW	Z991	PDI NEW FIFTH WHEEL (I	SAR	I-PDI	2.28	130.00	296.40
DINFW	Z991	PDI NEW FIFTH WHEEL (I	SAR	I-PDI	3.72	130.00	483.60
1	Z990	MISC LABOUR CODE (EXTE	GAH	I-SPN	0.50	25.00	12.50
2	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.20	150.00	30.00
3	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.20	150.00	30.00
4	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.00	150.00	0.00
4	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.01	150.00	1.50
5	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.40	150.00	60.00
5	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.00	150.00	0.00
5	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.00	150.00	0.00
6	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.20	150.00	30.00
7	Z990	MISCELLANEOUS REPAIR	SAR	W-1013	0.10	150.00	15.00

Job #	Excode	Description EXTRAS	bill to	Qty	Price	Total
DINFW	SS	SHOP SUPPLIES	I-PDI	1.00	35.00	35.00
DINFW	LP20	20 LB. LP CYLINDER	I-PDI	2.00	14.00	28.00
4	FRT	UPS-JOBS 4,5	W-1013	1.00	36.91	36.91

CUSTOMER COMMENTS

SHADE ORDERED (#658159) IS CORRECT AND THE ONLY MATERIAL
CURRENTLY AVAILABLE. SHADES HAVE BEEN AND STILL ARE A
PROBLEM. RUNNING CHANGES ARE MADE FREQUENTLY. PER NIKKI VIA PHONE
1-14-22 @ 2:58 P.M. THIS NEW MATERIAL IS THE ONLY THING
AVAILABLE.1-14-22
SHADE AND RECEPT IN BACKROOM 1-7-22...CAM
GAVE MATT PARTS SHEET
BH GOT APPROVEL
BH SENT IN FOR APPROVEL 1-4
ORDERED PARTS... GAVE BEN ORDER SHEET TO GET APPROVAL. 1-4-22

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	0.00	780.00	0.00	63.00	0.00	843.00
I	SPN	0.00	12.50	0.00	0.00	0.00	12.50
W	1013	110.15	166.50	0.00	36.91	0.00	313.56
	Totals	110.15	959.00	0.00	99.91	0.00	1,169.06

Continued on page 3

Work Order : 66186