GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 14078

Date In:	09 SEP 26	Author:	DMCGINLEY
Promised Date:	10 SEP 26	Stock No:	11642
:		Year:	2027
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	FLAGSTAFF SUPER-LITE T
:	CHICAGO, IL	Model:	26FKBS
Postal/Zip:	60673-1218	Miles/Hrs:	
Phone#(res):	219-534-3167	Exterior Color:	
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	NONE	Tag#:	
Purchased Date:	24 JUN 26	:	
Delivery Date:	08 JUL 26	:	
InService Date:		:	
Serial#:	4X4TFLB22VZ202489	:	

Job #		JOB INFORMATION	Type	Bill To	
1	COMPLAINT:	CUSTOMER STATES MAXAIR FAN ABOVE STOVE IS WAY LOUDER THAN BATHROOM FAN	W	1021	FORES
	CAUSE:	Test max air fan for operation. Customer says it louder than the bathroom fan. Checking to see if we can get a different motor only. The motor has a gear driven sound to it. The one in the bathroom don't.			
	CORRECTION:	REQ: NEW MAXAIR FAN AND .50 TIME			
2	COMPLAINT:	CUSTOMER STATES AWNING FABRIC IS PULLING AND NOT STRAIGHT IS CORKSCREWING WHILE COMING IN	W	1021	FORES
	CAUSE:	Check awning fabric. Has wrinkles when rolling.			
	CORRECTION:	Tried pulling fabric at the back of track tight. Didn't help much. Just all long tube that makes the fabric loose in the middle will cause some wrinkles when rolling up. Needs more sun time to help wrinkles out. Also adjusted front awning arm over so it doesn't hang up when rolling out. REQ: 2 HOURS			
3	COMPLAINT:	DRAWER UNDER BED ON RIGHT SIDE DOESNT WANT TO CLOSE WITHOUT SOME FOOLING AROUND, NEEDS ADJUSTMENT	W	1021	FORES
	CAUSE:	Drawer adjustment under bed right side.			
	CORRECTION:	Adjusted glides for drawer to operate better. Left hand glide wasn't working			

Continued on page 2

Work Order : 14078

Job #	Description	JOB INFORMATION	Type	Bill To	
		properly. Glides are soft close. REQ: .50			
4	COMPLAINT:	LOW POINT DRAINS HAD A LEAK SO CUSTOMER TIGHTENED CAP/CRIMP, WOULD LIKE US TO DOUBLE CHECK THAT EVERYTHING WAS FIXED PROPERLY	E	16319	SCHLI
	CAUSE:	Check low points for leaks.			
	CORRECTION:	One of the caps needed a rubber gasket. Tested good. REQ: .25			
5	COMPLAINT:	CUSTOMER STATES THE KITCHEN WATER PRESSURE IS JUST ABOUT NOTHING COMPARED TO THE BATHROOM SINK WATER PRESSURE	W	1021	FORES
	CAUSE:	Check kitchen faucet for pressure.			
	CORRECTION:	Was a little slow. Just removed the restricter. Has better flow. REQ: .25			
RI	COMPLAINT:	PREFORM ROOF INSPECTION AND ADVISE IF REPAIR IS NEEDED.	I	PD	GOODW
	CAUSE:	Roof inspection.			
	CORRECTION:	All looks good.			
6	COMPLAINT:	LITTLE FLAKES OF INSULATION IN PANTRY RIGHT HAND CORNER, CUSTOMER DOES HAVE MOUS TRAPS AND SUCH IN CASE IT IS A MOUSE, WOULD LIKE US TO SEE WHAT IT COULD BE	W	1021	FORES
	CAUSE:	Snow ball insulation from Styrofoam. Can move around in unit when traveling.			
	CORRECTION:	Just loose deposits from cut outs in exterior wall. Also put seam tape on ceiling in pantry. REQ: .03			

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
1	DIAG	DIAGNOSTICS		TD	W-1021	0.00	140.00	0.00
2	DIAG	DIAGNOSTICS		TD	W-1021	0.01	140.00	1.40
3	DIAG	DIAGNOSTICS		TD	W-1021	1.00	140.00	140.00
4	DIAG	DIAGNOSTICS		TD	E-16319	0.85	130.00	110.50
5	DIAG	DIAGNOSTICS		TD	W-1021	0.97	140.00	135.80
RI	RI	ROOF INSPECTION		TD	I-PD	0.30	70.00	21.00
6	DIAG	DIAGNOSTICS		TD	W-1021	1.00	140.00	140.00
1	DIAG	DIAGNOSTICS		TD	W-1021	0.49	140.00	68.60
4	DIAG	DIAGNOSTICS		TD	E-16319	0.15	130.00	19.50
2	DIAG	DIAGNOSTICS		TD	W-1021	0.99	140.00	138.60
5	DIAG	DIAGNOSTICS		TD	W-1021	0.03	140.00	4.20
6	Z990	TAPE CEILING PIECE IN		TD	W-1021	0.03	140.00	4.20
2	DIAG	DIAGNOSTICS		TD	W-1021	1.00	140.00	140.00
1	RV2-17	VENT INSTALL MAXAIRE (		TD	W-1021	0.00	140.00	0.00
1	RV2-17	VENT INSTALL MAXAIRE (		TD	W-1021	0.45	140.00	63.00

Continued on page 3

Work Order : 14078

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
4	SSE	SHOP SUPPLIES - EXTERNAL		E-16319	1.00	9.75	9.75

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
E	16319	0.00	130.00	0.00	9.75	7.71	147.46
I	PD	0.00	21.00	0.00	0.00	0.00	21.00
W	1021	0.00	835.80	0.00	0.00	0.00	835.80
	Totals	0.00	986.80	0.00	9.75	7.71	1,004.26

&k2S
&k0S