GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 14025

Date In:	28 AUG 26	Author:	DMCGINLEY
Promised Date:	31 DEC 26	Stock No:	11708
:		Year:	2027
Customer Name:	1021 - FOREST RIVER	Manufacturer:	FOREST RIVER
Address:	21815 NETWORK PLACE	Brand:	PUMA DESTINATION
:	CHICAGO, IL	Model:	38RLB
Postal/Zip:	60673-1218	Miles/Hrs:	0
Phone#(res):	219-534-3167	Exterior Color:	
Phone#(bus):	219-534-3167	Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	NONE	Tag#:	
Purchased Date:		:	
Delivery Date:		:	
InService Date:		:	
Serial#:	4X4TPUP29VP110383	:	

Job #	Description	JOB INFORMATION	Type	Bill To	
NTTS	NEW TRAVEL TRAILER STOCK PREP		I	PDI	PRE-D
CEN	CLEAN EXTERIOR- NEW		I	PDI	PRE-D
WS	WINTERIZE WATER SYSTEM & TRAPS -SELF CONTAINED - TOWABLE		E	1000	GREEN
WARR	WARRANTY REPAIR 1 - Both DS and ODS rear windows are stuck shut		W	1021	FORES
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Dining chair has black stains	W	1021	FORES
	CAUSE:	Stained			
	CORRECTION:	Used quick solve to remove black stains then went over that with fabric cleaner no more stain visable			
WARR	COMPLAINT:	WARRANTY REPAIR 3 - Patio door handle not locking with key	W	1021	FORES
	CAUSE:	Lock needed lubrication			
	CORRECTION:	Used lube and sprayed lick and latch well worked the lock until it was easier to latch and unlatch			
WARR	COMPLAINT:	WARRANTY REPAIR 4 - Bath vent the turn handle was on floor it's lost its screw	W	1021	FORES
	CAUSE:	Missing screw from mfg			
	CORRECTION:	I used a tiny rubber washer inserted in the handle hole and I took a screw filed end off and installed into receiving end of vent handle, tightened screw it now opened and closes and handle stays on . We did not have any screws like what was needed and that's why I filed the screw			

Continued on page 2

Work Order : 14025

Job #	Description	JOB INFORMATION	Type	Bill To	
		end off			
WARR	COMPLAINT:	WARRANTY REPAIR 5 -Metal shavings on lino , will damage lino	W	1021	FORES
	CAUSE:	Metal debris from mfg			
	CORRECTION:	Used vacuum to get metal shavings beneath slide fabric floor covering on all 4 slides and off lino			
WARR	WARRANTY REPAIR 6 - light marks on dark wood throughout unit		W	1021	FORES
WARR	COMPLAINT:	WARRANTY REPAIR 7 - Sides of bed platform have wood gouges both sides	W	1021	FORES
	CAUSE:	Mfg dragged staple gun along panel removing the finish			
	CORRECTION:	I mixed up putty to get a color match then filled the scratched areas with putty			
WARR	COMPLAINT:	WARRANTY REPAIR 8 -Corber of island has a gouge	W	1021	FORES
	CAUSE:	Chunk out of edge of island from dining chair when slide was in			
	CORRECTION:	I used putty to fill then used wood marker to blend			
WARR	COMPLAINT:	WARRANTY REPAIR 9 - floor has scratches in it	W	1021	FORES
	CAUSE:	Debris beneath lino some poking through and very sharp, dents in bedroom lino, cuts in floor , mfg did a lino repair and it was not done well it lays flat but it's very visable			
	CORRECTION:	14025REQUESTING TO REPAIR BY CUTTING LINO AND REMOVING DEBRI ,GLUE AND COVER CUT WITH FLOOR SEALANT AND PUTTY TO MAT H WITH FLOOR , TOUCHING UP MFG REPAIR TO MAKE LESS VISABLE , REQUESTING 2 HOURS FOR REPAIRING 11 SPOTS			

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
WS	009114950003	-50 F GLYCERIN FREE BASE		E-1000	0	7.60	0.00

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
NTTS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	0.00	70.00	0.00
CEN	CE	CLEAN EXTERIOR			I-PDI	0.00	70.00	0.00
NTTS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	2.42	70.00	169.40
WS	W495	WINTERIZE RV (WATER SY			E-1000	0.00	140.00	0.00
ARR01	Z992	MISC LABOUR CODE (WARR		HOD	W-1021	0.00	140.00	0.00

Continued on page 3

Work Order : 14025

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
ARR02	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.50	140.00	70.00
ARR03	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.41	140.00	57.40
ARR04	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.50	140.00	70.00
ARR05	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.27	140.00	37.80
ARR06	Z992	MISC LABOUR CODE	(WARR		W-1021	0.00	140.00	0.00
ARR07	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.50	140.00	70.00
NTTS	RV1F-1A	NEW STOCK PREP		HOD	I-PDI	0.17	70.00	11.90
ARR05	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.23	140.00	32.20
ARR08	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.50	140.00	70.00
ARR09	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.02	140.00	2.80
ARR09	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.48	140.00	67.20
ARR03	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.09	140.00	12.60
ARR01	Z992	MISC LABOUR CODE	(WARR	HOD	W-1021	0.07	140.00	9.80

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
WS	SSE	SHOP SUPPLIES - EXTERNAL		E-1000	1.00	0.00	0.00

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
I	PDI	0.00	181.30	0.00	0.00	0.00	181.30
W	1021	0.00	499.80	0.00	0.00	0.00	499.80
	Totals	0.00	681.10	0.00	0.00	0.00	681.10

&k2S
&k0S