MYERS RV CENTER
SALES ★ PARTS ★ SERVICE

12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72933-1
Promised Date: 30 OCT 26

WO #: 72933-1
Customer Name: 1000 - MYERS "RV" CENTER, INC.

Completed Date: 29 OCT 26
Invoice#:
Author: ADVISOR
Stock Desc: 9672 2026 SANIBEL 34LOUNGE
Serial#: 706323
Chassis#: 5ZT3SNZB9TG706323
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 22 MAY 26
Time In:

Customer #: 1000
MYERS "RV" CENTER, INC.,

Job #1 - Warranty
COMPLAINT: Transferred to RV*72933-2 on 29 OCT 26
Estimate amount was 0.00
SHADE IN UPPER BEDROOM INOP (STUCK OPEN)

CAUSE: The shade will not retract. Will not stay up if you manually roll it up.
Mechanisms inside have malfunctioned, not allowing any shade to operate, correct

CORRECTION: Found in the front bedroom had been pulled down would not go back up while inspecting another job attempted to manually roll it up would not roll up and stay up
Attempted to adjust it so that it would operate correctly and would not operate the mechanisms inside the roller of malfunctioned
The shade needs to be replaced
Requesting a total of 15 minutes for the removal and reinstall and testing

Labor

Job #	Description	Total
1	SHADE	0.00

Subtotal for Job #1: 0.00

Job #01 - Warranty
COMPLAINT: CHIPPED FIBERGLASS BY LEFT TAIL LIGHT (DRIVERS SIDE)

CAUSE: Damaged

CORRECTION: Sublet jib

Labor

Job #	Description	Total
01	MULTIPLE LABOR CODES	47.50

Sublet


Description	Total
FIBERGLASS REPAIR	582.00

Subtotal for Job #01: 629.50

Job #02 - Warranty
COMPLAINT: Found the entry step handle was missing a bolt from the bottom.

© 2026 Integrated Dealer Systems





CAUSE: Missing bolt

CORRECTION: Added new bolt

Labor

Job #	Description	Total
02	MULTIPLE LABOR CODES	19.00

Subtotal for Job #02: 19.00

Job #03 - Warranty
COMPLAINT: STRICKER PLATE NEEDS ADJUSTED

CAUSE: Out of adjustment

CORRECTION: Realigned striker plate door works correctly job complete

Labor

Job #	Description	Total
03	MULTIPLE LABOR CODES	38.00

Subtotal for Job #03: 38.00

Job #04 - Warranty
COMPLAINT: CLOSET DOOR NEEDS ADJUSTED

CAUSE: Out of alignment

CORRECTION: Realigned the closet doors for proper operation

Labor

Job #	Description	Total
04	MULTIPLE LABOR CODES	38.00

Subtotal for Job #04: 38.00

Job #05 - Warranty
COMPLAINT: VENT BROKEN CEILING A/C VENT

CAUSE: Broken

CORRECTION: Removed and replaced vent

Labor

Job #	Description	Total
05	MULTIPLE LABOR CODES	38.00

Parts

Part #	Description	Qty	Price	Total
55-5321	HEATING/COOLING REGISTER - POLAR WHITE	1.00	7.68	7.68

Subtotal for Job #05: 45.68

Job #06 - Warranty
COMPLAINT: PUSH BUTTON ON LIGHT COVER MISSING

CAUSE: Broken

CORRECTION: Replaced with new one

Labor

Job #	Description	Total
06	MULTIPLE LABOR CODES	5.70

Parts

Part #	Description	Qty	Price	Total

Customer Work Order

© 2026 Integrated Dealer Systems



F100350971	3.5" MUSHROOM LIGHT, ULTRA BRIGHT / SWITCH	1.00	1.82	1.82

Subtotal for Job #06: 7.52

Job #07 - Warranty
COMPLAINT: FRONT PANEL IS LOOSE

CAUSE: Panel came in-stapled

CORRECTION: Restapled and puttied

Labor

Job #	Description	Total
07	MULTIPLE LABOR CODES	19.00

Subtotal for Job #07: 19.00

Job #08 - Warranty
COMPLAINT: CO AX CABLE PULLED OUT OF THE END OF TV

CAUSE: Pulled apart

CORRECTION: Replaced cable with new

Labor

Job #	Description	Total
08	MULTIPLE LABOR CODES	19.00

Subtotal for Job #08: 19.00

Job #09 - Warranty
COMPLAINT: TRIM CAME OFF IN BEDROOM AT FLOOR ON THE SLIDE

CAUSE: Came loose

CORRECTION: Renailed and puttied

Labor

Job #	Description	Total
09	MULTIPLE LABOR CODES	19.00

Subtotal for Job #09: 19.00

Job #J - Warranty
COMPLAINT: Fires place remote missing

CAUSE: MISSING FROM UNIT

CORRECTION: Found the remote for the fireplace is missing
Need to order parts

Labor

Job #	Description	Total
J	MISC LABOUR CODE (WARRANTY)	0.00

Parts

Part #	Description	Qty	Price	Total
F100884885	REMOTE, FOR 60" FIREPLACE	1.00	31.03	31.03

Subtotal for Job #J: 31.03

Job #K - Warranty
COMPLAINT: SUBWOOFER MISSING

CAUSE: Missing

Customer Work Order

© 2026 Integrated Dealer Systems

CORRECTION: Factory sent total replacement subwoofer and sound bar replace the sound bar with a new sound bar scent box up the old sound bar set the subwoofer in place attached it to their mounting brackets job is now complete

Labor

Job #	Description	Total
K	MULTIPLE LABOR CODES	38.00

Parts

Part #	Description	Qty	Price	Total
F100793013	BAR, SOUND W/SUB WOOFER - DRSB-SW30-G	1.00	178.02	178.02

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	20.61	20.61

Subtotal for Job #K: 236.63

Parts Total:	218.55
Labour Total:	281.20
Sublet Total:	582.00
Extras Total:	20.61
WORK ORDER TOTAL:	**1,102.36**

Customer Work Order

NOTICE

Due to limited storage space, a storage fee of $15 per calendar day will be charged if the unit is not picked up within 48 hours after the customer is notified that the work is complete.

Effective January 12, 2026, a 3% surcharge will be applied to all credit card transactions.

MANUFACTURER WARRANTIES AND SERVICE CONTRACTS MAY NOT COVER DIAGNOSTIC TIME WHEN NO COVERED PROBLEM OR DEFECT IS FOUND. THE CUSTOMER IS RESPONSIBLE FOR ANY DIAGNOSTIC CHARGES NOT PAID BY THE MANUFACTURER OR SERVICE CONTRACT PROVIDER.

FREEZE
DAMAGE AND WINTERIZATION

The customer is responsible for ensuring that the unit is properly winterized before leaving it with Myers RV Center, Inc. Myers RV Center, Inc. is not responsible for freeze damage to the unit or to its plumbing, water, appliance, or related systems while the unit is awaiting service, undergoing service, awaiting parts, or awaiting pickup.

If the customer wants
Myers RV Center, Inc. to winterize the unit, the customer must submit the request by text message to the Service Department and receive confirmation that the request has been received and accepted. A verbal request is not sufficient and will not be considered authorization to perform winterization. Winterization is a separate, billable service and will not be performed automatically. Myers RV Center, Inc. is not responsible for freeze damage occurring before the requested winterization service has been completed.

LOSS OR DAMAGE

Although Myers RV Center, Inc. takes reasonable precautions to protect the unit while it is in our possession, we are not responsible for loss of or damage to the unit or its contents caused by fire, theft, severe weather, or any other cause beyond our reasonable control. Customers should remove or secure valuables, including firearms, cameras, jewelry, cash, and personal belongings, before leaving the unit for service.

AUTHORIZATION

I authorize Myers RV Center, Inc. to perform the repair work described in this work order and to furnish the parts and materials reasonably necessary to complete the authorized work. I understand that Myers RV Center, Inc. is not responsible for delays caused by parts availability, supplier or manufacturer delays, shipping delays, or other circumstances beyond its reasonable control.

I authorize Myers RV Center, Inc., its employees, and its authorized vendors to operate the vehicle on streets and highways when reasonably necessary for testing, inspection, diagnosis, transportation, or delivery to a subcontracted service provider.

I acknowledge an express mechanics lien on the vehicle described in this work order to secure payment for authorized repairs, parts, materials, storage fees, and other amounts lawfully due.

© 2026 Integrated Dealer Systems


Customer Signature : _____

Date: 29 Oct 2026

W/O: 72933-1
Promised Date: 30 OCT 26



Customer #: 1000
MYERS "RV" CENTER, INC.,



Customer Work Order

© 2026 Integrated Dealer Systems

