BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 71898
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 23873 - JEFF J. MEEKS
Address: 12429 S BROOKE DR HAUBSTADT, IN

47639
Phone: 812-632-0022
Stock Number: 11155 - 2023 COUGAR HALF-TON 33RLI 4YDTCGR28PV505313
VIN: 4YDTCGR28PV505313 HIN: SER#: 4YDTCGR28PV505313
Mileage: 0 Work Order Comp: 18 OCT 23
Auth. No: Dealer #: 1194
Warr. Date: 21 JUL 23 Work Order Date: 09 OCT 23 Inv #: 397554

WO #	Job #	Description	JOB INFORMATION
71898	4	THE SHOWER DOOR IS OUT OF ALIGNMENT . WATER RUNS OUT WHEN TAKING A SHOWER.	shower door took off doors and adjusted wheel on track all the way down,so door is not gapped open.
71898	6	WHEN THE BIG SLIDE ROOM ON THE DOOR SIDE IS IN AND YOU LOOK AT THE FRONT CORNER OF IT, YOU CAN SEE THAT THERE IS A METAL BRACKET THAT IS BENT OUT. CUSTOMER HAS BENT BRACKET OUT OF WAY SO THAT HE CAN STILL USE IT.	bracket bent took pics and took off bracket and bent back in place and reinstalled and 2 screws.
71898	7	THE 50AMP POWER PLUG DOOR ON THE OOF DOOR REAR SORNER OF THE TRAILER WILL NOT STAYY CLOSED.	50 amp plug door took out bottom screws and ground down and installed straight so door would not hit,now door latches.
71898	8	CUSTOMER ADVISES THAT THE SHOWER FLOOR IS VERY SOFT. CUSTOMER ADVISES THAT IT FEELS LIKE YOU COULD FALL THROUGHT THE FLOOR WHEN TAKING A SHOWER.	Soft Put blocking in the front of the shower floor pan.

Claim : 71898

WO #	Job #	Description	JOB INFORMATION
71898	9	THE FLOOR PANEL ON THE LEFT SIDE OF THE TOILET IS NOT SECURED PROPERLY.	floor panel took out panel and cut a piece of wood to mount behind it and screwed panel to it.
71898	10	THE BATHROOM DOOR IS OUT OF ADJUSTMENT. CUSTOMER THAT THE MAGNET AND THE STEEL PLATE WILL NOT COME CLOSE TO ATTACHING.	bathroom door took off top panel to get to adjusters,adjusted door flush and it will still not hit magnet,wall is sucked in to far,will half to take out trim and shim out.took off trim and shimed and put back together,shut door and now it latches,reinstalled header board.

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISCELLANEOUS REPAIR		0.20	160.00	32.00
Z990	6	MISCELLANEOUS REPAIR		0.20	160.00	32.00
Z990	7	MISCELLANEOUS REPAIR		0.20	160.00	32.00
Z990	8	MISCELLANEOUS REPAIR		0.50	160.00	80.00
Z990	8	MISCELLANEOUS REPAIR		0.00	160.00	0.00
Z990	9	MISCELLANEOUS REPAIR		0.20	160.00	32.00
Z990	10	MISCELLANEOUS REPAIR		0.20	160.00	32.00

Parts Total:	0.00
Labour Total:	240.00
Sublet Total:	0.00
Extras Total:	0.00
>>>>> Claim Total:	240.00

Customer Signature:_____ Date: _____