GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10928B

Date In:	12 AUG 24	Author:	MGRAY
Promised Date:	14 AUG 24	Stock No:	11102
:		Year:	2024
Customer Name:	13521 - WEGER, DARYL	Manufacturer:	FOREST RIVER
Address:	3954 E ARBOR LAKES	Brand:	PUMA DESTINATION
:	HERNANDO, FL	Model:	39FKL
Postal/Zip:	34442	Miles/Hrs:	0
Phone#(res):	608-579-1176	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	DMWEGS@YAHOO.COM	Tag#:	DEL@ST
Purchased Date:	01 AUG 24	:	
Delivery Date:	14 AUG 24	:	
InService Date:		:	
Serial#:	4X4TPUR20RP101400	:	

Job #	Description	JOB INFORMATION	Type	Bill To	
WARR	COMPLAINT:	WARRANTY REPAIR 1 - TOP AND BOTTOM DRESSER DRAWERS IN MASTER BEDROOM (ACROSS FROM BED) DO NOT CLOSE PROPERLY.	W	1021	FORES
	CAUSE:	MFG DEFECT WILL NEED TO ADJUST DRAWERS. WILL NEED .30 FOR REPAIRS			
	CORRECTION:	ADJUSTED DRAWERS AND GUIDES, DRAWERS NOW CLOSE PROPERLY.			
WARR	COMPLAINT:	WARRANTY REPAIR 2 - VENT RIGHT NEXT TO THE BED (RIGHTSIDE) BULDGES OFF OF THE WALL. NEEDS EXTRA SCREWS OR TO BE ADJUSTED.	W	1021	FORES
	CAUSE:	Mfg improper install, not secured correctly. WILL NEED .20 FOR REPAIRS.			
	CORRECTION:	Added 2 screws it now lays flat			
ISR0	COMPLAINT:	INTERNAL STOCK REPAIR 01 ods sofa the back has a hole in it	W	1021	FORES
	CAUSE:	Sofa back has a small rip in it Order new back of sofa .tag for sofa is in pictures. 55wide x 22 tall .WILL NEED .30 FOR REMOVAL AND REPLACEMENT OF SOFA			
	CORRECTION:	WILL NEED A NEW SOFA.			
ISR0	COMPLAINT:	INTERNAL STOCK REPAIR 02 ds sofa seat has a stain	W	1021	FORES
	CAUSE:	Silicone on the sofa cushions WILL NEED .30 FOR TIME SPENT CLEANING STAIN.			
	CORRECTION:	Cleaned off with quick solve Pics taken			
ISR0	COMPLAINT:	INTERNAL STOCK REPAIR 03. Positive	W	1021	FORES

Continued on page 2

Work Order : 10928B

Job #	Description	JOB INFORMATION	Type	Bill To	
		battery cable the end is missing			
	CAUSE:	Mfg did not correctly install the end it broke off. WILL NEED .50 FOR REPAIR.			
	CORRECTION:	Cut positive wire then crimped new end onto positive line and pulled to be sure it was crimped tightly it is then used electrical tape to secure more			
ISR0	COMPLAINT:	INTERNAL STOCK REPAIR 06 Dining area floor covering has a stain	W	1021	FORES
	CAUSE:	Stained floor covering from mfg. WILL NEED .30 FOR STAIN REMOVAL.			
	CORRECTION:	Used quick solve to remove stains Pics taken			
ISR0	COMPLAINT:	INTERNAL STOCK REPAIR 07 Water pump is weak and hardly no pressure coming out of. Interior shower head with the pump , other faucets are acceptable pressure but pump turns on and off many times when any faucet is on	W	1021	FORES
	CAUSE:	Low water pressure in int shower when using water pump. WILL NEED .40 FOR REPAIRS COMPLETED.			
	CORRECTION:	I adjusted water pump for more pressure , removed shower faucet to check if debris in lines doing both of these did absolutely nothing . changed shower hose the hole in hose for water to travel is a bit bigger still low pressure so I recommend use city water when showering you have good pressure then there are no leaks in line so I'm thinking the length water has to travel to shower line is a far distance and the water pump installed cannot give enough pressure to make water flow with pressure the way it's built			
ISR0	COMPLAINT:	INTERNAL STOCK REPAIR 08 Protruding nails throughout the unit	W	1021	FORES
	CAUSE:	Protruding nails that were never set. WILL NEED .30 TO SET ALL PROTRUDING NAILS.			
	CORRECTION:	Used nail set to set the nails			
ISR0	COMPLAINT:	INTERNAL STOCK REPAIR 09. Ods sliderooms top fascia board and the trim for ceiling of slideroom good sized gap between them	W	1021	FORES
	CAUSE:	Gap in trim WILL NEED .20 FOR REPAIR.			
	CORRECTION:	Used white silicone to fill cracks in slide out ceiling			

Continued on page 3

Work Order : 10928B

ISR1 COMPLAINT: INTERNAL STOCK REPAIR 10. Top and bottom W 1021 FORES
drawers in the bedrooms dresser do not
latch all of the way and they do not lay
flat against face of cabinetry
CAUSE: Mfg improper install. WILL NEED 1.5 TO
REMOVE, ADJUST AND REINSTALL ALL DRESSER
DRAWERS.
CORRECTION: Removed all drawers adjusted the frame
and glides then adjusted rails on side
of drawers they now open and completely
close as they should

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
ISR07	019079642578	HH SHW HOSE BK, 59, VINY		W-1021	1	9.30	9.30
ISR09	146877	NOVAFLEX SEALANT WHITE		W-1021	1	10.14	10.14

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
ARR01	Z992	MISC LABOUR CODE (WARR	HOD		W-1021	0.50	115.00	57.50
ARR02	Z992	MISC LABOUR CODE (WARR	HOD		W-1021	0.50	115.00	57.50
ARR02	Z992	MISC LABOUR CODE (WARR	HOD		W-1021	0.00	115.00	0.00
ISR01	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.49	115.00	56.35
ISR01	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.00	115.00	0.00
ISR01	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.01	115.00	1.15
ISR02	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.50	115.00	57.50
ISR02	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.00	115.00	0.00
ISR03	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.50	115.00	57.50
ISR03	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.00	115.00	0.00
ISR06	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.50	115.00	57.50
ISR06	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.00	115.00	0.00
ISR07	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.31	115.00	35.65
ISR07	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.00	115.00	0.00
ISR07	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.08	115.00	9.20
ISR07	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.11	115.00	12.65
ISR08	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.50	115.00	57.50
ISR08	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.00	115.00	0.00
ISR09	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.50	115.00	57.50
ISR09	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.00	115.00	0.00
ISR10	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.27	115.00	31.05
ISR10	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.00	115.00	0.00
ISR10	Z991	MISC LABOUR CODE (INTE	HOD		W-1021	0.23	115.00	26.45

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
ISR01	SSE	SHOP SUPPLIES - EXTERNAL		W-1021	1.00	0.00	0.00

Continued on page 4

Work Order : 10928B

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	1021	19.44	575.00	0.00	0.00	0.00	594.44
	Totals	19.44	575.00	0.00	0.00	0.00	594.44

&k2S
&k0S