FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0009497	**CLAIM STATUS**	Paid
GREENEWAY INC		**CLAIM**	2399996
DBA GREENEWAY RV SALES & SERVICE		**CLAIM ORIGIN**	WEB
8220 STATE HWY 13 SOUTH		**ORIGINAL CLAIM ID**	
WISCONSIN RAPIDS, WI 54494		**VIN**	4X4TPUS25SP104082
USA		**CHASSIS VIN**	
		MILEAGE	0
		SITE/WAREHOUSE	420 / 420
Labor rate:	$140.00	**ITEM #**	PUT401RLFT
OWNER INFORMATION		**DEALER RO #**	12409B
CRAIG A BEILKE		**CLAIM START DATE**	08/13/2025
4710 MESKER ST		**CLAIM END DATE**	11/18/2025
Schofield, WI 54476			
USA			
Retail Date of Purchase	08/14/2025	**WARRANTY EXPIRATION DATE**	08/14/2026

Claim Line Details

Labor

Line# 1

Operation Code
50-134-01-00-001467

Operational Description
LP Tank or Bottle Holder - Includes Leak Test - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2025-08-13 10:44:24 :: Complaint: The propane hold down is bent. Cause: From manufacturer. Correction: Replaced propane hold down .

Model#		**Dlr Sub Hrs**	0.30	**Sub Labor Amt**	$42.00
Serial#		**Appr Hrs**	0.30	**Appr Labor Amt**	$42.00

Notes

Part

Line# 1

Item #
USERPART

Description
0602.1161 hold-down bar heavy duty

Model #		**Serial #**		**Part tag**	
Sub Qty	1.00	**Sub Dlr Price**	$7.36	**Sub Freight**	$0.00
Appr Qty	1.00	**Appr Dlr Price**	$7.36	**Appr Freight**	$0.00

Notes

Line# 2

Item #
USERPART

Description
0605.3066 LP threaded rod 1/2" 30 LB 23 1/2"

Model #		**Serial #**		**Part tag**	
Sub Qty	1.00	**Sub Dlr Price**	$10.92	**Sub Freight**	$0.00
Appr Qty	1.00	**Appr Dlr Price**	$10.92	**Appr Freight**	$0.00

Notes

Labor

Line# 2

Operation Code
50-134-01-00-001442

Operational Description
LP Tank or Bottle - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2025-08-13 10:46:31 :: Complaint: One of the propane tanks, the handle got bent in and is into the tank. Cause: Came this way from manufacturer. Correction: Both tanks had a dent so we replaced both tanks. Additional Note : greeneway@dealer-advisors.com, 2025-11-18 11:42:56 :: Took tanks from stock unit. No part to claim.

Model#	1	**Dlr Sub Hrs**	0.30	**Sub Labor Amt**	$42.00

Serial#	1	**Appr Hrs**	0.20	**Appr Labor Amt**	$28.00

Notes
flat rate

Labor

Line# 3

Operation Code	**Operational Description**
50-134-01-00-001443	LP Regulator - Includes Leak Test - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2025-08-13 10:47:46 :: Complaint: Propane regulator has a leak. Cause: From manufacturer. Correction: Replace regulator.

Model#		**Dlr Sub Hrs**	0.70	**Sub Labor Amt**	$98.00
Serial#		**Appr Hrs**	0.50	**Appr Labor Amt**	$70.00

Notes
flat rate ,includes leak test
Part Return Required. Please attach tracking information. Part will be processed when received.
1Z03RW629005872808
Thank you for the tracking information. Claim will be processed once part is received. Please leave on your side.

Part

Line# 1

Item #		**Description**			
USERPART		MECMEGR-253 2 Stage Excela-Flo auto change over regulator			
Model #		**Serial #**		**Part tag**	0000391665
Sub Qty	1.00	**Sub Dlr Price**	$79.64	**Sub Freight**	$0.00
Appr Qty	1.00	**Appr Dlr Price**	$79.64	**Appr Freight**	$0.00

Notes

Labor

Line# 4

Operation Code	**Operational Description**
20-68-01-00-000695	Patio Screen Door - Exterior/Patio Doors/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : greeneway@dealer-advisors.com, 2025-08-13 10:48:59 :: Complaint: Screen door is bent. Cause: Bent from shipment/manufacturer. Correction: Replace patio door 30 inches wide by 71 1/2 inches tall.

Model#		**Dlr Sub Hrs**	0.30	**Sub Labor Amt**	$42.00
Serial#		**Appr Hrs**	0.20	**Appr Labor Amt**	$28.00

Notes
flat rate

Part

Line# 1

Item #		**Description**			
20X53515A		SCREEN DOOR, 30-1/8" X 71-5/8", 75PD BLACK RITE			
Model #		**Serial #**		**Part tag**	
Sub Qty	1.00	**Sub Dlr Price**	$53.13	**Sub Freight**	$164.34
Appr Qty	1.00	**Appr Dlr Price**	$53.13	**Appr Freight**	$164.34

Notes

Line# 2

Item #		**Description**			
420-C		CRATING			
Model #		**Serial #**		**Part tag**	
Sub Qty	1.00	**Sub Dlr Price**	$52.00	**Sub Freight**	$0.00
Appr Qty	1.00	**Appr Dlr Price**	$0.00	**Appr Freight**	$40.00

Notes
Forest River excludes the crating fee from mark-up considerations
Please put Crate fee in "Crate charge" area

Labor

Line# 5

Operation Code	**Operational Description**
30-100-01-00-001035	Cabinet Door - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-08-13 10:50:20 :: Complaint: Cabinet door in loft above the bathroom has a crack in it. Cause: Screw was over tightened. Correction: Replace door 24 in tall by 14 in wide.

Model#		**Dlr Sub Hrs**	0.40	**Sub Labor Amt**	$56.00
Serial#		**Appr Hrs**	0.40	**Appr Labor Amt**	$56.00

Notes

Part

Line# 1

Item #		**Description**			
F100448721		DOOR, CABINET, FLAT PANEL SQUARE, CHILLOUT DRIFT, 14 X 24			
Model #		**Serial #**		**Part tag**	
Sub Qty	1.00	**Sub Dlr Price**	$34.48	**Sub Freight**	$9.41
Appr Qty	1.00	**Appr Dlr Price**	$34.48	**Appr Freight**	$9.41

Notes

Labor

Line# 6

Operation Code	**Operational Description**
30-100-01-00-001035	Cabinet Door - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-08-13 10:51:19 :: Complaint: Cabinet door above the tv on the right has a crack in it. Cause: Screw was overtightened at factory. Correction: replace cabinet door 10 inches wide by 21 inches long.

Model#		**Dlr Sub Hrs**	0.40	**Sub Labor Amt**	$56.00
Serial#		**Appr Hrs**	0.40	**Appr Labor Amt**	$56.00

Notes

Part

Line# 1

Item #		**Description**			
F100451818		DOOR, CABINET, CURIO, 19 X 10 SHORTLINE-PRESTON SNOW, #652539, 2024			
Model #		**Serial #**		**Part tag**	
Sub Qty	1.00	**Sub Dlr Price**	$25.18	**Sub Freight**	$18.81
Appr Qty	1.00	**Appr Dlr Price**	$25.18	**Appr Freight**	$18.81

Notes

Line# 2

Item #		**Description**			
F100267847		GLASS, 17-7/16 X 6-7/16 SEEDED W/BLACKOUT PRINT			
Model #		**Serial #**		**Part tag**	
Sub Qty	1.00	**Sub Dlr Price**	$6.44	**Sub Freight**	$0.00
Appr Qty	1.00	**Appr Dlr Price**	$6.44	**Appr Freight**	$0.00

Notes

Line# 3

Item #		**Description**			
USERPART		109672 - catch door. Cannot get invoice - it came from Keystone.			
Model #		**Serial #**		**Part tag**	
Sub Qty	1.00	**Sub Dlr Price**	$0.33	**Sub Freight**	$0.00
Appr Qty	1.00	**Appr Dlr Price**	$0.33	**Appr Freight**	$0.00

Notes

Labor

Line# 7

Operation Code	**Operational Description**
30-100-24-00-001046	Cabinet Door - Interior/Cabinetry/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-08-13 10:52:12 :: Complaint: Several cabinet door have cracks in them. Cause: Screws overtightened from factory. Correction: Covered the cracks with putty where

possible.

Model#		**Dlr Sub Hrs**	0.70	**Sub Labor Amt**	$98.00
Serial#		**Appr Hrs**	0.70	**Appr Labor Amt**	$98.00

Notes

Labor

Line# 8

Operation Code	**Operational Description**
30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : greeneway@dealer-advisors.com, 2025-08-13 10:53:13 :: Complaint: Piece of trim above the bathroom door to the left of the loft stairs is coming off. Cause: Nails let loose. Correction: Resecuredthe trim.

Model#		**Dlr Sub Hrs**	0.20	**Sub Labor Amt**	$28.00
Serial#		**Appr Hrs**	0.10	**Appr Labor Amt**	$14.00

Notes

flat rate to secure

Submitted		
	Labor Amt	$462.00
	Parts & Freight	$462.04
	Total	$924.04

Approved		
	Labor Amt	$392.00
	Parts & Freight	$450.04
	Total	$842.04

DEALER SIGNATURE **DATE**

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER SIGNATURE **DATE**

All repairs described have been inspected and are satisfactory.