

Pre-Authorization

Pre-Authorization number PA02998645 Reference no: 64813 Status: Approved Approved by WillT Approved date 12/8/2021
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDF31623M2508552 3/27/2021
 600 E Baseline Rd
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	4103206B	A/C - Coleman - F	0.00	2.50	1.50		1	1.00	Complaint: CUSTOMER STATES THAT AC TRIPS AT GFI CAMPGROUND WHEN THE CAMPGROUND HAS A GFIIT DOES NOT HAPPEN WHEN THEY ARE NOT AT A CAMPGROUND WITHOUT GCFI Cause: amp draw test on compressor. removed inside shroud. hooked up tester to compressor wire. compressor is pulling 46.3 amps at start up. Correction: need to replace a/c unit. compressor is pulling too many amps. KRV-VCB-Coleman- MDINC-0072468 URL. Scrape off large upper unit data label and return. Field scrape the defective.

Pre-Authorization number PA02998645

1.50

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company