Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26865

WO #: 26865

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711
Home Phone: 423-235-1167
Work Phone:
Author:S.DAVIS
Location: IH
Invoice #:

Stock #: 11169
Stock Desc: 2026 TT KZ-RV SPORTSMEN CLASS 191BHK
Model: 191BHK
Serial #: 4EZTK1814T5067765
Chassis #:
Mileage:0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 20 MAR 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 01 NOV 25

Job #1 - Warranty

COMPLAINT: DURING LOT CHECK TECH FOUND THE ROOF IS LEAKING AND CAUSED WATER DAMAGE WITHIN THE UNIT

CAUSE: TECH VERIFIED WATER IS GETTING INTO UNIT FROM THE FRONT DS GUTTER RAIL NOT BEING SEALED CORRECTLY AT FACTORY. ALSO FOUND SMALL OPEN VOID IN SEALANT ON ROOF. THESE ISSUES HAVE ALLOWED WATER TO ENTER UNIT AND DAMAGE A CEILING PANEL,LOWER FRONT INT PANEL,GRAY PANEL AT SIDE OF MATTRESS AND WATER ON PLASTIC COVERING OF MATTRESS.

CORRECTION: SEAL GUTTER RAILING AND VOID ON FRONT TO PREVENT FURTHER LEAKING/DAMAGE.REMOVE AND REPLACE THE CEILING PANEL THAT IS CURVED,WALL PANEL WHERE ELECTRICAL OUTLET IS,LOWER GRAY PANEL AT MATTRESS AND CLEAN MATTRESS PLASTIC COVERING.
LABOR 4.0

Subtotal for Job #1: 0.00

Customer #: 47602
TRI-AM RV CENTER-EAST TN,

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	**0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X_____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 Mar 2026

© 2026 Integrated Dealer Systems