MYERS RV CENTER
SALES ★ PARTS ★ SERVICE
12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72933-1
Promised Date:
72933-1

Customer #: 1000
MYERS "RV" CENTER, INC.,
1000

WO #: 72933-1
Customer Name: 1000 - MYERS "RV" CENTER, INC.

Completed Date:
Invoice#:
Author: ADVISOR
Stock Desc: 9672 2026 SANIBEL 34LOUNGE
Serial#: 706323
Chassis#: 5ZT3SNZB9TG706323
Miles/Hrs:
Tag#:
Purchased Date:
Warranty Date:

Date In: 22 MAY 26
Time In:

Job #J - Warranty
COMPLAINT: Fires place remote missing

CAUSE: MISSING FROM UNIT

CORRECTION: Found the remote for the fireplace is missing
Need to order parts

Labor

Job #	Description	Total
J	Fireplace remote missing	N/C
	Subtotal for Job #J:	**0.00**

Job #K - Warranty
COMPLAINT: SUBWOOFER MISSING

CAUSE: UNKNOWN

CORRECTION: Found the subwoofer at the dining area is missing
Need to order parts

Labor

Job #	Description	Total
K	Subwoofer missing	N/C
	Subtotal for Job #K:	**0.00**

Job #01 - Warranty
COMPLAINT: CHIPPED FIBERGLASS BY LEFT TAIL LIGHT

CAUSE: UNKNOWN

CORRECTION: Recommend fill sand and repaint area
Send out for sublet

Labor

Job #	Description	Total
01	MISC LABOUR CODE (WARRANTY)	N/C

© 2026 Integrated Dealer Systems
72933-1

Subtotal for Job #01: 0.00

Job #02 - Warranty
COMPLAINT: Found the entry step handle was missing a bolt from the bottom.

CAUSE: Bolt fell out

CORRECTION: Found the entry step handle was missing a bolt from the bottom. Found the right size machine bolt and the right length installed the bolt tightened down the entry step entry step is now fixed work complete. REQUESTING .15

Labor

Job #	Description	Total
02	Missing bolt entry handle	N/C

Subtotal for Job #02: 0.00

Job #03 - Warranty
COMPLAINT: STRICKER PLATE NEEDS ADJUSTED

CAUSE: Sticking on striker plate

CORRECTION: Adjusted striker plate so the door will no longer drag on striker plate
By flattening the striker out and moving it forward
REQUESTING .15

Labor

Job #	Description	Total
03	Entry door adjustment hard to close	N/C

Subtotal for Job #03: 0.00

Job #04 - Warranty
COMPLAINT: CLOSET DOOR NEEDS ADJUSTED

CAUSE: Closet door dragging on bottom rail

CORRECTION: Adjusted the door up to stop the dragging on the rail
Ran the adjustment screws up until the door stopped dragging and closed evenly

Labor

Job #	Description	Total
04	Closet door adjustment	N/C

Subtotal for Job #04: 0.00

Job #05 - Warranty
COMPLAINT: VENT BROKEN CEILING A/C VENT

CAUSE: Vent broke louvers fell out ac register closes

CORRECTION: Removed broken piece replaced with new vent REQUESTING .15

Labor

Job #	Description	Total
05	Broken ac vent	N/C

Parts

Part #	Description	Qty	Price	Total
55-5321	HEATING/COOLING REGISTER - POLAR WHITE	1.00	N/C	N/C

Customer Work Order

Subtotal for Job #05: **0.00**

Job #06 - Warranty
COMPLAINT: PUSH BUTTON ON LIGHT COVER MISSING

CAUSE: Push button fell out of light cover

CORRECTION: Removed broken cover push button missing will need to replace the cover
Hold for parts

Labor

Job #	Description	Total
06	Light cover push button fell out	N/C

Subtotal for Job #06: **0.00**

Job #07 - Warranty
COMPLAINT: FRONT PANEL IS LOOSE

CAUSE: Panel came loose

CORRECTION: Renailed panel back down to the wall
REQUESTING .15

Labor

Job #	Description	Total
07	Panel came off in passenger side basement	N/C

Subtotal for Job #07: **0.00**

Job #08 - Warranty
COMPLAINT: CO AX CABLE PULLED OUT OF THE END OF TV

CAUSE: Cable broke off

CORRECTION: Removed broken cable
Replaced cable
REQUSTING .35

Labor

Job #	Description	Total
08	Cable tv coax cable broke	N/C

Subtotal for Job #08: **0.00**

Job #09 - Warranty
COMPLAINT: TRIM CAME OFF IN BEDROOM AT FLOOR ON THE SLIDE

CAUSE: Trim falling off

CORRECTION: Removed trim cut to fit Renailed trim back in place puttied nail holes
requesting.15

Labor

Job #	Description	Total
09	Trim cut long pushed off with slide. Movement	N/C

Subtotal for Job #09: **0.00**

Customer Work Order

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	**0.00**

NOTICE:
DUE TO A LACK OF SPACE, A $15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 22 May 2026

Customer Signature : _____

Customer Work Order

W/O: 72933-1
Promised Date: 30 APR 26

72933-1

Customer #: 1000
MYERS "RV" CENTER, INC.,

1000