

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 80251
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11783 - 2026 TRACER 286RL 5ZT2TRUB3TB527120

VIN: 5ZT2TRUB3TB527120 HIN:

SER#: 5ZT2TRUB3TB527120

Mileage: 0

Work Order Comp: 08 JUL 26

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 11 JUN 26

Inv #: 432549

WO # Job # Description JOB INFORMATION

80251 4 ANTENNA DOESN'T WORK
 Anetnna not working
 During pdi noticed anetnna would not pick up any channels when
 scanning tv. Pulled unit outside to get better signal and still
 did not pick ip any channels. Parts request for new antenna

80251 2 THERE ARE MULTIPLE VOIDS VISIBLE IN THE SEALANT AROUND THE
 OUTSIDE OF UNIT.
 Voids In silcione
 During pdi noticed mutliple voids in silcione around outside of
 camper. Went around unit and filled voids with clear silcione.
 Pictures taken.

80251 3 THE ARE SOME SCRATCHES IN THE CABINET DOOR BELOW THE KITCHEN
 SINK.
 Scratches in wood
 During pdi notcied scratches in door under sink, entertainment
 center drawer, and bathroom door. Covered with wood putty.
 Pictures taken.

80251 5 INSIDE LIVING ROOM DOES NOT HAVE CHANNELS AFTER REPLACING THE
 ANTENNA
 cable not connected
 while trying to test new antenna found that there was never a
 coax cable ran to tv in living room. connection inb slideroom on
 outside was not working as well. placed tester on cable

Claim : 80251

 WO # Job # Description JOB INFORMATION

 connection and attached to cable in wall at booster. line was
 open. removed old connection and placed new fitting on line. line
 is no longer open. tested connection outside of slideroom to be
 working. removed hinges for compartment door to lower door.
 removed fridge. removed false wall to access cable. spliced cable
 and put fittings on both ends. added splitter to connect. added
 coax cable to run from spliter to tv inside. once ran attached to
 connection for tv and tested. cables work properly and tv inside
 gets picture and sound. added flase wall back, placed fridge in
 place and secured with screws, and placed hinges back up for
 door.

 Part No Job# Description PARTS Qty Price Total

 F100766707 4 ANTENNA, AIR 360 LOW PROFILE, OEM 0.00 33.63 0.00
 13-1320 4 PW HAPS FREE SELF-LEVELING DICOR 1.00 8.98 8.98

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.11 195.00 21.45
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.06 195.00 11.70
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.01 195.00 1.95
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.40 195.00 78.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.42 195.00 81.90
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 195.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 195.00 39.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.30 195.00 58.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.27 195.00 52.65
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.48 195.00 93.60

Parts Total: 8.98
 Labour Total: 438.75
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 447.73

Customer Signature: _____

Date: _____